

Town	Facility	Building	Asset No	Lot Plan	Address	Build Date	Auditor	Date of Inspection	ACM Location	Use of ACM / Component	ACM Material	Friable / Bonded	ACM Status	Sample #	ACM Type	ACM Condition	ACM Treatment	ACM Risk	Photo #
Amby	Amby Cemetery	Longdrop Shed	26867	215DUB5393	Springhill Access Rd	1970's	Craig Carlson	22-Jul-20	Building	Building all timber and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	A.01
Amby	Amby Hall	Building	55674	208A3841	George St	1960's	Craig Carlson	22-Jul-20	Building	Male amenities asbestos cement sheeting walls behind toilet, urinal and sink; masonite remaining walls and ceiling	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	A.02; A.03; A.04
Amby	Amby Hall	Building	55674	208A3841	George St	1960's	Craig Carlson	22-Jul-20	Building	Female amenities asbestos cement sheeting walls behind toilet and sink; masonite remaining walls and ceiling	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	A.05; A.06
Amby	Amby Hall	Building	55674	208A3841	George St	1960's	Craig Carlson	22-Jul-20	Building	Cleaner's void, kitchen area and main hall masonite walls and ceiling with non-asbestos vinyl sheet and timber flooring	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Amby	Amby Hall	Building	55674	208A3841	George St	1960's	Craig Carlson	22-Jul-20	Building	Building external non-asbestos fibre cement sheeting soffits	Cement based (1)	N/A	Not present (tested)	Q34183S01	No asbestos detected	N/A	N/A	N/A	A.07; A.08
Amby	Amby Hall	Building	55674	208A3841	George St	1960's	Craig Carlson	22-Jul-20	Building	Building external asbestos cement sheeting infill panels above and under glazing on main hall	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	A.09
Amby	Amby Hall	Building	55674	208A3841	George St	1960's	Craig Carlson	22-Jul-20	Building	Building external asbestos cement sheeting drain trap surround under kitchen area	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	A.11
Amby	Amby Hall	Carport	55675	208A3841	George St	Post 2000	Craig Carlson	22-Jul-20	Building	Building all metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	A.12
Amby	Heritage Park	Play Shelter	27527	209A3841	George St	Post 2000	Craig Carlson	22-Jul-20	Park	Shelter all steel and shade cloth; picnic shelter all timber and metal sheeting	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	A.13; A.14
Amby	Amby Sewerage Treatment Plant	Storage and Equipment Shed	63295	168DL342	Warrego Hwy	Post 2000	Craig Carlson	22-Jul-20	Sewerage Treatment Plant	Building all metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	A.15
Amby	Amby Bore 1	Bore 1 Treatment Building	60707	Road Reserve	Amby North Rd	Post 2000	Craig Carlson	22-Jul-20	Water Treatment Plant	Building all metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	A.16
Amby	Amby Bore 1	Generator Shelter	62772	Road Reserve	Amby North Rd	Post 2000	Craig Carlson	22-Jul-20	Water Treatment Plant	Building all metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	A.17
Amby	Amby Bore 1	Main electrical board	Unknown	Road Reserve	Amby North Rd	1980's	Craig Carlson	22-Jul-20	Water Treatment Plant	Main electrical board compressed asbestos mounting panel	Insulation board (2)	Bonded	Confirmed	Q34183S02	Chrysotile (1)	Fair (2)	Unsealed bonded (2)	Low	A.18