

Town	Facility	Building	Asset No	Lot Plan	Address	Build Date	Auditor	Date of Inspection	ACM Location	Use of ACM / Component	ACM Material	Friable / Bonded	ACM Status	Sample #	ACM Type	ACM Condition	ACM Treatment	ACM Risk	Photo #
Injune	Injune Aerodrome	Toilet Block	26815	142SP126465	Airport Dv	Post 2000	Craig Carlson	6-Jul-20	Public Amenities	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	I.56
Injune	Courthouse Museum	Building	55685	1SP166537	32-36 Hutton St	1930's (refurbished 1990's)	Craig Carlson	7-Jul-20	Building	Main room and back room non-asbestos fibre cement sheeting walls and ceiling sections	Cement based (1)	N/A	No asbestos detected	Q34056S06	No asbestos detected	N/A	N/A	N/A	I.57; I.58; I.59
Injune	Courthouse Museum	Building	55685	1SP166537	32-36 Hutton St	1930's (refurbished 1990's)	Craig Carlson	7-Jul-20	Building	Back toilet non-asbestos vinyl sheet flooring	Vinyl sheeting (2)	N/A	No asbestos detected	Q34056S07	No asbestos detected	N/A	N/A	N/A	I.60
Injune	Courthouse Museum	Building	55685	1SP166537	32-36 Hutton St	1930's (refurbished 1990's)	Craig Carlson	7-Jul-20	Building	External non-asbestos fibre cement sheeting soffits (some areas of masonite) and fascia panel on front verandah which is part of the newer verandah of the multi-purpose facility	Cement based (1)	N/A	Not present (not tested)	Similar to Q34056S06	No asbestos detected	N/A	N/A	N/A	I.61; I.62; I.63
Injune	Injune Lawn Cemetery	Equipment Shed	26879	137WT197	Cemetery Rd	1990's	Craig Carlson	7-Jul-20	Building	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	I.92
Injune	Injune Lawn Cemetery	Shade Shelter	26876	137WT197	Cemetery Rd	1990's	Craig Carlson	7-Jul-20	Park	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	I.93
Injune	Injune Multi Purpose Facility	Injune Creek Gallery	56310	1SP166537	32-36 Hutton St	1970's (renovated post 2000)	Craig Carlson	17-Aug-20	Building	Internal all plasterboard walls and ceilings with carpet flooring; gallery is part of the larger multi purpose building and is internal area only	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Injune	Injune Multi Purpose Facility	Library and Offices	60396	1SP166537	32-36 Hutton St	1970's (renovated post 2000)	Craig Carlson	17-Aug-20	Building	Internal areas throughout including library, offices, lunch room and amenities foyer plasterboard walls and ceilings with carpet flooring	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Injune	Injune Multi Purpose Facility	Library and Offices	60396	1SP166537	32-36 Hutton St	1970's (renovated post 2000)	Craig Carlson	17-Aug-20	Building	Amenities non-asbestos fibre cement sheeting walls including back wall in cleaner's cupboard	Cement based (1)	N/A	Not present (not tested)	None taken	No asbestos detected	N/A	N/A	N/A	I.124; I.125; I.126
Injune	Injune Multi Purpose Facility	Library and Offices	60396	1SP166537	32-36 Hutton St	1970's (renovated post 2000)	Craig Carlson	17-Aug-20	Building	External non-asbestos fibre cement sheeting ceiling in front entry foyer	Cement based (1)	N/A	Not present (not tested)	None taken	No asbestos detected	N/A	N/A	N/A	I.127
Injune	Injune Multi Purpose Facility	Library and Offices	60396	1SP166537	32-36 Hutton St	1970's (renovated post 2000)	Craig Carlson	17-Aug-20	Building	External asbestos cement sheeting soffits including front verandah ceiling	Cement based (1)	Bonded	Confirmed	Q34056S14	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.128; I.129; I.130
Injune	Injune Multi Purpose Facility	Play Shelter	27627	1SP166537	32-36 Hutton St	Post 2000	Craig Carlson	17-Aug-20	Building	All steel and shadecloth construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	I.131
Injune	Injune RSL Memorial Hall	Building	55701	303I7182	38 Hutton St	1960's	Craig Carlson	7-Jul-20	Building	Front north office area and storeroom asbestos cement sheeting ceiling with masonite walls	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.65
Injune	Injune RSL Memorial Hall	Building	55701	303I7182	38 Hutton St	1960's	Craig Carlson	7-Jul-20	Building	Front foyer area asbestos cement sheeting ceiling with masonite walls	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.66
Injune	Injune RSL Memorial Hall	Building	55701	303I7182	38 Hutton St	1960's	Craig Carlson	7-Jul-20	Building	Main hall north wall asbestos cement sheeting infills above two double doors and wall in centre panel	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.67; I.68
Injune	Injune RSL Memorial Hall	Building	55701	303I7182	38 Hutton St	1960's	Craig Carlson	7-Jul-20	Building	Main hall asbestos cement sheeting upper ceiling above suspended synthetic mineral fibre tile ceiling; the ceiling sheeting has been damaged for the installation of the ceiling hangers	Cement based (1)	Bonded	Presumed	Similar to Q34056S08	Chrysotile (1)	Fair (2)	Unsealed bonded (2)	Low	I.69; I.70
Injune	Injune RSL Memorial Hall	Building	55701	303I7182	38 Hutton St	1960's	Craig Carlson	7-Jul-20	Building	Main hall stage area and dressing rooms asbestos cement sheeting ceiling including upper ceiling above suspended synthetic mineral fibre tile ceiling; the ceiling sheeting has been damaged for the installation of the ceiling hangers	Cement based (1)	Bonded	Presumed	Similar to Q34056S08	Chrysotile (1)	Fair (2)	Unsealed bonded (2)	Low	I.71; I.72
Injune	Injune RSL Memorial Hall	Building	55701	303I7182	38 Hutton St	1960's	Craig Carlson	7-Jul-20	Building	Dining hall and kitchen asbestos cement sheeting ceiling throughout and random wall panels on centre internal partition	Cement based (1)	Bonded	Presumed	Similar to Q34056S08	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.73; I.74
Injune	Injune RSL Memorial Hall	Building	55701	303I7182	38 Hutton St	1960's	Craig Carlson	7-Jul-20	Building	RSL Room asbestos cement sheeting ceiling including in small back section	Cement based (1)	Bonded	Presumed	Similar to Q34056S08	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.75
Injune	Injune RSL Memorial Hall	Building	55701	303I7182	38 Hutton St	1960's	Craig Carlson	7-Jul-20	Building	RSL Room kitchenette asbestos cement sheeting walls and ceiling	Cement based (1)	Bonded	Presumed	Similar to Q34056S08	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.76

Town	Facility	Building	Asset No	Lot Plan	Address	Build Date	Auditor	Date of Inspection	ACM Location	Use of ACM / Component	ACM Material	Friable / Bonded	ACM Status	Sample #	ACM Type	ACM Condition	ACM Treatment	ACM Risk	Photo #
Injune	Injune RSL Memorial Hall	Building	55701	30317182	38 Hutton St	1960's	Craig Carlson	7-Jul-20	Building	Rear north storeroom (old bathroom) asbestos cement sheeting walls and ceiling (lower walls Tilux sheeting)	Cement based (1)	Bonded	Presumed	Similar to Q34056S08	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.77; I.78
Injune	Injune RSL Memorial Hall	Building	55701	30317182	38 Hutton St	1960's	Craig Carlson	7-Jul-20	Building	Amenities section of building is a new extension constructed in 2007; all non-asbestos fibre cement sheeting internal walls, ceilings and cubicle dividers and external soffits and ceilings	Cement based (1)	N/A	Not present (not tested)	None taken	No asbestos detected	N/A	N/A	N/A	I.79; I.80
Injune	Injune RSL Memorial Hall	Building	55701	30317182	38 Hutton St	1960's	Craig Carlson	7-Jul-20	Building	External asbestos cement sheeting front entry foyer ceiling	Cement based (1)	Bonded	Presumed	Similar to Q34056S08	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.81
Injune	Injune RSL Memorial Hall	Building	55701	30317182	38 Hutton St	1960's	Craig Carlson	7-Jul-20	Building	External asbestos cement sheeting soffits (excluding amenities structure)	Cement based (1)	Bonded	Confirmed	Q34056S08	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.82; I.83
Injune	Injune SES	SES Facility	55679	1017181	Annandale St	1985	Craig Carlson	17-Aug-20	Building	Internal areas throughout non-asbestos fibre cement sheeting and timber walls and ceiling including office, kitchen, amenities, vehicle parking areas and storerooms	Cement based (1)	N/A	Not present (tested)	Q34056S15; Q34056S16	No asbestos detected	N/A	N/A	N/A	I.133 through to I.146
Injune	Injune SES	SES Facility	55679	1017181	Annandale St	1985	Craig Carlson	17-Aug-20	Building	External all metal sheeting roof and walls	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Injune	Youth Centre - Community Centre	Building	55695	3171817	41-45 Hutton St	1995	Craig Carlson	7-Jul-20	Building	Internal all timber, plasterboard and non-asbestos fibre cement sheeting walls and ceilings	Cement based (1)	N/A	Not present (not tested)	Q34056S09	No asbestos detected	N/A	N/A	N/A	I.85
Injune	Youth Centre - Community Centre	Building	55695	3171817	41-45 Hutton St	1995	Craig Carlson	7-Jul-20	Building	External all timber and metal sheeting construction with non-asbestos compressed fibre cement sheeting flooring on access ramps	Cement based (1)	N/A	Not present (not tested)	None taken	No asbestos detected	N/A	N/A	N/A	I.86
Injune	Youth Centre - Community Centre	Pergola	55696	3171817	41-45 Hutton St	1990's	Craig Carlson	7-Jul-20	Building	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	I.87
Injune	Youth Centre - Community Centre	Toilet Block - Original	55697	3171817	41-45 Hutton St	No longer present	Craig Carlson	7-Jul-20	Building	N/A	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Injune	Injune Council Depot	Office - Transportable	62541	1017181	Annandale St	No longer present	Craig Carlson	17-Aug-20	Depot	Building removed from site	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Injune	Injune Council Depot	Poison Shed	56063	1017181	Annandale St	1960's	Craig Carlson	17-Aug-20	Depot	Internal asbestos cement sheeting internal partition and ceiling; external all timber and metal sheeting	Cement based (1)	Bonded	Confirmed	Q34056S17	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.147; I.148
Injune	Injune Council Depot	Workshop No2 - Plumbers	56062	1017181	Annandale St	1970's	Craig Carlson	17-Aug-20	Depot	All steel and metal sheeting with non-asbestos upper infill panels in areas	Cement based (1)	N/A	Not present (not tested)	None taken	No asbestos detected	N/A	N/A	N/A	I.149; I.150
Injune	Injune Council Depot	Main Workshop Shed	Unknown	1017181	Annandale St	1970's	Craig Carlson	17-Aug-20	Depot	All steel, timber and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	I.151
Injune	Workers Camp (Injune)	Accommodation R01-R04 - Donga 1	56067	Road Reserve	Annandale St	1990's	Craig Carlson	17-Aug-20	Building	Demountable internal timber laminate walls with non-asbestos fibre cement sheeting ceilings and non-asbestos vinyl sheet flooring; external all metal sheeting roof and walls	Cement based (1)	N/A	Not present (not tested)	None taken	No asbestos detected	N/A	N/A	N/A	I.152; I.153; I.154
Injune	Workers Camp (Injune)	Accommodation R05-R08 - Donga 2	58933	Road Reserve	Annandale St	1990's	Craig Carlson	17-Aug-20	Building	Demountable internal timber laminate walls with non-asbestos fibre cement sheeting ceilings and non-asbestos vinyl sheet flooring; external all metal sheeting roof and walls	Cement based (1)	N/A	Not present (not tested)	None taken	No asbestos detected	N/A	N/A	N/A	I.155; I.156; I.157
Injune	Workers Camp (Injune)	Accommodation R09-R10 and Kitchens	56066	Road Reserve	Annandale St	1990's	Craig Carlson	17-Aug-20	Building	Internal non-asbestos fibre cement sheeting walls and ceilings and non-asbestos vinyl sheet flooring; external masonite artificial weatherboard walls with non-asbestos fibre cement sheeting soffits and metal sheeting roof	Cement based (1)	N/A	Not present (not tested)	Q34056S18; Q34056S19; Q34056S20	No asbestos detected	N/A	N/A	N/A	I.158 through to I.164
Injune	Workers Camp (Injune)	Accommodation R11-R16 - Nurses Quarters	56065	Road Reserve	Annandale St	1970's	Craig Carlson	17-Aug-20	Building	Kitchen masonite walls and ceiling with asbestos cement sheeting walls behind fridge and stove	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.165; I.166
Injune	Workers Camp (Injune)	Accommodation R11-R16 - Nurses Quarters	56065	Road Reserve	Annandale St	1970's	Craig Carlson	17-Aug-20	Building	Accommodation rooms 11 to 16 masonite walls and ceiling with some non-asbestos fibre cement sheeting wall panels	Cement based (1)	N/A	Not present (tested)	Q34056S21	No asbestos detected	N/A	N/A	N/A	I.167
Injune	Workers Camp (Injune)	Accommodation R11-R16 - Nurses Quarters	56065	Road Reserve	Annandale St	1970's	Craig Carlson	17-Aug-20	Building	Accommodation rooms 11 to 16 asbestos cement sheeting infill panels adjacent air conditioning units	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.168

Town	Facility	Building	Asset No	Lot Plan	Address	Build Date	Auditor	Date of Inspection	ACM Location	Use of ACM / Component	ACM Material	Friable / Bonded	ACM Status	Sample #	ACM Type	ACM Condition	ACM Treatment	ACM Risk	Photo #
Injune	Workers Camp (Injune)	Accommodation R11-R16 - Nurses Quarters	56065	Road Reserve	Annandale St	1970's	Craig Carlson	17-Aug-20	Building	Centre hall masonite walls and ceiling with asbestos cement sheeting walls in hall to back door	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.169
Injune	Workers Camp (Injune)	Accommodation R11-R16 - Nurses Quarters	56065	Road Reserve	Annandale St	1970's	Craig Carlson	17-Aug-20	Building	Centre shower asbestos cement sheeting walls including partition to shower	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.170
Injune	Workers Camp (Injune)	Accommodation R11-R16 - Nurses Quarters	56065	Road Reserve	Annandale St	1970's	Craig Carlson	17-Aug-20	Building	TV room (built-in verandah) asbestos cement sheeting ceiling, outer end walls and infill panels under glazing to external and upper walls on partition to centre hall	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.171; I.172; I.173
Injune	Workers Camp (Injune)	Accommodation R11-R16 - Nurses Quarters	56065	Road Reserve	Annandale St	1970's	Craig Carlson	17-Aug-20	Building	South toilet asbestos cement sheeting partition to external behind toilet with masonite remaining walls and ceiling	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.174
Injune	Workers Camp (Injune)	Accommodation R11-R16 - Nurses Quarters	56065	Road Reserve	Annandale St	1970's	Craig Carlson	17-Aug-20	Building	South bathrooms (two) asbestos cement sheeting walls including partitions to showers	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.175; I.176
Injune	Workers Camp (Injune)	Accommodation R11-R16 - Nurses Quarters	56065	Road Reserve	Annandale St	1970's	Craig Carlson	17-Aug-20	Building	External asbestos cement sheeting infill panels adjacent air conditioning units	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.177
Injune	Workers Camp (Injune)	Accommodation R11-R16 - Nurses Quarters	56065	Road Reserve	Annandale St	1970's	Craig Carlson	17-Aug-20	Building	External asbestos cement sheeting artificial weatherboard cladding on building in verandah	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.178
Injune	Workers Camp (Injune)	Accommodation R11-R16 - Nurses Quarters	56065	Road Reserve	Annandale St	1970's	Craig Carlson	17-Aug-20	Building	External asbestos cement sheeting soffits on building verandah; main building soffits masonite	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.179
Injune	Workers Camp (Injune)	Accommodation R17-R20 - PL2015	58928	Road Reserve	Annandale St	Post 2000	Craig Carlson	17-Aug-20	Building	Demountable internal timber laminate walls and ceiling with non-asbestos vinyl sheet flooring; external all metal sheeting	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	I.181
Injune	Workers Camp (Injune)	Accommodation R21-R24 - PL2016	58929	Road Reserve	Annandale St	Post 2000	Craig Carlson	17-Aug-20	Building	Demountable internal timber laminate walls and ceiling with non-asbestos vinyl sheet flooring; external all metal sheeting	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	I.182
Injune	Workers Camp (Injune)	Amenities Building	Unknown	Road Reserve	Annandale St	Post 2000	Craig Carlson	17-Aug-20	Building	Demountable internal timber laminate walls and ceiling with non-asbestos vinyl sheet flooring; external all metal sheeting	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	I.184
Injune	Workers Camp (Injune)	Barbecue Cover	Unknown	Road Reserve	Annandale St	Post 2000	Craig Carlson	17-Aug-20	Building	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	I.183
Injune	Workers Camp (Injune)	Office Building	Unknown	Road Reserve	Annandale St	Post 2000	Craig Carlson	17-Aug-20	Building	Demountable internal timber laminate walls and ceiling with non-asbestos vinyl sheet flooring; external all metal sheeting	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	I.185
Injune	Injune Caravan Park	Accommodation Buildings	55938	25SP166550	2-4 Third Av	Post 2000	Craig Carlson	7-Jul-20	Building	Demountable buildings all timber laminated internal walls and ceiling and metal sheeting external walls and roof	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	I.111; I.112
Injune	Injune Caravan Park	Office Demountable	Unknown	25SP166550	2-4 Third Av	Post 2000	Craig Carlson	7-Jul-20	Building	Demountable building all timber laminated internal walls and ceiling and metal sheeting external walls and roof	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	I.110
Injune	Injune Caravan Park	BBQ Shed	Unknown	25SP166550	2-4 Third Av	Post 2000	Craig Carlson	7-Jul-20	Park	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	I.109
Injune	Injune Caravan Park	Injune Laundromat	55941	25SP166550	2-4 Third Av	1950's (Refurbished post 2000)	Craig Carlson	7-Jul-20	Building	Male and female non-amenities asbestos fibre cement sheeting walls, ceilings and cubicle dividers and non-asbestos vinyl sheet flooring	Cement based (1)	N/A	Not present (not tested)	None taken	No asbestos detected	N/A	N/A	N/A	I.113; I.114
Injune	Injune Caravan Park	Injune Laundromat	55941	25SP166550	2-4 Third Av	1950's (Refurbished post 2000)	Craig Carlson	7-Jul-20	Building	Laundry room (and suspected in cleaner's room) non-asbestos fibre cement sheeting walls and ceilings and non-asbestos vinyl sheet flooring	Cement based (1)	N/A	Not present (not tested)	None taken	No asbestos detected	N/A	N/A	N/A	I.115
Injune	Injune Caravan Park	Injune Laundromat	55941	25SP166550	2-4 Third Av	1950's (Refurbished post 2000)	Craig Carlson	7-Jul-20	Building	Building throughout all rooms two layers of fibre cement sheeting ceiling present with the original upper layer being asbestos cement sheeting	Cement based (1)	Bonded	Confirmed	Q34056S13	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.116
Injune	Injune Caravan Park	Injune Laundromat	55941	25SP166550	2-4 Third Av	1950's (Refurbished post 2000)	Craig Carlson	7-Jul-20	Building	Building external asbestos cement sheeting front awning ceiling and façade panel	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.118; I.119

Town	Facility	Building	Asset No	Lot Plan	Address	Build Date	Auditor	Date of Inspection	ACM Location	Use of ACM / Component	ACM Material	Friable / Bonded	ACM Status	Sample #	ACM Type	ACM Condition	ACM Treatment	ACM Risk	Photo #
Injune	Injune Caravan Park	Injune Laundromat	55941	25SP166550	2-4 Third Av	1950's (Refurbished post 2000)	Craig Carlson	7-Jul-20	Building	Building external asbestos cement sheeting upper wall above front awning (visible within ceiling/roof cavity); main building walls may be asbestos cement sheeting behind artificial vinyl weatherboard however this was unable to determine	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.117; I.120
Injune	Injune Caravan Park	Injune Laundromat	55941	25SP166550	2-4 Third Av	1950's (Refurbished post 2000)	Craig Carlson	7-Jul-20	Building	Building external rear awning asbestos cement sheeting ceiling	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.121
Injune	Injune Caravan Park	Laundry Showers and Toilet Block	55940	25SP166550	2-4 Third Av	1970's	Craig Carlson	7-Jul-20	Public Amenities	Internal concrete block walls with asbestos cement sheeting partition walls to toilet cubicles and ceiling sheeting throughout	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.103; I.104
Injune	Injune Caravan Park	Laundry Showers and Toilet Block	55940	25SP166550	2-4 Third Av	1970's	Craig Carlson	7-Jul-20	Public Amenities	External asbestos cement sheeting soffits and external ceilings including in entry foyers	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.105
Injune	Injune Caravan Park	Laundry Showers and Toilet Block	55940	25SP166550	2-4 Third Av	1970's	Craig Carlson	7-Jul-20	Public Amenities	External asbestos cement vent pipe	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.106
Injune	Injune Caravan Park	Laundry Showers and Toilet Block	55940	25SP166550	2-4 Third Av	1970's	Craig Carlson	7-Jul-20	Public Amenities	Centre store area asbestos cement sheeting ceiling	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.107
Injune	Injune Caravan Park	Laundry Showers and Toilet Block	55940	25SP166550	2-4 Third Av	1970's	Craig Carlson	7-Jul-20	Public Amenities	Main electrical board compressed asbestos mounting panel	Insulation board (2)	Bonded	Presumed	None taken	Chrysotile (1)	Fair (2)	Sealed bonded (1)	Low	I.108
Injune	Injune Rodeo Grounds	Canteen	27653	143WT243	Carnarvon Hwy	1950's	Craig Carlson	17-Aug-20	Building	Internal kitchen, servery, kitchen storeroom and storeroom (old amenities) asbestos cement sheeting walls and ceilings throughout	Cement based (1)	Bonded	Presumed	Q34056S22	Chrysotile (1)	Fair (2)	Sealed bonded (1)	Low	I.186; I.187; I.188; I.189; I.190
Injune	Injune Rodeo Grounds	Canteen	27653	143WT243	Carnarvon Hwy	1950's	Craig Carlson	17-Aug-20	Building	External asbestos cement vent pipe for amenities	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Fair (2)	Unsealed bonded (2)	Low	I.191
Injune	Injune Rodeo Grounds	Canteen	27653	143WT243	Carnarvon Hwy	1950's	Craig Carlson	17-Aug-20	Building	External asbestos cement sheeting walls and ceiling in servery	Cement based (1)	Bonded	Presumed	Similar to Q34056S22	Chrysotile (1)	Fair (2)	Sealed bonded (1)	Low	I.192
Injune	Injune Rodeo Grounds	Grandstand	55703	143WT243	Carnarvon Hwy	1970's	Craig Carlson	17-Aug-20	Building	Dining area asbestos cement sheeting upper walls to external, upper wall on partition to outdoor dining and ceiling sheeting in front of servery	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.194; I.195; I.196; I.197
Injune	Injune Rodeo Grounds	Grandstand	55703	143WT243	Carnarvon Hwy	1970's	Craig Carlson	17-Aug-20	Building	Bar area asbestos cement sheeting ceiling and upper walls to servery and dining area	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.198; I.199
Injune	Injune Rodeo Grounds	Grandstand	55703	143WT243	Carnarvon Hwy	1970's	Craig Carlson	17-Aug-20	Building	External asbestos cement sheeting end walls on west awning and upper wall above west awning	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.200; I.201
Injune	Injune Rodeo Grounds	Grandstand	55703	143WT243	Carnarvon Hwy	1970's	Craig Carlson	17-Aug-20	Building	External asbestos cement sheeting soffits on east side of servery area	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.202
Injune	Injune Rodeo Grounds	Shower and Toilet Block	55557	143WT243	Carnarvon Hwy	Post 2000	Craig Carlson	17-Aug-20	Public Amenities	Demountable non-asbestos fibre cement sheeting internal walls and soffits; metal sheeting external walls and roof	Cement based (1)	N/A	Not present (not tested)	None taken	No asbestos detected	N/A	N/A	N/A	I.203; I.204; I.205
Injune	Injune Rodeo Grounds	Shower Block - at Possum Park	27655	143WT243	Carnarvon Hwy	No longer present	Craig Carlson	17-Aug-20	Public Amenities	N/A	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Injune	Injune Rodeo Grounds	Toilet Block	27654	143WT243	Carnarvon Hwy	Post 2000	Craig Carlson	17-Aug-20	Public Amenities	Demountable internal timber laminate walls and ceiling with non-asbestos vinyl sheet flooring; external all metal sheeting	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	I.206
Injune	Injune Rodeo Grounds	Callers Stand	Unknown	143WT243	Carnarvon Hwy	1960's	Craig Carlson	17-Aug-20	Building	All timber construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	I.207
Injune	Injune Rodeo Grounds	Pump House	Unknown	143WT243	Carnarvon Hwy	1960's	Craig Carlson	17-Aug-20	Building	All timber and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	I.208

Town	Facility	Building	Asset No	Lot Plan	Address	Build Date	Auditor	Date of Inspection	ACM Location	Use of ACM / Component	ACM Material	Friable / Bonded	ACM Status	Sample #	ACM Type	ACM Condition	ACM Treatment	ACM Risk	Photo #
Injune	Injune Rodeo Grounds	Open Ground Area	Unknown	143WT243	Carnarvon Hwy	1960's	Craig Carlson	17-Aug-20	Park	Asbestos cement sheeting fragments were present on along the front of the canteen area; all visible fragments were collected at the time of the inspection, however additional fragments may be present under vegetation	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Poor (3)	Unsealed bonded (2)	Medium	I.209; I.210
Injune	Injune Swimming Pool	Kids Pool Sheds (two)	Unknown	3171817	41-45 Hutton St	Post 2000	Craig Carlson	18-Aug-20	Swimming Pool	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	I.211
Injune	Injune Swimming Pool	Garden Sheds (two)	Unknown	3171817	41-45 Hutton St	1990's	Craig Carlson	18-Aug-20	Swimming Pool	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	I.212
Injune	Injune Swimming Pool	Chemical Shed	55690	3171817	41-45 Hutton St	1990's	Craig Carlson	18-Aug-20	Swimming Pool	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	I.213
Injune	Injune Swimming Pool	Filtration Shed	55691	3171817	41-45 Hutton St	1970's	Craig Carlson	18-Aug-20	Swimming Pool	Main room masonite walls with asbestos cement sheeting ceiling and partition to west external and walls in south west corner	Cement based (1)	Bonded	Confirmed	Q34056S23; Q34056S24	Chrysotile (1)	Poor (3)	Unsealed bonded (2)	Medium	I.214; I.215; I.216
Injune	Injune Swimming Pool	Filtration Shed	55691	3171817	41-45 Hutton St	1970's	Craig Carlson	18-Aug-20	Swimming Pool	Acid store asbestos cement sheeting ceiling	Cement based (1)	Bonded	Presumed	Similar to Q34056S23	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.217
Injune	Injune Swimming Pool	Filtration Shed	55691	3171817	41-45 Hutton St	1970's	Craig Carlson	18-Aug-20	Swimming Pool	Acid store compressed non-asbestos fibre cement sheeting panel at floor at doorway	Cement based (1)	N/A	Not present (tested)	Q34056S25	No asbestos detected	N/A	N/A	N/A	I.218
Injune	Injune Swimming Pool	Filtration Shed	55691	3171817	41-45 Hutton St	1970's	Craig Carlson	18-Aug-20	Swimming Pool	Building external timber walls and soffits with metal sheeting roof	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Injune	Injune Swimming Pool	Kiosk and Toilet Block	55689	3171817	41-45 Hutton St	1970's	Craig Carlson	18-Aug-20	Swimming Pool	Male and female amenities/change rooms all brick walls with metal sheeting roof and compressed non-asbestos fibre cement sheeting door panels	Cement based (1)	N/A	Not present (tested)	Q34056S26	No asbestos detected	N/A	N/A	N/A	I.219; I.220
Injune	Injune Swimming Pool	Kiosk and Toilet Block	55689	3171817	41-45 Hutton St	1970's	Craig Carlson	18-Aug-20	Swimming Pool	Amenities/change room asbestos cement vent pipe to roof	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.221
Injune	Injune Swimming Pool	Kiosk and Toilet Block	55689	3171817	41-45 Hutton St	1970's	Craig Carlson	18-Aug-20	Swimming Pool	Kiosk canteen area asbestos cement sheeting ceiling, upper walls above glazing and servery and upper centre wall	Cement based (1)	Bonded	Confirmed	Q34056S26	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.222; I.223
Injune	Injune Swimming Pool	Kiosk and Toilet Block	55689	3171817	41-45 Hutton St	1970's	Craig Carlson	18-Aug-20	Swimming Pool	External asbestos cement sheeting ceilings in entry foyers to male and female change rooms	Cement based (1)	Bonded	Presumed	Similar to Q34056S26	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.224; I.225
Injune	Injune Swimming Pool	Kiosk and Toilet Block	55689	3171817	41-45 Hutton St	1970's	Craig Carlson	18-Aug-20	Swimming Pool	External asbestos cement sheeting soffits and external ceilings	Cement based (1)	Bonded	Presumed	Similar to Q34056S26	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.226; I.230
Injune	Injune Swimming Pool	Kiosk and Toilet Block	55689	3171817	41-45 Hutton St	1970's	Craig Carlson	18-Aug-20	Swimming Pool	External asbestos cement sheeting ceiling in main entry foyer area	Cement based (1)	Bonded	Presumed	Similar to Q34056S26	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.227
Injune	Injune Swimming Pool	Kiosk and Toilet Block	55689	3171817	41-45 Hutton St	1970's	Craig Carlson	18-Aug-20	Swimming Pool	External asbestos cement sheeting infill panels above servery/glazing including front ceiling and upper wall for main building sign	Cement based (1)	Bonded	Presumed	Similar to Q34056S26	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.228; I.229
Injune	Injune Swimming Pool	Shelter - Main Pool South End	55692	3171817	41-45 Hutton St	Post 2000	Craig Carlson	18-Aug-20	Swimming Pool	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	I.231
Injune	Injune Tennis Courts	Tennis Clubhouse	27646	3171817	41-45 Hutton St	1960's	Craig Carlson	7-Jul-20	Building	Amenities foyer asbestos cement sheeting walls and ceiling in sink recess and partition to toilet with masonite remaining walls	Cement based (1)	Bonded	Presumed	Similar to Q34056S11	Chrysotile; amosite (2)	Good (1)	Sealed bonded (1)	Low	I.94
Injune	Injune Tennis Courts	Tennis Clubhouse	27646	3171817	41-45 Hutton St	1960's	Craig Carlson	7-Jul-20	Building	West side toilet asbestos cement sheeting walls and ceiling	Cement based (1)	Bonded	Confirmed	Q34056S11	Chrysotile; amosite (2)	Good (1)	Sealed bonded (1)	Low	I.95; I.96
Injune	Injune Tennis Courts	Tennis Clubhouse	27646	3171817	41-45 Hutton St	1960's	Craig Carlson	7-Jul-20	Building	Main room asbestos cement sheeting partition to courtyard with masonite remaining walls and ceiling	Cement based (1)	Bonded	Presumed	Similar to Q34056S11	Chrysotile; amosite (2)	Good (1)	Sealed bonded (1)	Low	I.97

Town	Facility	Building	Asset No	Lot Plan	Address	Build Date	Auditor	Date of Inspection	ACM Location	Use of ACM / Component	ACM Material	Friable / Bonded	ACM Status	Sample #	ACM Type	ACM Condition	ACM Treatment	ACM Risk	Photo #
Injune	Injune Tennis Courts	Tennis Clubhouse	27646	3I71817	41-45 Hutton St	1960's	Craig Carlson	7-Jul-20	Building	Main room asbestos backed vinyl sheet flooring under non-asbestos vinyl sheet flooring	Vinyl sheeting (2)	Friable	Confirmed	Q34056S12	Chrysotile (1)	Fair (2)	Sealed friable (2)	Low	I.100; I.101
Injune	Injune Tennis Courts	Tennis Clubhouse	27646	3I71817	41-45 Hutton St	1960's	Craig Carlson	7-Jul-20	Building	West storeroom and canteen room masonite walls and ceilings with timber flooring	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Injune	Injune Tennis Courts	Tennis Clubhouse	27646	3I71817	41-45 Hutton St	1960's	Craig Carlson	7-Jul-20	Building	East foyer asbestos cement sheeting walls and ceiling in sink recess and partition to toilet with masonite remaining walls	Cement based (1)	Bonded	Presumed	Similar to Q34056S11	Chrysotile; amosite (2)	Good (1)	Sealed bonded (1)	Low	I.98
Injune	Injune Tennis Courts	Tennis Clubhouse	27646	3I71817	41-45 Hutton St	1960's	Craig Carlson	7-Jul-20	Building	East side toilet asbestos cement sheeting walls and ceiling	Cement based (1)	Bonded	Confirmed	Similar to Q34056S11	Chrysotile; amosite (2)	Good (1)	Sealed bonded (1)	Low	I.99
Injune	Injune Tennis Courts	Tennis Clubhouse	27646	3I71817	41-45 Hutton St	1960's	Craig Carlson	7-Jul-20	Building	External timber walls with metal sheeting roof and no soffit lining	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Injune	Steve Murray Sports Oval	Cricket Clubhouse	27635	131I7187	Carnarvon Hwy	Renovated post 2000	Craig Carlson	18-Aug-20	Building	Internal masonite and non-asbestos fibre cement sheeting walls and ceilings throughout	Cement based (1)	N/A	Not present (tested)	Q34056S28	No asbestos detected	N/A	N/A	N/A	I.232; I.233; I.234
Injune	Steve Murray Sports Oval	Cricket Clubhouse	27635	131I7187	Carnarvon Hwy	Renovated post 2000	Craig Carlson	18-Aug-20	Building	External asbestos cement sheeting soffits	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.235
Injune	Steve Murray Sports Oval	Cricket Clubhouse	27635	131I7187	Carnarvon Hwy	Renovated post 2000	Craig Carlson	18-Aug-20	Building	External non-asbestos fibre cement sheeting fascia and flooring on rear verandah	Cement based (1)	N/A	Not present (tested)	Q34056S29	No asbestos detected	N/A	N/A	N/A	I.236
Injune	Steve Murray Sports Oval	Toilet Block	27636	131I7187	Carnarvon Hwy	Post 2000	Craig Carlson	18-Aug-20	Public Amenities	Concrete block walls with compressed non-asbestos fibre cement sheeting cubicle dividers	Cement based (1)	N/A	Not present (tested)	Q34056S30	No asbestos detected	N/A	N/A	N/A	I.238; I.239
Injune	Gwyder Laycock Park	Toilet Block	27564	3I71817	41-45 Hutton St	Post 2000	Craig Carlson	7-Jul-20	Public Amenities	Internal and external all brick and non-asbestos fibre cement sheeting walls and ceilings, soffits and roof infill panels	Cement based (1)	N/A	Not present (tested)	None taken	No asbestos detected	N/A	N/A	N/A	I.88; I.89; I.90; I.91
Injune	Henricks Park	Table Shelter	60544	1SP166540	50-52 Hutton St	Post 2000	Craig Carlson	18-Aug-20	Park	All steel, timber and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	I.241
Injune	Train Stop Apex Park	Shed	27545	6I71821	5 Hutton St	1920's (relocated 2011)	Craig Carlson	18-Aug-20	Park	Main building timber walls, floor and ceiling with metal sheeting roof	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	I.242
Injune	Train Stop Apex Park	Shed	27545	6I71821	5 Hutton St	1920's (relocated 2011)	Craig Carlson	18-Aug-20	Park	Electrical board compressed asbestos mounting panel	Insulation board (2)	Bonded	Presumed	None taken	Chrysotile (1)	Fair (2)	Unsealed bonded (2)	Low	I.243
Injune	Train Stop Apex Park	Shed	27545	6I71821	5 Hutton St	1920's (relocated 2011)	Craig Carlson	18-Aug-20	Park	Electrical board internal fuse box lining	Cement based (1)	Bonded	Presumed	None taken	Chrysotile; amosite (2)	Fair (2)	Unsealed bonded (2)	Medium	I.243
Injune	Train Stop Apex Park	Shed	27545	6I71821	5 Hutton St	1920's (relocated 2011)	Craig Carlson	18-Aug-20	Display Item	Engine/train asbestos textile gaskets and friction materials suspected	Woven textile (2)	Friable	Presumed	None taken	Chrysotile (1)	Fair (2)	Unsealed friable (3)	Medium	I.244
Injune	1 Broughton Street	Dwelling Duplex 1-2	28880	1WT803552	Broughton St	1990's	Craig Carlson	6-Jul-20	Building	Internal throughout plasterboard walls and ceilings in lounge, kitchen, dining, hall and bedrooms with non-asbestos vinyl sheet and carpet flooring	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Injune	1 Broughton Street	Dwelling Duplex 1-2	28880	1WT803552	Broughton St	1990's	Craig Carlson	6-Jul-20	Building	Bathroom (selected areas) and laundry non-asbestos fibre cement sheeting walls with plasterboard ceilings and non-asbestos vinyl sheet flooring	Cement based (1)	N/A	Not present (not tested)	None taken	No asbestos detected	N/A	N/A	N/A	I.1; I.2
Injune	1 Broughton Street	Dwelling Duplex 1-2	28880	1WT803552	Broughton St	1990's	Craig Carlson	6-Jul-20	Building	Building external non-asbestos fibre cement sheeting soffit and carport ceiling sheeting and external artificial weatherboard gable ends and infill panels above doorways	Cement based (1)	N/A	Not present (tested)	Q34056S01	No asbestos detected	N/A	N/A	N/A	I.3; I.4; I.5; I.6
Injune	10 Railway Parade	Dwelling	28893	13I71822	10 Railway Pde	1990's	Craig Carlson	6-Jul-20	Building	Internal throughout plasterboard walls and ceilings in lounge, kitchen, dining, bedrooms and toilet with non-asbestos vinyl sheet and carpet flooring	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Injune	10 Railway Parade	Dwelling	28893	13I71822	10 Railway Pde	1990's	Craig Carlson	6-Jul-20	Building	Laundry and bathroom non-asbestos fibre cement sheeting walls with plasterboard ceilings and non-asbestos vinyl sheet flooring	Cement based (1)	N/A	Not present (tested)	Q34056S05	No asbestos detected	N/A	N/A	N/A	I.46; I.47

Town	Facility	Building	Asset No	Lot Plan	Address	Build Date	Auditor	Date of Inspection	ACM Location	Use of ACM / Component	ACM Material	Friable / Bonded	ACM Status	Sample #	ACM Type	ACM Condition	ACM Treatment	ACM Risk	Photo #
Injune	10 Railway Parade	Dwelling	28893	13171822	10 Railway Pde	1990's	Craig Carlson	6-Jul-20	Building	External non-asbestos fibre cement sheeting soffits, verandah ceilings, carport ceiling and infill panels above glazing	Cement based (1)	N/A	Not present (not tested)	Similar to Q34056S05	No asbestos detected	N/A	N/A	N/A	I.48; I.49; I.50
Injune	12 Railway Parade	Dwelling	28897	14171822	12 Railway Pde	Late 1980's	Craig Carlson	6-Jul-20	Building	Internal lounge, kitchen, dining, bedrooms (three), laundry and toilet plasterboard walls and ceiling with non-asbestos vinyl sheet and carpet flooring	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Injune	12 Railway Parade	Dwelling	28897	14171822	12 Railway Pde	Late 1980's	Craig Carlson	6-Jul-20	Building	Bathroom non-asbestos fibre cement sheeting walls with plasterboard ceiling	Cement based (1)	N/A	Not present (not tested)	None taken	No asbestos detected	N/A	N/A	N/A	I.43
Injune	12 Railway Parade	Dwelling	28897	14171822	12 Railway Pde	Late 1980's	Craig Carlson	6-Jul-20	Building	External non-asbestos fibre cement sheeting soffits and external ceilings	Cement based (1)	N/A	Not present (not tested)	Similar to Q34056S04	No asbestos detected	N/A	N/A	N/A	I.44
Injune	12 Railway Parade	Dwelling	28897	14171822	12 Railway Pde	Late 1980's	Craig Carlson	6-Jul-20	Building	External non-asbestos fibre cement sheeting artificial weatherboards cladding	Cement based (1)	N/A	Not present (tested)	Q34056S04	No asbestos detected	N/A	N/A	N/A	I.45
Injune	16 Third Avenue	Dwelling	28729	1017181	16 Third Av	1950's	Craig Carlson	6-Jul-20	Building	Lounge, kitchen, dining asbestos cement sheeting walls and ceiling in outer area (rooms appeared to be a built-in verandah) and partition to bathroom	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.26; I.27
Injune	16 Third Avenue	Dwelling	28729	1017181	16 Third Av	1950's	Craig Carlson	6-Jul-20	Building	Lounge room main area asbestos cement sheeting ceiling	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.28
Injune	16 Third Avenue	Dwelling	28729	1017181	16 Third Av	1950's	Craig Carlson	6-Jul-20	Building	Front bedroom asbestos cement sheeting ceiling	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.29
Injune	16 Third Avenue	Dwelling	28729	1017181	16 Third Av	1950's	Craig Carlson	6-Jul-20	Building	Front sleep-out asbestos cement sheeting walls and ceiling (timber partition to west bedroom)	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.30
Injune	16 Third Avenue	Dwelling	28729	1017181	16 Third Av	1950's	Craig Carlson	6-Jul-20	Building	Bathroom asbestos cement sheeting walls and ceiling	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.31
Injune	16 Third Avenue	Dwelling	28729	1017181	16 Third Av	1950's	Craig Carlson	6-Jul-20	Building	Toilet asbestos cement sheeting walls and ceiling	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.32
Injune	16 Third Avenue	Dwelling	28729	1017181	16 Third Av	1950's	Craig Carlson	6-Jul-20	Building	Front and side verandah areas asbestos cement sheeting walls and ceiling	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.33; I.34
Injune	16 Third Avenue	Dwelling	28729	1017181	16 Third Av	1950's	Craig Carlson	6-Jul-20	Building	Laundry asbestos cement sheeting walls and ceiling	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.35
Injune	17 Railway Parade	Dwelling	28733	9SP152683	17 Railway Pde	1970's	Craig Carlson	6-Jul-20	Building	Internal lounge, kitchen, hall, three bedrooms and toilet masonite walls and ceilings with non-asbestos vinyl sheet and carpet flooring	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Injune	17 Railway Parade	Dwelling	28733	9SP152683	17 Railway Pde	1970's	Craig Carlson	6-Jul-20	Building	Bathroom asbestos cement sheeting walls and ceiling with non-asbestos vinyl sheet flooring	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.36
Injune	17 Railway Parade	Dwelling	28733	9SP152683	17 Railway Pde	1970's	Craig Carlson	6-Jul-20	Building	Kitchen, bathroom and toilet non-asbestos vinyl sheet flooring	Vinyl sheeting (2)	N/A	Not present (tested)	Q34056S03	No asbestos detected	N/A	N/A	N/A	I.37; I.38
Injune	17 Railway Parade	Dwelling	28733	9SP152683	17 Railway Pde	1970's	Craig Carlson	6-Jul-20	Building	External asbestos cement sheeting soffits including external ceilings	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.39; I.40
Injune	17 Railway Parade	Dwelling	28733	9SP152683	17 Railway Pde	1970's	Craig Carlson	6-Jul-20	Building	External asbestos cement sheeting lower walls on rear verandah	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.41
Injune	17 Railway Parade	Dwelling	28733	9SP152683	17 Railway Pde	1970's	Craig Carlson	6-Jul-20	Building	External asbestos cement sheeting gable ends (two on ends of building and one on front)	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.42
Injune	28 Annandale Street	Dwelling	28901	3917187	28 Annandale St	1970's	Craig Carlson	6-Jul-20	Building	Internal lounge, kitchen, dining, hall, three bedrooms and toilet masonite walls and ceilings with non-asbestos vinyl sheet and carpet flooring	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Injune	28 Annandale Street	Dwelling	28901	3917187	28 Annandale St	1970's	Craig Carlson	6-Jul-20	Building	Laundry asbestos cement sheeting walls and ceiling with non-asbestos vinyl sheet flooring	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.7

Town	Facility	Building	Asset No	Lot Plan	Address	Build Date	Auditor	Date of Inspection	ACM Location	Use of ACM / Component	ACM Material	Friable / Bonded	ACM Status	Sample #	ACM Type	ACM Condition	ACM Treatment	ACM Risk	Photo #
Injune	28 Annandale Street	Dwelling	28901	39I7187	28 Annandale St	1970's	Craig Carlson	6-Jul-20	Building	Bathroom asbestos cement sheeting walls and ceiling with non-asbestos vinyl sheet flooring	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.8
Injune	28 Annandale Street	Dwelling	28901	39I7187	28 Annandale St	1970's	Craig Carlson	6-Jul-20	Building	External asbestos cement sheeting soffits and external ceilings	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.9
Injune	28 Annandale Street	Dwelling	28901	39I7187	28 Annandale St	1970's	Craig Carlson	6-Jul-20	Building	External asbestos cement sheeting gable ends	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.10
Injune	28 Annandale Street	Dwelling	28901	39I7187	28 Annandale St	1970's	Craig Carlson	6-Jul-20	Building	External asbestos cement sheeting wall lining in rear stair foyer	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.11
Injune	28 Annandale Street	Dwelling	28901	39I7187	28 Annandale St	1970's	Craig Carlson	6-Jul-20	Building	External compressed asbestos cement sheeting flooring in rear stair foyer	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.12
Injune	54 Ronald Street	Dwelling	28737	10I7181	54 Ronald St	1970's	Craig Carlson	6-Jul-20	Building	Lounge, kitchen, dining low density asbestos fibreboard ceilings and masonite walls	Low density board (2)	Friable	Presumed	Similar to Q34056S02	Chrysotile; amosite (2)	Good (1)	Sealed friable (2)	Medium	I.20; I.21
Injune	54 Ronald Street	Dwelling	28737	10I7181	54 Ronald St	1970's	Craig Carlson	6-Jul-20	Building	Bedrooms (three) low density asbestos fibreboard ceilings and masonite walls	Low density board (2)	Friable	Presumed	Similar to Q34056S02	Chrysotile; amosite (2)	Good (1)	Sealed friable (2)	Medium	I.22
Injune	54 Ronald Street	Dwelling	28737	10I7181	54 Ronald St	1970's	Craig Carlson	6-Jul-20	Building	Bathroom asbestos cement sheeting walls and ceiling with ceramic tile flooring on unknown substrate	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.23
Injune	54 Ronald Street	Dwelling	28737	10I7181	54 Ronald St	1970's	Craig Carlson	6-Jul-20	Building	Toilet and laundry low density asbestos fibreboard ceilings and masonite walls	Low density board (2)	Friable	Confirmed	Q34056S02	Chrysotile; amosite (2)	Good (1)	Sealed friable (2)	Medium	I.24
Injune	54 Ronald Street	Dwelling	28737	10I7181	54 Ronald St	1970's	Craig Carlson	6-Jul-20	Building	External asbestos cement sheeting soffits	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.25
Injune	56 Ronald Street	Dwelling	28741	10I7181	56 Ronald St	1970's	Craig Carlson	6-Jul-20	Building	Internal lounge, kitchen main room, dining, three bedrooms and toilet main room masonite walls and ceilings with non-asbestos vinyl sheet and carpet flooring	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Injune	56 Ronald Street	Dwelling	28741	10I7181	56 Ronald St	1970's	Craig Carlson	6-Jul-20	Building	Toilet asbestos cement sheeting wall behind sink	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.13
Injune	56 Ronald Street	Dwelling	28741	10I7181	56 Ronald St	1970's	Craig Carlson	6-Jul-20	Building	Bathroom asbestos cement sheeting walls and ceiling (wall sheeting is painted Tilux in areas) and ceramic tile flooring on unknown substrate	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.14
Injune	56 Ronald Street	Dwelling	28741	10I7181	56 Ronald St	1970's	Craig Carlson	6-Jul-20	Building	Kitchen asbestos cement sheeting walls and ceiling in old stove recess	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.15
Injune	56 Ronald Street	Dwelling	28741	10I7181	56 Ronald St	1970's	Craig Carlson	6-Jul-20	Building	External asbestos cement sheeting soffits	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Fair (2)	Sealed bonded (1)	Low	I.16; I.17
Injune	56 Ronald Street	Dwelling	28741	10I7181	56 Ronald St	1970's	Craig Carlson	6-Jul-20	Building	External asbestos cement vent pipe for amenities	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Fair (2)	Unsealed bonded (2)	Low	I.18
Injune	56 Ronald Street	Dwelling	28741	10I7181	56 Ronald St	1970's	Craig Carlson	6-Jul-20	Building	Laundry asbestos cement sheeting partition wall to main house	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	I.19
Injune	6 Railway Parade	Dwelling	28889	11I71822	6 Railway Pde	1990's	Craig Carlson	6-Jul-20	Building	Internal throughout plasterboard walls and ceilings in lounge, kitchen, dining, bedrooms and toilet with non-asbestos vinyl sheet and carpet flooring	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Injune	6 Railway Parade	Dwelling	28889	11I71822	6 Railway Pde	1990's	Craig Carlson	6-Jul-20	Building	Laundry and bathroom non-asbestos fibre cement sheeting and plasterboard walls and ceilings with non-asbestos vinyl sheet flooring	Cement based (1)	N/A	Not present (not tested)	None taken	No asbestos detected	N/A	N/A	N/A	I.51; I.52
Injune	6 Railway Parade	Dwelling	28889	11I71822	6 Railway Pde	1990's	Craig Carlson	6-Jul-20	Building	External non-asbestos fibre cement sheeting soffits, verandah ceilings, carport ceiling and infill panels above glazing	Cement based (1)	N/A	Not present (not tested)	None taken	No asbestos detected	N/A	N/A	N/A	I.53; I.54; I.55
Injune	Injune Bore 1	Bore 1 Treatment Building	60687	10I7181	Annandale St	1990's	Craig Carlson	18-Aug-20	Water Treatment Plant	All concrete block and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	I.245

Town	Facility	Building	Asset No	Lot Plan	Address	Build Date	Auditor	Date of Inspection	ACM Location	Use of ACM / Component	ACM Material	Friable / Bonded	ACM Status	Sample #	ACM Type	ACM Condition	ACM Treatment	ACM Risk	Photo #
Injune	Injune Bore 2	Bore 2 Treatment Building	60689	3171816	Broughton St	1990's	Craig Carlson	18-Aug-20	Water Treatment Plant	All concrete block and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	I.246
Injune	Injune Bore 3	Bore 3 Treatment Building	60691	144WT249	Womblebank Gap Rd	1990's	Craig Carlson	18-Aug-20	Water Treatment Plant	All concrete block and metal sheeting construction; shed all steel and metal sheeting	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	I.247; I.248
Injune	Injune Reservoir and Booster	Booster Pump Building	60802	21171814	46-50 Annandale St	Post 2000	Craig Carlson	18-Aug-20	Water Treatment Plant	All concrete block and metal sandwich panel construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	I.249
Injune	Injune Washdown Facility	Pump Shed	75581	143WT243	Carnarvon Hwy	Post 2000	Craig Carlson	18-Aug-20	Water Treatment Plant	All concrete block and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	I.250