

Town	Facility	Building	Asset No	Lot Plan	Address	Build Date	Auditor	Date of Inspection	ACM Location	Use of ACM / Component	ACM Material	Friable / Bonded	ACM Status	Sample #	ACM Type	ACM Condition	ACM Treatment	ACM Risk	Photo #
Mungallala	Mungallala Hall	Building	55786	7M5442	Redford St	1955 (renovated in 2001)	Craig Carlson	23-Jul-20	Building	Main hall, male and female amenities and kitchen area masonite and timber walls and ceiling with non-asbestos vinyl sheet and timber flooring	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Mungallala	Mungallala Hall	Building	55786	7M5442	Redford St	1955 (renovated in 2001)	Craig Carlson	23-Jul-20	Building	Council office timber and masonite in main room with asbestos cement sheeting walls and ceiling in rear window recess (suspected old stove recess; old patched hole for stack present)	Cement based (1)	Bonded	Presumed	Similar to Q34184S01	Chrysotile; amosite; crocidolite (3)	Good (1)	Sealed bonded (1)	Low	MG.01; MG.02
Mungallala	Mungallala Hall	Building	55786	7M5442	Redford St	1955 (renovated in 2001)	Craig Carlson	23-Jul-20	Building	Building external asbestos cement sheeting soffits and front entry foyer ceiling	Cement based (1)	Bonded	Presumed	Similar to Q34184S01	Chrysotile; amosite; crocidolite (3)	Good (1)	Sealed bonded (1)	Low	MG.03; MG.04
Mungallala	Mungallala Hall	Building	55786	7M5442	Redford St	1955 (renovated in 2001)	Craig Carlson	23-Jul-20	Building	External main electrical board compressed asbestos sheeting mounting panel	Insulation board (2)	Bonded	Presumed	None taken	Chrysotile (1)	Fair (2)	Unsealed bonded (2)	Low	MG.05
Mungallala	Mungallala Hall	Building	55786	7M5442	Redford St	1955 (renovated in 2001)	Craig Carlson	23-Jul-20	Building	External low levels of loose asbestos cement sheeting debris present on surface ground	Cement based (1)	Bonded	Confirmed	Q34184S01	Chrysotile; amosite; crocidolite (3)	Poor (3)	Unsealed bonded (2)	Medium	MG.07
Mungallala	Mungallala Hall	Building	55786	7M5442	Redford St	1955 (renovated in 2001)	Craig Carlson	23-Jul-20	Building	External asbestos cement vent pipes for amenities (two)	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Fair (2)	Unsealed bonded (2)	Low	MG.08
Mungallala	Mungallala Hall	Carport	55788	7M5442	Redford St	Post 2000	Craig Carlson	23-Jul-20	Building	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	MG.09
Mungallala	Mungallala Hall	Shade Roof to Post Office	60727	7M5442	Redford St	Post 2000	Craig Carlson	23-Jul-20	Building	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	MG.10
Mungallala	Mungallala Public Toilets	Men's Shower and Toilet Block	75591	117DL488	Burke Street	1950's	Craig Carlson	23-Jul-20	Public Amenities	Internal timber walls in main area with asbestos cement sheeting walls and dividers in shower area	Cement based (1)	Bonded	Presumed	Q34184S02	Chrysotile; amosite; crocidolite (3)	Fair (2)	Sealed bonded (1)	Low	MG.11
Mungallala	Mungallala Public Toilets	Men's Shower and Toilet Block	75591	117DL488	Burke Street	1950's	Craig Carlson	23-Jul-20	Public Amenities	External all asbestos cement sheeting upper walls and soffits	Cement based (1)	Bonded	Presumed	Similar to Q34184S02	Chrysotile; amosite; crocidolite (3)	Fair (2)	Sealed bonded (1)	Low	MG.12; MG.13
Mungallala	Mungallala Public Toilets	Men's Shower and Toilet Block	75591	117DL488	Burke Street	1950's	Craig Carlson	23-Jul-20	Public Amenities	External disused asbestos cement flue pipe for old hot water system (now removed)	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Fair (2)	Unsealed bonded (2)	Low	MG.13
Mungallala	Mungallala Public Toilets	Men's Shower and Toilet Block	75591	117DL488	Burke Street	1950's	Craig Carlson	23-Jul-20	Public Amenities	External asbestos cement sheeting fragments on surface ground	Cement based (1)	Bonded	Presumed	Similar to Q34184S02	Chrysotile; amosite; crocidolite (3)	Poor (3)	Unsealed bonded (2)	Medium	MG.23
Mungallala	Mungallala Public Toilets	Women's Shower and Toilet Block	27871	117DL488	Burke Street	1950's	Craig Carlson	23-Jul-20	Public Amenities	Internal timber walls in main area with asbestos cement sheeting walls and dividers in shower area	Cement based (1)	Bonded	Presumed	Similar to Q34184S02	Chrysotile; amosite; crocidolite (3)	Fair (2)	Sealed bonded (1)	Low	MG.17; MG.18
Mungallala	Mungallala Public Toilets	Women's Shower and Toilet Block	27871	117DL488	Burke Street	1950's	Craig Carlson	23-Jul-20	Public Amenities	External all asbestos cement sheeting upper walls and soffits	Cement based (1)	Bonded	Presumed	Similar to Q34184S02	Chrysotile; amosite; crocidolite (3)	Fair (2)	Sealed bonded (1)	Low	MG.19; MG.20
Mungallala	Mungallala Public Toilets	Women's Shower and Toilet Block	27871	117DL488	Burke Street	1950's	Craig Carlson	23-Jul-20	Public Amenities	External disused asbestos cement flue pipe for old hot water system (now removed)	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Fair (2)	Unsealed bonded (2)	Low	MG.22
Mungallala	Mungallala Public Toilets	Women's Shower and Toilet Block	27871	117DL488	Burke Street	1950's	Craig Carlson	23-Jul-20	Public Amenities	External asbestos cement sheeting fragments on surface ground	Cement based (1)	Bonded	Presumed	Similar to Q34184S02	Chrysotile; amosite; crocidolite (3)	Poor (3)	Unsealed bonded (2)	Medium	MG.24
Mungallala	Mungallala Sports Ground	Bar	27873	1M54413	Redford Rd	1970's	Craig Carlson	23-Jul-20	Building	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	MG.28
Mungallala	Mungallala Sports Ground	Canteen	27874	1M54413	Redford Rd	1970's	Craig Carlson	23-Jul-20	Building	Internal all non-asbestos fibre cement sheeting walls and ceilings and external all timber construction	Cement based (1)	N/A	Not present (tested)	Q34184S03	No asbestos detected	N/A	N/A	N/A	MG.25; MG.26; MG.27
Mungallala	Mungallala Sports Ground	Play Shelter	27877	1M54413	Redford Rd	Post 2000	Craig Carlson	23-Jul-20	Park	All steel and shadecloth construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	MG.29
Mungallala	Mungallala Sports Ground	Shower and Toilet Block	27872	1M54413	Redford Rd	1970's	Craig Carlson	23-Jul-20	Public Amenities	All timber wall and metal sheeting roof	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	MG.30
Mungallala	Cobb and Co Rest Area	Table Shelter	27894	117DL488	Burke Street	1970's	Craig Carlson	23-Jul-20	Park	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	MG.31
Mungallala	Cobb and Co Rest Area	Toilet Block	Unknown	117DL488	Burke Street	1980's	Craig Carlson	23-Jul-20	Public Amenities	All concrete block and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	MG.32
Mungallala	Ooline Park	Table Shelter	27908	Road Reserve	Warrego Hwy	1990's	Craig Carlson	23-Jul-20	Park	All timber and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	MG.40
Mungallala	Ooline Park	Toilet Block - Longdrop	63425	Road Reserve	Warrego Hwy	1990's	Craig Carlson	23-Jul-20	Public Amenities	All timber and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	MG.39

Town	Facility	Building	Asset No	Lot Plan	Address	Build Date	Auditor	Date of Inspection	ACM Location	Use of ACM / Component	ACM Material	Friable / Bonded	ACM Status	Sample #	ACM Type	ACM Condition	ACM Treatment	ACM Risk	Photo #
Mungallala	Mungallala Sewerage Treatment Plant	Storage and Equipment Shed	63294	110M5445	Burke St	1980's	Craig Carlson	23-Jul-20	Sewerage Treatment Plant	Shed all steel and metal sheeting construction; electrical cabinet all asbestos free	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	MG.33
Mungallala	Mungallala Bore 3	Bore 3 Treatment Building	60704	Road Reserve	School St West	Post 2000	Craig Carlson	23-Jul-20	Water Treatment Plant	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	MG.35
Mungallala	Mungallala Bore 3	Generator Shelter	62809	Road Reserve	School St West	Post 2000	Craig Carlson	23-Jul-20	Water Treatment Plant	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	MG.37
Mungallala	Mungallala Reservoir	Chlorine Dosing Building	62889	Road Reserve	School St West	Post 2000	Craig Carlson	23-Jul-20	Water Treatment Plant	All concrete block and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	MG.36
Mungallala	Mungallala Reservoir	Pumphouse	62887	Road Reserve	School St West	1990's	Craig Carlson	23-Jul-20	Water Treatment Plant	All steel and metal sheeting construction; pumps all new installation	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	MG.34