

Town	Facility	Building	Asset No	Lot Plan	Address	Build Date	Auditor	Date of Inspection	ACM Location	Use of ACM / Component	ACM Material	Friable / Bonded	ACM Status	Sample #	ACM Type	ACM Condition	ACM Treatment	ACM Risk	Photo #
Jackson	Jackson CWA Hall and Park	Picnic Shelter and Table	27697	7J4617	2 Queen St	Post 2000	Craig Carlson	8-Jul-20	Park	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	J.29
Jackson	Jackson CWA Hall and Park	Toilet Block	Unknown	7J4617	2 Queen St	1970's	Craig Carlson	8-Jul-20	Public Amenities	All concrete block and metal sheeting construction	N/A	N/A	No	None taken	No asbestos detected	N/A	N/A	N/A	J.30
Jackson	Jackson Library	Building	55706	5BWR824	1-23 Edward St	1950's	Craig Carlson	8-Jul-20	Building	Level 1 rear built-in verandah asbestos cement sheeting partition to rear foyer, infill panel above glazing and ceiling sheeting	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	J.12; J.13; J.14
Jackson	Jackson Library	Building	55706	5BWR824	1-23 Edward St	1950's	Craig Carlson	8-Jul-20	Building	Level 1 main room and back room timber (VJ) and masonite walls and ceilings throughout	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Jackson	Jackson Library	Building	55706	5BWR824	1-23 Edward St	1950's	Craig Carlson	8-Jul-20	Building	Level 1 back room vinyl asbestos tile flooring	Vinyl tiles (1)	Bonded	Confirmed	Q34057S03	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	J.15
Jackson	Jackson Library	Building	55706	5BWR824	1-23 Edward St	1950's	Craig Carlson	8-Jul-20	Building	Level 1 rear foyer asbestos cement sheeting partition to rear built-in verandah and external and ceiling sheeting	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	J.16; J.17
Jackson	Jackson Library	Building	55706	5BWR824	1-23 Edward St	1950's	Craig Carlson	8-Jul-20	Building	Building external asbestos cement sheeting soffits	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	J.18
Jackson	Jackson Library	Building	55706	5BWR824	1-23 Edward St	1950's	Craig Carlson	8-Jul-20	Building	Building external non-asbestos fibre cement sheeting fascia at front and rear stair landings at floor level, with the front damaged and fragments on ground	Cement based (1)	N/A	Not present (tested)	Q34057S04	No asbestos detected	N/A	N/A	N/A	J.19; J.20
Jackson	Jackson Library	Building	55706	5BWR824	1-23 Edward St	1950's	Craig Carlson	8-Jul-20	Building	Building external asbestos cement sheeting infill panels above rear built-in verandah glazing and adjacent rear door	Cement based (1)	N/A	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	J.21; J.22
Jackson	Jackson Library	Building	55706	5BWR824	1-23 Edward St	1950's	Craig Carlson	8-Jul-20	Building	Amenities block male and female amenities masonite internal walls in main room with asbestos cement sheeting wall to external in cubicles and urinal	Cement based (1)	Bonded	Confirmed	Q34057S05	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	J.24; J.25; J.26
Jackson	Jackson SES and Rural Fire	SES Facility	55710	5BWR824	1-23 Edward St	1990's	Craig Carlson	8-Jul-20	Building	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	J.31
Jackson	Noonga Community Centre	Noonga Hall	63230	37BWR452	2237 Jackson Wandoan Rd	Opened 1929	Craig Carlson	3-Jul-20	Building	Main hall east section masonite and asbestos cement sheeting walls at random locations (predominantly masonite)	Cement based (1)	Bonded	Presumed	Similar to Q34057S01	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	J.01
Jackson	Noonga Community Centre	Noonga Hall	63230	37BWR452	2237 Jackson Wandoan Rd	Opened 1929	Craig Carlson	3-Jul-20	Building	Main hall throughout low density asbestos fibreboard ceiling sheeting both perforated and flat	Low density board (2)	Friable	Confirmed	Q34057S02	Chrysotile; amosite (2)	Fair (2)	Unsealed friable (3)	Medium	J.02; J.03
Jackson	Noonga Community Centre	Noonga Hall	63230	37BWR452	2237 Jackson Wandoan Rd	Opened 1929	Craig Carlson	3-Jul-20	Building	Kitchen asbestos cement sheeting walls and ceiling	Cement based (1)	Bonded	Confirmed	Q34057S01	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	J.04
Jackson	Noonga Community Centre	Noonga Hall	63230	37BWR452	2237 Jackson Wandoan Rd	Opened 1929	Craig Carlson	3-Jul-20	Building	Kitchen vinyl asbestos tile flooring	Vinyl tiles (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	J.05
Jackson	Noonga Community Centre	Noonga Hall	63230	37BWR452	2237 Jackson Wandoan Rd	Opened 1929	Craig Carlson	3-Jul-20	Building	Stage area electrical board mounting panel	Insulation board (2)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Unsealed bonded (2)	Low	J.06
Jackson	Noonga Community Centre	Noonga Hall	63230	37BWR452	2237 Jackson Wandoan Rd	Opened 1929	Craig Carlson	3-Jul-20	Building	Stage area electrical board internal box lining	Cement based (1)	Bonded	Presumed	None taken	Chrysotile; amosite (2)	Fair (2)	Unsealed bonded (2)	Medium	J.06
Jackson	Noonga Community Centre	Noonga Hall	63230	37BWR452	2237 Jackson Wandoan Rd	Opened 1929	Craig Carlson	3-Jul-20	Building	External east side asbestos cement sheeting soffits	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	J.07
Jackson	Noonga Community Centre	Noonga Hall	63230	37BWR452	2237 Jackson Wandoan Rd	Opened 1929	Craig Carlson	3-Jul-20	Building	External asbestos cement sheeting artificial weatherboard cladding on old stove recess	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	J.08
Jackson	Noonga Community Centre	Noonga Hall	63230	37BWR452	2237 Jackson Wandoan Rd	1970's	Craig Carlson	3-Jul-20	Building	Toilet block main construction all timber and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Jackson	Noonga Community Centre	Noonga Hall	63230	37BWR452	2237 Jackson Wandoan Rd	1970's	Craig Carlson	3-Jul-20	Building	Toilet block north wall disused electrical board compressed asbestos mounting panel	Insulation board (2)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Unsealed bonded (2)	Low	J.10

Town	Facility	Building	Asset No	Lot Plan	Address	Build Date	Auditor	Date of Inspection	ACM Location	Use of ACM / Component	ACM Material	Friable / Bonded	ACM Status	Sample #	ACM Type	ACM Condition	ACM Treatment	ACM Risk	Photo #
Jackson	Noonga Community Centre	Noonga Hall	63230	37BWR452	2237 Jackson Wandoan Rd	Post 2000	Craig Carlson	3-Jul-20	Building	Tennis clubhouse all steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	J.11
Jackson	RTC and Post Office	Building	55896	5BWR824	1-23 Edward St	1980's	Craig Carlson	8-Jul-20	Building	Internal asbestos cement sheeting walls and ceiling; external all metal sheeting	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	J.27; J.28