

Town	Facility	Building	Asset No	Lot Plan	Address	Build Date	Auditor	Date of Inspection	ACM Location	Use of ACM / Component	ACM Material	Friable / Bonded	ACM Status	Sample #	ACM Type	ACM Condition	ACM Treatment	ACM Risk	Photo #
Surat	Surat Aerodrome	Terminal Building	56166	124EG247	River Rd	1960's	Craig Carlson	19-Aug-20	Building	Internal asbestos cement sheeting walls and ceiling	Cement based (1)	Bonded	Presumed	Similar to Q34054S20	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.151
Surat	Surat Aerodrome	Terminal Building	56166	124EG247	River Rd	1960's	Craig Carlson	19-Aug-20	Building	External asbestos cement sheeting (shadowline) wall cladding; paint coating has deteriorated in areas	Cement based (1)	Bonded	Confirmed	Q34054S20	Chrysotile (1)	Fair (2)	Unsealed bonded (2)	Low	S.152; S.153
Surat	Surat Aerodrome	Terminal Building	56166	124EG247	River Rd	1960's	Craig Carlson	19-Aug-20	Building	External asbestos cement sheeting soffits including soffit inner wall lining along front of building	Cement based (1)	Bonded	Presumed	Similar to Q34054S20	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.154; S.155
Surat	Surat Aerodrome	Terminal Building	56166	124EG247	River Rd	1960's	Craig Carlson	19-Aug-20	Building	External asbestos cement sheeting infill panel on main door from runway side of building	Cement based (1)	Bonded	Presumed	Similar to Q34054S20	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.156
Surat	Surat Aerodrome	Toilet Block	56167	124EG247	River Rd	Post 2000	Craig Carlson	19-Aug-20	Public Amenities	Demountable internal timber laminate walls and ceiling with non-asbestos vinyl sheet flooring; external all metal sheeting; walkway flooring non-asbestos fibre cement sheeting	Cement based (1)	N/A	Not present (not tested)	None taken	No asbestos detected	N/A	N/A	N/A	S.157; S.158
Surat	Cobb and Co Changing Station	Museum	55851	1RP202318	Burrowes St	1880's (renovated 1996)	Craig Carlson	19-Aug-20	Building	Front foyer area plasterboard walls and ceiling tiles with non-asbestos vinyl tile flooring	Vinyl tiles (1)	N/A	Not present (not tested)	None taken	No asbestos detected	N/A	N/A	N/A	S.159
Surat	Cobb and Co Changing Station	Museum	55851	1RP202318	Burrowes St	1880's (renovated 1996)	Craig Carlson	19-Aug-20	Building	Centre west room non-asbestos fibre cement sheeting ceiling and wall to south and west external	Cement based (1)	N/A	Not present (not tested)	Similar to Q34054S21	No asbestos detected	N/A	N/A	N/A	S.160
Surat	Cobb and Co Changing Station	Museum	55851	1RP202318	Burrowes St	1880's (renovated 1996)	Craig Carlson	19-Aug-20	Building	Fish tank room timber and non-asbestos fibre cement sheeting walls and ceiling	Cement based (1)	N/A	Not present (tested)	Q34054S21	No asbestos detected	N/A	N/A	N/A	S.161; S.162
Surat	Cobb and Co Changing Station	Museum	55851	1RP202318	Burrowes St	1880's (renovated 1996)	Craig Carlson	19-Aug-20	Building	Back office area non-asbestos fibre cement sheeting walls and ceiling; non-asbestos vinyl sheet flooring	Cement based (1)	N/A	Not present (tested)	Q34054S22	No asbestos detected	N/A	N/A	N/A	S.163
Surat	Cobb and Co Changing Station	Museum	55851	1RP202318	Burrowes St	1880's (renovated 1996)	Craig Carlson	19-Aug-20	Building	Building external timber walls and front awning with metal sheeting roof	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Surat	Surat Library and Art Gallery	Building	55854	2SP147834	62-64 Burrowes St	1960's (renovated 1996)	Craig Carlson	19-Aug-20	Building	Back storage building all non-asbestos fibre cement sheeting internal walls and ceilings; all metal sheeting external construction	Cement based (1)	N/A	Not present (tested)	Q34054S23	No asbestos detected	N/A	N/A	N/A	S.164
Surat	Surat Library and Art Gallery	Building	55854	2SP147834	62-64 Burrowes St	1960's (renovated 1996)	Craig Carlson	19-Aug-20	Building	Amenities and amenities foyer asbestos cement sheeting walls and ceilings	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.165; S.166; S.167
Surat	Surat Library and Art Gallery	Building	55854	2SP147834	62-64 Burrowes St	1960's (renovated 1996)	Craig Carlson	19-Aug-20	Building	Main gallery non-asbestos fibre cement sheeting walls and walls and ceiling in storeroom	Cement based (1)	N/A	No asbestos detected	Q34054S24	No asbestos detected	N/A	N/A	N/A	S.168; S.169
Surat	Surat Library and Art Gallery	Building	55854	2SP147834	62-64 Burrowes St	1960's (renovated 1996)	Craig Carlson	19-Aug-20	Building	Library front room asbestos cement sheeting ceiling and upper wall to east offices, partition to gallery and partition to Cobb & Co at front office; masonite lower to east offices and infill panels above and under glazing to building external	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.170; S.171; S.172; S.173
Surat	Surat Library and Art Gallery	Building	55854	2SP147834	62-64 Burrowes St	1960's (renovated 1996)	Craig Carlson	19-Aug-20	Building	Library east offices asbestos cement sheeting ceiling (including in front office) and upper walls	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.174; S.175
Surat	Surat Library and Art Gallery	Building	55854	2SP147834	62-64 Burrowes St	1960's (renovated 1996)	Craig Carlson	19-Aug-20	Building	Old residential unit throughout including bath/laundry, main room, bedroom and kitchen asbestos cement sheeting ceiling; masonite walls and non-asbestos vinyl sheet flooring	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.176; S.177; S.178; S.179
Surat	Surat Library and Art Gallery	Building	55854	2SP147834	62-64 Burrowes St	1960's (renovated 1996)	Craig Carlson	19-Aug-20	Building	Building external asbestos cement sheeting (corrugated) wall above front awning with timber upper wall above asbestos cement	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.180; S.181
Surat	Surat Library and Art Gallery	Building	55854	2SP147834	62-64 Burrowes St	1960's (renovated 1996)	Craig Carlson	19-Aug-20	Building	Main building external brick and timber walls with metal sheeting roof and front awning ceiling and awning fascia panel	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Surat	Surat RSL Memorial Hall and Child Care	Building	55841	7035282	50-52 Burrowes St	1950's (Refurbished 1999)	Craig Carlson	9-Jul-20	Building	RSL offices including main office, kitchen and east offices timber and non-asbestos fibre cement sheeting walls and ceilings	Cement based (1)	N/A	Not present (not tested)	Q34054S09; Q34054S10	No asbestos detected	N/A	N/A	N/A	S.51; S.52; S.53

Town	Facility	Building	Asset No	Lot Plan	Address	Build Date	Auditor	Date of Inspection	ACM Location	Use of ACM / Component	ACM Material	Friable / Bonded	ACM Status	Sample #	ACM Type	ACM Condition	ACM Treatment	ACM Risk	Photo #
Surat	Surat RSL Memorial Hall and Child Care	Building	55841	703S282	50-52 Burrowes St	1950's (Refurbished 1999)	Craig Carlson	9-Jul-20	Building	RSL offices main office and east offices suspected vinyl asbestos tiles under carpet and exposed in storage cupboard	Vinyl tiles (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.54; S.55
Surat	Surat RSL Memorial Hall and Child Care	Building	55841	703S282	50-52 Burrowes St	1950's (Refurbished 1999)	Craig Carlson	9-Jul-20	Building	Public amenities non-asbestos fibre cement sheeting walls and ceiling	Cement based (1)	N/A	Not present (not tested)	Similar to Q34054S09; Q34054S10	No asbestos detected	N/A	N/A	N/A	S.56
Surat	Surat RSL Memorial Hall and Child Care	Building	55841	703S282	50-52 Burrowes St	1950's (Refurbished 1999)	Craig Carlson	9-Jul-20	Building	Child Care Centre throughout plasterboard and non-asbestos fibre cement sheeting walls and ceilings with non-asbestos vinyl sheet flooring	Cement based (1)	N/A	Not present (tested)	Q34054S11; Q34054S12	No asbestos detected	N/A	N/A	N/A	S.57 to S66
Surat	Surat RSL Memorial Hall and Child Care	Building	55841	703S282	50-52 Burrowes St	1950's (Refurbished 1999)	Craig Carlson	9-Jul-20	Building	External rear Child Care section non-asbestos fibre cement sheeting soffits and rear verandah ceiling	Cement based (1)	N/A	Not present (not tested)	None taken	No asbestos detected	N/A	N/A	N/A	S.67; S.68; S.73
Surat	Surat RSL Memorial Hall and Child Care	Building	55841	703S282	50-52 Burrowes St	1950's (Refurbished 1999)	Craig Carlson	9-Jul-20	Building	External Child Care access ramp non-asbestos fibre cement sheeting floor	Cement based (1)	N/A	Not present (not tested)	None taken	No asbestos detected	N/A	N/A	N/A	S.69
Surat	Surat RSL Memorial Hall and Child Care	Building	55841	703S282	50-52 Burrowes St	1950's (Refurbished 1999)	Craig Carlson	9-Jul-20	Building	External asbestos cement sheeting soffits on RSL wing and on front section of Child Care centre section including entry awning ceilings	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.70; S.71
Surat	Surat RSL Memorial Hall and Child Care	Building	55841	703S282	50-52 Burrowes St	1950's (Refurbished 1999)	Craig Carlson	9-Jul-20	Building	External asbestos cement lining in front foyers (two)	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.72
Surat	Surat RSL Memorial Hall and Child Care	Carport	55843	703S282	50-52 Burrowes St	Post 2000	Craig Carlson	9-Jul-20	Park	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Surat	Surat RSL Memorial Hall and Child Care	Shade Cover No1	55846	703S282	50-52 Burrowes St	Post 2000	Craig Carlson	9-Jul-20	Park	All steel and shadecloth construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Surat	Surat RSL Memorial Hall and Child Care	Shade Cover No2	75586	703S282	50-52 Burrowes St	Post 2000	Craig Carlson	9-Jul-20	Park	All steel and shadecloth construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Surat	Surat RSL Memorial Hall and Child Care	Shelter	55845	703S282	50-52 Burrowes St	Post 2000	Craig Carlson	9-Jul-20	Park	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Surat	Surat RSL Memorial Hall and Child Care	Storage Shed No1	55847	703S282	50-52 Burrowes St	Post 2000	Craig Carlson	9-Jul-20	Building	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Surat	Surat RSL Memorial Hall and Child Care	Storage Shed No2	55848	703S282	50-52 Burrowes St	Post 2000	Craig Carlson	9-Jul-20	Building	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Surat	Surat Shire Hall	Building	55832	17S282	56 William St	1930	Craig Carlson	19-Aug-20	Building	Front foyer asbestos cement sheeting upper walls and ceiling; lower walls timber	Cement based (1)	Bonded	Presumed	Similar to Q34054S28	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.202
Surat	Surat Shire Hall	Building	55832	17S282	56 William St	1930	Craig Carlson	19-Aug-20	Building	Front offices (two) asbestos cement sheeting upper walls and ceiling; lower walls timber	Cement based (1)	Bonded	Confirmed	Q34054S28	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.203; S.204
Surat	Surat Shire Hall	Building	55832	17S282	56 William St	1930	Craig Carlson	19-Aug-20	Building	Upper level asbestos cement sheeting fragments visible on ceiling of front offices; backs of asbestos cement wall sheets visible	Cement based (1)	Bonded	Confirmed	Q34054S29	Chrysotile (1)	Poor (3)	Unsealed bonded (2)	Medium	S.205; S.206
Surat	Surat Shire Hall	Building	55832	17S282	56 William St	1930	Craig Carlson	19-Aug-20	Building	Main hall asbestos cement sheeting upper walls and ceiling throughout including frame/truss boxing; timber lower walls	Cement based (1)	Bonded	Presumed	Similar to Q34054S28	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.207; S.208
Surat	Surat Shire Hall	Building	55832	17S282	56 William St	1930	Craig Carlson	19-Aug-20	Building	Main hall stage area asbestos cement sheeting upper walls and ceiling; timber lower walls	Cement based (1)	Bonded	Presumed	Similar to Q34054S28	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.209; S.210
Surat	Surat Shire Hall	Building	55832	17S282	56 William St	1930	Craig Carlson	19-Aug-20	Building	Building external timber walls with metal sheeting roof; asbestos cement sheeting walls and ceiling in main front entry foyer	Cement based (1)	Bonded	Presumed	Similar to Q34054S28	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.212
Surat	Surat Shire Hall	Pottery Shed	55835	17S282	56 William St	1990's	Craig Carlson	19-Aug-20	Building	Concrete block walls with metal sheeting roof and non-asbestos fibre cement sheeting upper walls	Cement based (1)	N/A	Not present (not tested)	Q34054S30	No asbestos detected	N/A	N/A	N/A	S.213
Surat	Surat Shire Hall	Storage Shed	55834	17S282	56 William St	Post 2000	Craig Carlson	19-Aug-20	Building	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.215

Town	Facility	Building	Asset No	Lot Plan	Address	Build Date	Auditor	Date of Inspection	ACM Location	Use of ACM / Component	ACM Material	Friable / Bonded	ACM Status	Sample #	ACM Type	ACM Condition	ACM Treatment	ACM Risk	Photo #
Surat	Surat Shire Hall	Amenities Building	Unknown	17S282	56 William St	Post 2000	Craig Carlson	19-Aug-20	Public Amenities	Concrete block walls with metal sheeting roof	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.214
Surat	Surat Shire Hall	Supper Room	55833	17S282	56 William St	1970's	Craig Carlson	19-Aug-20	Building	Main room masonite walls and ceiling and timber flooring	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Surat	Surat Shire Hall	Supper Room	55833	17S282	56 William St	1970's	Craig Carlson	19-Aug-20	Building	Kitchen asbestos cement sheeting ceiling in stove recess	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.216
Surat	Surat Shire Hall	Supper Room	55833	17S282	56 William St	1970's	Craig Carlson	19-Aug-20	Building	Kitchen asbestos cement sheeting lower west wall and wall in south west corner behind stove	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.217; S.218
Surat	Surat Shire Hall	Supper Room	55833	17S282	56 William St	1970's	Craig Carlson	19-Aug-20	Building	Kitchen asbestos cement sheeting walls and ceiling in cold room room	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.221
Surat	Surat Shire Hall	Supper Room	55833	17S282	56 William St	1970's	Craig Carlson	19-Aug-20	Building	Kitchen non-asbestos fibre cement sheeting partition wall to plate store and walls in plate store	Cement based (1)	N/A	Not present (tested)	Q34054S31	No asbestos detected	N/A	N/A	N/A	S.219; S.220
Surat	Surat Shire Hall	Supper Room	55833	17S282	56 William St	1970's	Craig Carlson	19-Aug-20	Building	Building external asbestos cement sheeting ceilings and soffits on two covered walkways to main hall	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.222; S.223
Surat	Surat Shire Hall	Supper Room	55833	17S282	56 William St	1970's	Craig Carlson	19-Aug-20	Building	Building external asbestos cement sheeting ceiling on back verandah/landing awning	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.224
Surat	Surat Shire Hall	Supper Room	55833	17S282	56 William St	1970's	Craig Carlson	19-Aug-20	Building	Building external timber walls with vinyl artificial weatherboard over; metal sheeting roof and asbestos cement sheeting soffits	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.225
Surat	Shop Front (prev Surat RTC)	Building	55928	803S282	70-72 Burrowes St	1970's	Craig Carlson	20-Aug-20	Building	Front entry foyer masonite walls with asbestos cement sheeting ceiling	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.227
Surat	Shop Front (prev Surat RTC)	Building	55928	803S282	70-72 Burrowes St	1970's	Craig Carlson	20-Aug-20	Building	Internal offices, main room and amenities masonite and concrete rendered brick walls	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Surat	Shop Front (prev Surat RTC)	Building	55928	803S282	70-72 Burrowes St	1970's	Craig Carlson	20-Aug-20	Building	Office strong room door may be internally insulated with asbestos insulation	Loose fill (3)	Friable	Presumed	None taken	Chrysotile (1)	Fair (2)	Sealed friable (2)	Medium	S.228
Surat	Shop Front (prev Surat RTC)	Building	55928	803S282	70-72 Burrowes St	1970's	Craig Carlson	20-Aug-20	Building	Roof/ceiling cavity asbestos cement sheeting old roofing fragments present suspected of being as a result of incomplete removal and decontamination; very; limited access due to low pitch of roof and only one ceiling access panel present	Cement based (1)	Bonded	Confirmed	Q34054S32	Chrysotile; amosite (2)	Poor (3)	Unsealed bonded (2)	Medium	S.229
Surat	Shop Front (prev Surat RTC)	Building	55928	803S282	70-72 Burrowes St	1970's	Craig Carlson	20-Aug-20	Building	Building external asbestos cement sheeting soffits and external ceilings	Cement based (1)	Bonded	Presumed	Similar to Q34054S32	Chrysotile; amosite (2)	Good (1)	Sealed bonded (1)	Low	S.231; S.232
Surat	Shop Front (prev Surat RTC)	Building	55928	803S282	70-72 Burrowes St	1970's	Craig Carlson	20-Aug-20	Building	Building external asbestos cement sheeting gable ends east and west sides	Cement based (1)	Bonded	Presumed	Similar to Q34054S32	Chrysotile; amosite (2)	Good (1)	Sealed bonded (1)	Low	S.233; S.234
Surat	Shop Front (prev Surat RTC)	Building	55928	803S282	70-72 Burrowes St	1970's	Craig Carlson	20-Aug-20	Building	Building external asbestos cement sheeting internal lining on electrical board	Cement based (1)	Bonded	Presumed	None taken	Chrysotile; amosite (2)	Fair (2)	Unsealed bonded (2)	Medium	S.235
Surat	Surat Administration Centre	Building	55922	35M1513	100 Cambridge St	1963	Craig Carlson	20-Aug-20	Building	Level 1 east office masonite and brick walls with timber fibre ceiling; asbestos cement sheeting upper walls and ceiling in void adjacent glazing to roof	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.289
Surat	Surat Administration Centre	Building	55922	35M1513	100 Cambridge St	1963	Craig Carlson	20-Aug-20	Building	Level 1 east office strong room door may be internally insulated with asbestos insulation	Loose fill (3)	Friable	Presumed	None taken	Chrysotile (1)	Fair (2)	Sealed friable (2)	Medium	S.290
Surat	Surat Administration Centre	Building	55922	35M1513	100 Cambridge St	1963	Craig Carlson	20-Aug-20	Building	Level 1, two centre offices masonite walls with timber fibre ceiling; asbestos cement sheeting upper walls and ceiling in void adjacent glazing to roof	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.291; S.292
Surat	Surat Administration Centre	Building	55922	35M1513	100 Cambridge St	1963	Craig Carlson	20-Aug-20	Building	Level 1 foyer, stairwell and reception plasterboard, timber and concrete walls with non-asbestos vermiculite insulated fibrous plaster ceiling	Sprayed coating (3)	N/A	Not present (not tested)	Similar to Q34054S47	No asbestos detected	N/A	N/A	N/A	S.293; S.294
Surat	Surat Administration Centre	Building	55922	35M1513	100 Cambridge St	1963	Craig Carlson	20-Aug-20	Building	Level 1 foyer area asbestos cement sheeting partition to amenities area	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.295

Town	Facility	Building	Asset No	Lot Plan	Address	Build Date	Auditor	Date of Inspection	ACM Location	Use of ACM / Component	ACM Material	Friable / Bonded	ACM Status	Sample #	ACM Type	ACM Condition	ACM Treatment	ACM Risk	Photo #
Surat	Surat Administration Centre	Building	55922	35M1513	100 Cambridge St	1963	Craig Carlson	20-Aug-20	Building	Level 1 foyer and lunch room vinyl asbestos tile flooring	Vinyl tiles (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.296; S.297
Surat	Surat Administration Centre	Building	55922	35M1513	100 Cambridge St	1963	Craig Carlson	20-Aug-20	Building	Level 1 male and female amenities masonite walls and ceilings	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.298; S.299
Surat	Surat Administration Centre	Building	55922	35M1513	100 Cambridge St	1963	Craig Carlson	20-Aug-20	Building	Level 1 amenities asbestos cement vent pipes in service riser and ceiling cavity to building roof	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Fair (2)	Unsealed bonded (2)	Low	S.300
Surat	Surat Administration Centre	Building	55922	35M1513	100 Cambridge St	1963	Craig Carlson	20-Aug-20	Building	Level 1 roof cavity rear of asbestos cement sheeting façade panels visible in front glazing void	Cement based (1)	Bonded	Confirmed	Q34054S44	Chrysotile; amosite (2)	Fair (2)	Unsealed bonded (2)	Medium	No image
Surat	Surat Administration Centre	Building	55922	35M1513	100 Cambridge St	1963	Craig Carlson	20-Aug-20	Building	Level G corridor to west external, centre offices, lunch room, stairwell skirting and stair tread fascia's vinyl asbestos tile flooring	Vinyl tiles (1)	Bonded	Confirmed	Q34054S43	Chrysotile (1)	Fair (2)	Sealed bonded (1)	Low	S.303; S.304; S.305; S.306; S.307; S.308
Surat	Surat Administration Centre	Building	55922	35M1513	100 Cambridge St	1963	Craig Carlson	20-Aug-20	Building	Level G west offices concrete and masonite walls with masonite ceilings	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Surat	Surat Administration Centre	Building	55922	35M1513	100 Cambridge St	1963	Craig Carlson	20-Aug-20	Building	Level G east end office asbestos cement sheeting upper ceiling above suspended ceiling; sheeting has sustained damage as a result of penetrations	Cement based (1)	Bonded	Confirmed	Q34054S46	Chrysotile (1)	Poor (3)	Unsealed bonded (2)	Medium	S.309, S.310
Surat	Surat Administration Centre	Building	55922	35M1513	100 Cambridge St	1963	Craig Carlson	20-Aug-20	Building	Building external asbestos cement sheeting back wall on level 1 and ceiling/soffits on back verandah	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.311; S.312; S.313
Surat	Surat Administration Centre	Building	55922	35M1513	100 Cambridge St	1963	Craig Carlson	20-Aug-20	Building	Building external non-asbestos fibre cement sheeting stair landings on back stairs	Cement based (1)	N/A	Not present (not tested)	None taken	No asbestos detected	N/A	N/A	N/A	S.314
Surat	Surat Administration Centre	Building	55922	35M1513	100 Cambridge St	1963	Craig Carlson	20-Aug-20	Building	Building external asbestos cement sheeting ceiling on east awning with timber slats over	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.315
Surat	Surat Administration Centre	Building	55922	35M1513	100 Cambridge St	1963	Craig Carlson	20-Aug-20	Building	Building external asbestos cement sheeting panel between glazing to roof cavity along front of building (sampled internally)	Cement based (1)	Bonded	Confirmed	Q34054S44	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.316; S.317
Surat	Surat Administration Centre	Building	55922	35M1513	100 Cambridge St	1963	Craig Carlson	20-Aug-20	Building	Building external asbestos cement sheeting ceiling/soffits on front glazing void	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.318
Surat	Surat Administration Centre	Building	55922	35M1513	100 Cambridge St	1963	Craig Carlson	20-Aug-20	Building	Building external suspected asbestos cement sheeting ceiling on covered walkways and front entry foyer with non-asbestos vermiculite spray over	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.319; S.320
Surat	Surat Administration Centre	Carport	55925	35M1513	100 Cambridge St	1980's	Craig Carlson	20-Aug-20	Building	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Surat	Surat Council Depot	Parks Shed	56115	5RP67606	Ivan St	1990's	Craig Carlson	19-Aug-20	Depot	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.199
Surat	Surat Council Depot	Toilet Block	62621	5RP67606	Ivan St	1990's	Craig Carlson	19-Aug-20	Depot	Internal and external non-asbestos fibre cement sheeting walls and ceilings	Cement based (1)	N/A	Not present (tested)	Q34054S27	No asbestos detected	N/A	N/A	N/A	S.200; S.201
Surat	Surat Council Depot	WIP - New Amenities 2019-2020	77196	5RP67606	Ivan St	Post 2000	Craig Carlson	19-Aug-20	Depot	Amenities areas throughout non-asbestos fibre cement sheeting walls and ceiling with resin flooring; part of Workshop and Store Building	Cement based (1)	N/A	Not present (not tested)	Similar to Q34054S26	No asbestos detected	N/A	N/A	N/A	S.191; S.192; S.193
Surat	Surat Council Depot	Workshop and Store	56112	5RP67606	Ivan St	1990's	Craig Carlson	19-Aug-20	Depot	Main workshop metal sheeting roof and walls with non-asbestos fibre cement sheeting wall to office and internal walls and ceiling in office	Cement based (1)	N/A	Not present (not tested)	Similar to Q34054S26	No asbestos detected	N/A	N/A	N/A	S.183; S.184
Surat	Surat Council Depot	Workshop and Store	56112	5RP67606	Ivan St	1990's	Craig Carlson	19-Aug-20	Depot	Tool store non-asbestos fibre cement sheeting partition to store	Cement based (1)	N/A	Not present (not tested)	Similar to Q34054S26	No asbestos detected	N/A	N/A	N/A	S.185
Surat	Surat Council Depot	Workshop and Store	56112	5RP67606	Ivan St	1990's	Craig Carlson	19-Aug-20	Depot	Main store metal sheeting and non-asbestos fibre cement sheeting walls including mezzanine level store room	Cement based (1)	N/A	Not present (not tested)	Similar to Q34054S26	No asbestos detected	N/A	N/A	N/A	S.186; S.187
Surat	Surat Council Depot	Workshop and Store	56112	5RP67606	Ivan St	1990's	Craig Carlson	19-Aug-20	Depot	Stores offices (two) non-asbestos fibre cement sheeting walls and ceilings	Cement based (1)	N/A	Not present (not tested)	Similar to Q34054S26	No asbestos detected	N/A	N/A	N/A	S.188; S.189

Town	Facility	Building	Asset No	Lot Plan	Address	Build Date	Auditor	Date of Inspection	ACM Location	Use of ACM / Component	ACM Material	Friable / Bonded	ACM Status	Sample #	ACM Type	ACM Condition	ACM Treatment	ACM Risk	Photo #
Surat	Surat Council Depot	Workshop and Store	56112	5RP67606	Ivan St	1990's	Craig Carlson	19-Aug-20	Depot	Lunch room non-asbestos fibre cement sheeting walls and ceiling	Cement based (1)	N/A	Not present (tested)	S34054526	No asbestos detected	N/A	N/A	N/A	S.190
Surat	Surat Council Depot	Wash Bay Shed	Unknown	5RP67606	Ivan St	1990's	Craig Carlson	19-Aug-20	Depot	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.194
Surat	Surat Council Depot	Carpenter's Shed	Unknown	5RP67606	Ivan St	1960's	Craig Carlson	19-Aug-20	Depot	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.195
Surat	Surat Council Depot	Carpenter's Shed	Unknown	5RP67606	Ivan St	1960's	Craig Carlson	19-Aug-20	Depot	Stored equipment may have asbestos textile gaskets; unable to confirm without dismantling of equipment	Woven textile (2)	Friable	Presumed	None taken	Chrysotile (1)	Fair (2)	Unsealed friable (3)	Medium	S.196
Surat	Surat Council Depot	Cement Shed	Unknown	5RP67606	Ivan St	1970's	Craig Carlson	19-Aug-20	Depot	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.197
Surat	Surat Council Depot	Chemical Shed	Unknown	5RP67606	Ivan St	1970's	Craig Carlson	19-Aug-20	Depot	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.198
Surat	Workers Camp (Begonia)	Accommodation R01-R03 - PL1102	56096	10MAR85	Begonia Rd	1980's	Craig Carlson	30-Jul-20	Depot	Demountable internal timber laminate walls and ceiling with non-asbestos vinyl sheet flooring; external all metal sheeting	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.113
Surat	Workers Camp (Begonia)	Accommodation R04-R06 - PL1103	27089	10MAR85	Begonia Rd	1980's	Craig Carlson	30-Jul-20	Depot	Demountable internal timber laminate walls and ceiling with non-asbestos vinyl sheet flooring; external all metal sheeting	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.114
Surat	Workers Camp (Begonia)	Accommodation R07-R08 - PL1108	68060	10MAR85	Begonia Rd	Post 2000	Craig Carlson	30-Jul-20	Depot	Demountable all metal sandwich panel internal walls and ceiling and metal sheeting external walls and roof	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.115
Surat	Workers Camp (Begonia)	Accommodation R09-R11 - PL2011	68067	10MAR85	Begonia Rd	1990's	Craig Carlson	30-Jul-20	Depot	Shipping container all steel external and metal sandwich panel internal walls and ceiling	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.116
Surat	Workers Camp (Begonia)	Awning	56098	10MAR85	Begonia Rd	Post 2000	Craig Carlson	30-Jul-20	Depot	All metal sandwich panel construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.118
Surat	Workers Camp (Begonia)	Toilet Block	Unknown	10MAR85	Begonia Rd	1980's	Craig Carlson	30-Jul-20	Depot	Demountable all metal sandwich panel internal walls and ceiling and metal sheeting external walls and roof	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.117
Surat	Recreation Oval	Canteen - Demolished	28252	2S2821	Ivan St	Building no longer present	Craig Carlson	20-Aug-20	Building	Demolished	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Surat	Recreation Oval	Canteen and Bar	55552	2S2821	Ivan St	Post 2000	Craig Carlson	20-Aug-20	Building	Internal all non-asbestos fibre cement sheeting walls with metal sheeting ceiling; external all metal sheeting roof and walls	Cement based (1)	N/A	Not present (not tested)	None taken	No asbestos detected	N/A	N/A	N/A	S.270; S.271; S.272
Surat	Recreation Oval	Playground Shade	28259	2S2821	Ivan St	Post 2000	Craig Carlson	20-Aug-20	Park	All steel and shadecloth construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.273
Surat	Recreation Oval	Shelter (at Entrance)	28263	2S2821	Ivan St	1990's	Craig Carlson	20-Aug-20	Park	All steel, timber and metal sheeting construction; non-asbestos fibre cement sheeting small gable ends in roof structure	Cement based (1)	N/A	Not present (tested)	Q34054539	No asbestos detected	N/A	N/A	N/A	S.274; S.275; S.276
Surat	Recreation Oval	Shelter (at Playground)	62625	2S2821	Ivan St	1990's	Craig Carlson	20-Aug-20	Park	All steel, timber and metal sheeting construction; non-asbestos fibre cement sheeting small gable ends in roof structure	Cement based (1)	N/A	Not present (not tested)	Similar to Q34054539	No asbestos detected	N/A	N/A	N/A	S.277; S.278
Surat	Recreation Oval	Toilet Block	28251	2S2821	Ivan St	1980's	Craig Carlson	20-Aug-20	Public Amenities	Concrete block walls with metal sheeting roof; non-asbestos fibre cement sheeting partition at shower in male amenities	Cement based (1)	N/A	Not present (tested)	Q34054540	No asbestos detected	N/A	N/A	N/A	S.279, S.280
Surat	Recreation Oval	Grandstand	Unknown	2S2821	Ivan St	1970's	Craig Carlson	20-Aug-20	Park	All steel, timber and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.281
Surat	Surat Swimming Pool	Change Rooms - Roof	56302	13S288	70-74 Robert St	1967	Craig Carlson	20-Aug-20	Swimming Pool	Metal sheeting and timber ceiling and façade panels; no access to roof	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.238
Surat	Surat Swimming Pool	Change Rooms - Roof	56302	13S288	70-74 Robert St	1967	Craig Carlson	20-Aug-20	Swimming Pool	Asbestos cement sheeting infill panels on ends of roller doors/grilles at main entry	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.240; S.241
Surat	Surat Swimming Pool	Change Rooms and Toilet Block (Female)	56009	13S288	70-74 Robert St	1967	Craig Carlson	20-Aug-20	Swimming Pool	Brick walls with metal sheeting roof; asbestos cement sheeting ceiling in storeroom at entry	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.237
Surat	Surat Swimming Pool	Change Rooms and Toilet Block (Male)	56008	13S288	70-74 Robert St	1967	Craig Carlson	20-Aug-20	Swimming Pool	Brick and masonite artificial weatherboard walls with metal sheeting roof	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image

Town	Facility	Building	Asset No	Lot Plan	Address	Build Date	Auditor	Date of Inspection	ACM Location	Use of ACM / Component	ACM Material	Friable / Bonded	ACM Status	Sample #	ACM Type	ACM Condition	ACM Treatment	ACM Risk	Photo #
Surat	Surat Swimming Pool	Kiosk	56007	13S288	70-74 Robert St	1967	Craig Carlson	20-Aug-20	Swimming Pool	Kiosk/office brick walls with asbestos cement sheeting ceiling and partition to male change room	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.236
Surat	Surat Swimming Pool	Kiosk	56007	13S288	70-74 Robert St	1967	Craig Carlson	20-Aug-20	Swimming Pool	Storeroom brick walls with timber ceiling	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Surat	Surat Swimming Pool	Kiosk	56007	13S288	70-74 Robert St	1967	Craig Carlson	20-Aug-20	Swimming Pool	Ticket office brick and timber walls with timber ceiling	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Surat	Surat Swimming Pool	Kiosk	56007	13S288	70-74 Robert St	1967	Craig Carlson	20-Aug-20	Swimming Pool	External asbestos cement sheeting infill panels beside roller doors to office; timber upper panels	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.239
Surat	Surat Swimming Pool	Lawn Locker	56013	13S288	70-74 Robert St	1990's	Craig Carlson	20-Aug-20	Swimming Pool	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.244
Surat	Surat Swimming Pool	Shade Shelter - Swimming Pool	62615	13S288	70-74 Robert St	Post 2000	Craig Carlson	20-Aug-20	Swimming Pool	All steel and shadecloth construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.245
Surat	Surat Swimming Pool	Shade Shelter - Wading Pool	62596	13S288	70-74 Robert St	Post 2000	Craig Carlson	20-Aug-20	Swimming Pool	All steel and shadecloth construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.246
Surat	Surat Swimming Pool	Storage Shed	56012	13S288	70-74 Robert St	1970's	Craig Carlson	20-Aug-20	Swimming Pool	Storeroom and pump room brick walls with asbestos cement sheeting ceiling	Cement based (1)	Bonded	Confirmed	Q34054S33	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.247; S.248; S.249
Surat	Surat Swimming Pool	Storage Shed	56012	13S288	70-74 Robert St	1970's	Craig Carlson	20-Aug-20	Swimming Pool	Acid store brick walls with asbestos cement sheeting ceiling; non-asbestos fibre cement sheeting wall panel at doorway	Cement based (1)	Bonded	Confirmed	Similar to Q34054S33	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.250; S.251
Surat	Surat Swimming Pool	Storage Shed	56012	13S288	70-74 Robert St	1970's	Craig Carlson	20-Aug-20	Swimming Pool	Building external asbestos cement sheeting soffits and infill panel above front door to pump room	Cement based (1)	Bonded	Confirmed	Similar to Q34054S33	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.252; S.253
Surat	Surat Swimming Pool	Swimming Club Shed	56014	13S288	70-74 Robert St	1990's	Craig Carlson	20-Aug-20	Swimming Pool	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.243
Surat	Surat Swimming Pool	Chemical Shed	Unknown	13S288	70-74 Robert St	1990's	Craig Carlson	20-Aug-20	Swimming Pool	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.242
Surat	Surat Tennis Courts	Clubhouse	28373	2S2821	Ivan St	1993	Craig Carlson	20-Aug-20	Building	Internal bar area and centre room non-asbestos fibre cement sheeting walls and ceilings	Cement based (1)	N/A	Not present (tested)	Q34054S41	No asbestos detected	N/A	N/A	N/A	S.282; S.283
Surat	Surat Tennis Courts	Clubhouse	28373	2S2821	Ivan St	1993	Craig Carlson	20-Aug-20	Building	Internal kitchen non-asbestos fibre cement sheeting walls and ceiling and non-asbestos vinyl sheet floor	Cement based (1)	N/A	Not present (tested)	Q34054S42	No asbestos detected	N/A	N/A	N/A	S.284
Surat	Surat Tennis Courts	Clubhouse	28373	2S2821	Ivan St	1993	Craig Carlson	20-Aug-20	Building	Male and female amenities non-asbestos fibre cement sheeting walls and ceilings	Cement based (1)	N/A	Not present (not tested)	Similar to Q34054S42	No asbestos detected	N/A	N/A	N/A	S.285; S.286
Surat	Surat Tennis Courts	Clubhouse	28373	2S2821	Ivan St	1993	Craig Carlson	20-Aug-20	Building	External masonite artificial weatherboard walls with non-asbestos fibre cement sheeting soffits and external ceilings	Cement based (1)	N/A	Not present (not tested)	Similar to Q34054S42	No asbestos detected	N/A	N/A	N/A	S.287; S.288
Surat	Warroo Sporting Complex - Racecourse	Bar and Covered Area	55994	85EG141	229 Surat Development Rd	1990's	Craig Carlson	20-Aug-20	Building	Non-asbestos fibre cement sheeting artificial weatherboard walls and gable end and compressed non-asbestos fibre cement sheeting counter top	Cement based (1)	N/A	Not present (tested)	Q34054S34; Q34054S35	No asbestos detected	N/A	N/A	N/A	S.255; S.256; S.257
Surat	Warroo Sporting Complex - Racecourse	Fluctuation Box	55996	85EG141	229 Surat Development Rd	Post 2000	Craig Carlson	20-Aug-20	Building	New demountable building	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.258
Surat	Warroo Sporting Complex - Racecourse	Grandstand and Canteen	55992	85EG141	229 Surat Development Rd	1970's (renovated post 2000)	Craig Carlson	20-Aug-20	Building	Lower level kitchen throughout non-asbestos fibre cement sheeting walls and ceilings	Cement based (1)	N/A	Not present (tested)	Q34054S36; Q34084S37	No asbestos detected	N/A	N/A	N/A	S.259; S.260; S.261
Surat	Warroo Sporting Complex - Racecourse	Grandstand and Canteen	55992	85EG141	229 Surat Development Rd	1970's (renovated post 2000)	Craig Carlson	20-Aug-20	Building	External non-asbestos fibre cement sheeting walls on kitchen, wall at kitchen entry and infill panels adjacent servery roller doors	Cement based (1)	N/A	Not present (tested)	Q34084S38	No asbestos detected	N/A	N/A	N/A	S.262; S.263; S.264

Town	Facility	Building	Asset No	Lot Plan	Address	Build Date	Auditor	Date of Inspection	ACM Location	Use of ACM / Component	ACM Material	Friable / Bonded	ACM Status	Sample #	ACM Type	ACM Condition	ACM Treatment	ACM Risk	Photo #
Surat	Warroo Sporting Complex - Racecourse	Jockeys Room	55993	85EG141	229 Surat Development Rd	Post 2000	Craig Carlson	20-Aug-20	Building	New demountable building	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.258
Surat	Warroo Sporting Complex - Racecourse	Photo Finish Tower	55995	85EG141	229 Surat Development Rd	1990's	Craig Carlson	20-Aug-20	Building	All steel and metal sheeting construction; no access to upper level	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.265
Surat	Warroo Sporting Complex - Racecourse	Shed No1	56000	85EG141	229 Surat Development Rd	1980's	Craig Carlson	20-Aug-20	Building	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.266
Surat	Warroo Sporting Complex - Racecourse	Shed No2	56001	85EG141	229 Surat Development Rd	1980's	Craig Carlson	20-Aug-20	Building	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.267
Surat	Warroo Sporting Complex - Racecourse	Shower and Toilet Block	56002	85EG141	229 Surat Development Rd	Post 2000	Craig Carlson	20-Aug-20	Public Amenities	Demountable all metal sandwich panel construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.268
Surat	Warroo Sporting Complex - Racecourse	Shower and Toilet Block	56002	85EG141	229 Surat Development Rd	Post 2000	Craig Carlson	20-Aug-20	Public Amenities	Demountable all timber laminate and non-asbestos fibre cement sheeting internal construction; metal sheeting external construction	Cement based (1)	N/A	Not present (not tested)	None taken	No asbestos detected	N/A	N/A	N/A	S.269
Surat	AG Nason Park	Play Shelter	28325	1RP90497	Cordelia St	Post 2000	Craig Carlson	16-Aug-20	Park	All steel and shadecloth construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.119
Surat	AG Nason Park	Table Shelter	28330	1RP90497	Cordelia St	1990's	Craig Carlson	16-Aug-20	Park	All steel, timber and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.120
Surat	Fisherman's Park	Caravan Park Shelter	56018	Road Reserve	Carnarvon Hwy	1990's	Craig Carlson	16-Aug-20	Park	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.124
Surat	Fisherman's Park	Shelter No1	56017	Road Reserve	Carnarvon Hwy	1990's	Craig Carlson	16-Aug-20	Park	All steel, timber and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.121
Surat	Fisherman's Park	Shelter No2	62302	Road Reserve	Carnarvon Hwy	1990's	Craig Carlson	16-Aug-20	Park	All steel, timber and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.122
Surat	Fisherman's Park	Shelter No3	62303	Road Reserve	Carnarvon Hwy	1990's	Craig Carlson	16-Aug-20	Park	All steel, timber and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.123
Surat	Fisherman's Park	Shower and Toilet Block - New	55550	Road Reserve	Carnarvon Hwy	Post 2000	Craig Carlson	16-Aug-20	Public Amenities	Internal all non-asbestos fibre cement sheeting walls and ceiling and non-asbestos vinyl sheet flooring; external all metal sheeting	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.125; S.126
Surat	Lions Park	BBQ Shelter	28271	Road Reserve	Third Av - NW cnr Annandale	Post 2000	Craig Carlson	16-Aug-20	Park	Shelter all steel and metal sheeting construction; barbecue concrete block construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.127
Surat	Lions Park	Information Signage Shelter	75589	Road Reserve	Third Av - NW cnr Annandale	Post 2000	Craig Carlson	16-Aug-20	Park	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.128
Surat	Lions Park	Table Shelter	28269	Road Reserve	Third Av - NW cnr Annandale	1990's	Craig Carlson	16-Aug-20	Park	Shelters no longer present; tables only remain	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.129; S.130; S.131
Surat	Memorial Park Riverside Park	BBQ Shelter	28350	96EG176	Marcus St	Unable to locate	Craig Carlson	16-Aug-20	Park	See above BBQ shelter for Lions Park	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.127
Surat	Memorial Park Riverside Park	Gazebo	28352	96EG176	Marcus St	Post 2000	Craig Carlson	16-Aug-20	Park	All timber construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.132
Surat	Memorial Park Riverside Park	New Shade Shelter	62664	96EG176	Marcus St	Post 2000	Craig Carlson	16-Aug-20	Park	All timber and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.133
Surat	Memorial Park Riverside Park	Shade Shelter	28349	96EG176	Marcus St	Post 2000	Craig Carlson	16-Aug-20	Park	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.134
Surat	Memorial Park Riverside Park	Shelter	28351	96EG176	Marcus St	Unable to locate	Craig Carlson	16-Aug-20	Park	Suspect structure removed	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Surat	Memorial Park Riverside Park	Toilet Block	Unknown	96EG176	Marcus St	1970's	Craig Carlson	16-Aug-20	Public Amenities	All concrete walls, floor and ceiling; appears to be an old water tank	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.135
Surat	River Walk	Canvas Shade Shelters x8	28296	120EG226	Marcus St	Post 2000	Craig Carlson	16-Aug-20	Park	Canvas covers removed; only posts and tables remain which are all timber construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.136
Surat	River Walk	Community Shelter	56040	120EG226	Marcus St	Post 2000	Craig Carlson	16-Aug-20	Park	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.137
Surat	River Walk	Gazebo Shelter	28302	120EG226	Marcus St	Unable to locate	Craig Carlson	16-Aug-20	Park	Unable to locate; see Gazebo above in Memorial Park	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.132
Surat	River Walk	Shade Shelter	28310	120EG226	Marcus St	Unable to locate	Craig Carlson	16-Aug-20	Park	Suspect structure removed	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image

Town	Facility	Building	Asset No	Lot Plan	Address	Build Date	Auditor	Date of Inspection	ACM Location	Use of ACM / Component	ACM Material	Friable / Bonded	ACM Status	Sample #	ACM Type	ACM Condition	ACM Treatment	ACM Risk	Photo #
Surat	Weir Park	Picnic Shelter 1	28283	3S287	River Rd	Unable to locate	Craig Carlson	16-Aug-20	Park	Suspect structure removed	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Surat	Weir Park	Picnic Shelter 2	28284	3S287	River Rd	Unable to locate	Craig Carlson	16-Aug-20	Park	Suspect structure removed	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Surat	Weir Park	Picnic Shelter 3	28285	3S287	River Rd	Unable to locate	Craig Carlson	16-Aug-20	Park	Suspect structure removed	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Surat	112 William Street	Dwelling	28801	604S2816	112 William St	1990's	Craig Carlson	9-Jul-20	Building	Lounge, kitchen, dining and bedrooms plasterboard walls and ceilings with carpet and tile flooring	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Surat	112 William Street	Dwelling	28801	604S2816	112 William St	1990's	Craig Carlson	9-Jul-20	Building	Laundry, toilet and bathroom non-asbestos fibre cement sheeting walls and ceilings	Cement based (1)	N/A	Not present (tested)	Q34054S03	No asbestos detected	N/A	N/A	N/A	S.07; S.08; S.09
Surat	112 William Street	Dwelling	28801	604S2816	112 William St	1990's	Craig Carlson	9-Jul-20	Building	Building external non-asbestos fibre cement sheeting artificial weatherboard walls	Cement based (1)	N/A	Not present (tested)	Q34054S04	No asbestos detected	N/A	N/A	N/A	S.10
Surat	112 William Street	Dwelling	28801	604S2816	112 William St	1990's	Craig Carlson	9-Jul-20	Building	Building external non-asbestos fibre cement sheeting soffits, carport ceiling and verandah ceiling	Cement based (1)	N/A	Not present (not tested)	Similar to Q34054S03	No asbestos detected	N/A	N/A	N/A	S.11; S.12
Surat	112 William Street	Dwelling	28801	604S2816	112 William St	1990's	Craig Carlson	9-Jul-20	Building	Rear shed timber and non-asbestos fibre cement sheeting artificial weatherboard walls and metal sheeting roof	Cement based (1)	N/A	Not present (not tested)	Similar to Q34054S04	No asbestos detected	N/A	N/A	N/A	S.13
Surat	113 Robert Street	Dwelling Duplex 113a-113b	28959	610S2816	113 Robert St	1970's	Craig Carlson	9-Jul-20	Building	113A vinyl asbestos tiles in kitchen, hallway, toilet, laundry and suspected under carpet in bedroom	Vinyl tiles (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.14
Surat	113 Robert Street	Dwelling Duplex 113a-113b	28959	610S2816	113 Robert St	1970's	Craig Carlson	9-Jul-20	Building	113A kitchen asbestos cement sheeting ceiling and infill panels under glazing to external (two)	Cement based (1)	Bonded	Presumed	Similar to Q34054S05	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.15; S.16
Surat	113 Robert Street	Dwelling Duplex 113a-113b	28959	610S2816	113 Robert St	1970's	Craig Carlson	9-Jul-20	Building	113A front bedroom asbestos cement sheeting ceiling and wall panels at random (along with masonite)	Cement based (1)	Bonded	Confirmed	Q34054S05	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.17
Surat	113 Robert Street	Dwelling Duplex 113a-113b	28959	610S2816	113 Robert St	1970's	Craig Carlson	9-Jul-20	Building	113A hall asbestos cement sheeting ceiling and wall panels at random (along with masonite)	Cement based (1)	Bonded	Presumed	Similar to Q34054S05	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.18
Surat	113 Robert Street	Dwelling Duplex 113a-113b	28959	610S2816	113 Robert St	1970's	Craig Carlson	9-Jul-20	Building	113A toilet asbestos cement sheeting ceiling and wall panels at random (along with masonite)	Cement based (1)	Bonded	Presumed	Similar to Q34054S05	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.19
Surat	113 Robert Street	Dwelling Duplex 113a-113b	28959	610S2816	113 Robert St	1970's	Craig Carlson	9-Jul-20	Building	113A laundry and bathroom asbestos cement sheeting walls and ceilings	Cement based (1)	Bonded	Presumed	Similar to Q34054S05	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.20; S.21
Surat	113 Robert Street	Dwelling Duplex 113a-113b	28959	610S2816	113 Robert St	1970's	Craig Carlson	9-Jul-20	Building	113B vinyl asbestos tiles in hallway and laundry	Vinyl tiles (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.22; S.25
Surat	113 Robert Street	Dwelling Duplex 113a-113b	28959	610S2816	113 Robert St	1970's	Craig Carlson	9-Jul-20	Building	113B kitchen and bathroom asbestos cement sheeting walls and ceiling	Cement based (1)	Bonded	Presumed	Similar to Q34054S05	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.23; S.24
Surat	113 Robert Street	Dwelling Duplex 113a-113b	28959	610S2816	113 Robert St	1970's	Craig Carlson	9-Jul-20	Building	113B hallway, front east bedroom and toilet asbestos cement sheeting ceilings	Cement based (1)	Bonded	Confirmed	Similar to Q34054S05	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.26; S.27; S.28
Surat	113 Robert Street	Dwelling Duplex 113a-113b	28959	610S2816	113 Robert St	1970's	Craig Carlson	9-Jul-20	Building	113B laundry asbestos cement sheeting ceiling and wall infill panels around door to external	Cement based (1)	Bonded	Presumed	Similar to Q34054S05	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.29
Surat	113 Robert Street	Dwelling Duplex 113a-113b	28959	610S2816	113 Robert St	1970's	Craig Carlson	9-Jul-20	Building	113B asbestos cement sheeting walls and ceiling in cupboard	Cement based (1)	Bonded	Presumed	Similar to Q34054S05	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.30
Surat	113 Robert Street	Dwelling Duplex 113a-113b	28959	610S2816	113 Robert St	1970's	Craig Carlson	9-Jul-20	Building	Building external asbestos cement sheeting soffits and external foyer ceilings	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.31
Surat	113 Robert Street	Dwelling Duplex 113a-113b	28959	610S2816	113 Robert St	1970's	Craig Carlson	9-Jul-20	Building	Building external asbestos cement sheeting walls including infill panels above and under glazing	Cement based (1)	Bonded	Confirmed	Q34054S06	Chrysotile; amosite (2)	Good (1)	Sealed bonded (1)	Low	S.32; S.33; S.34
Surat	114 William Street	Dwelling	28805	2SP188008	114 William St	1960's	Craig Carlson	9-Jul-20	Building	Lounge, kitchen, dining, centre hall and bedrooms (three) plasterboard and masonite walls and ceilings with carpet and non-asbestos vinyl sheet flooring	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Surat	114 William Street	Dwelling	28805	2SP188008	114 William St	1960's	Craig Carlson	9-Jul-20	Building	Centre hall cupboard asbestos cement sheeting walls and ceiling	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Fair (2)	Unsealed bonded (2)	Low	S.41

Town	Facility	Building	Asset No	Lot Plan	Address	Build Date	Auditor	Date of Inspection	ACM Location	Use of ACM / Component	ACM Material	Friable / Bonded	ACM Status	Sample #	ACM Type	ACM Condition	ACM Treatment	ACM Risk	Photo #
Surat	114 William Street	Dwelling	28805	2SP188008	114 William St	1960's	Craig Carlson	9-Jul-20	Building	Bathroom, laundry and toilet low density asbestos fibreboard ceilings	Low density board (2)	Friable	Confirmed	Q34054S08	Chrysotile; amosite (2)	Good (1)	Sealed friable (2)	Medium	S.42; S.43; S.44
Surat	114 William Street	Dwelling	28805	2SP188008	114 William St	1960's	Craig Carlson	9-Jul-20	Building	Laundry and toilet asbestos cement sheeting walls	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.43; S.44
Surat	114 William Street	Dwelling	28805	2SP188008	114 William St	1960's	Craig Carlson	9-Jul-20	Building	Bathroom, laundry and toilet asbestos cement sheeting ceramic tile flooring substrate	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.45
Surat	114 William Street	Dwelling	28805	2SP188008	114 William St	1960's	Craig Carlson	9-Jul-20	Building	Laundry asbestos cement sheeting walls and ceiling in cupboard	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.46
Surat	114 William Street	Dwelling	28805	2SP188008	114 William St	1960's	Craig Carlson	9-Jul-20	Building	Building external asbestos cement sheeting soffits, external ceilings and front and rear gable ends	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.47; S.48; S.49
Surat	114 William Street	Dwelling	28805	2SP188008	114 William St	1960's	Craig Carlson	9-Jul-20	Building	Building external asbestos cement sheeting artificial weatherboard along base of exterior walls	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.50
Surat	229 Development Road - Racecourse	Dwelling	28809	85EG141	229 Surat Development Rd	1970's	Craig Carlson	10-Jul-20	Building	Lounge, kitchen, dining masonite walls with asbestos cement sheeting ceiling	Cement based (1)	Bonded	Confirmed	Q34045S17	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.95; S.96
Surat	229 Development Road - Racecourse	Dwelling	28809	85EG141	229 Surat Development Rd	1970's	Craig Carlson	10-Jul-20	Building	Bedrooms (three) asbestos cement sheeting ceilings	Cement based (1)	Bonded	Presumed	Similar to Q34045S17	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.97; S.98; S.99
Surat	229 Development Road - Racecourse	Dwelling	28809	85EG141	229 Surat Development Rd	1970's	Craig Carlson	10-Jul-20	Building	West bedroom asbestos cement sheeting infill panel adjacent air conditioning unit	Cement based (1)	Bonded	Presumed	Similar to Q34045S17	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.100
Surat	229 Development Road - Racecourse	Dwelling	28809	85EG141	229 Surat Development Rd	1970's	Craig Carlson	10-Jul-20	Building	Laundry, toilet and bathroom asbestos cement sheeting walls and ceilings	Cement based (1)	Bonded	Presumed	Similar to Q34045S17	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.101; S.102; S.103
Surat	229 Development Road - Racecourse	Dwelling	28809	85EG141	229 Surat Development Rd	1970's	Craig Carlson	10-Jul-20	Building	Laundry and bathroom asbestos backed vinyl sheet flooring	Vinyl sheeting (2)	Friable	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed friable (2)	Low	S.104; S.105
Surat	229 Development Road - Racecourse	Dwelling	28809	85EG141	229 Surat Development Rd	1970's	Craig Carlson	10-Jul-20	Building	Centre hallway asbestos cement sheeting ceiling and walls and ceiling in linen cupboard	Cement based (1)	Bonded	Presumed	Similar to Q34045S17	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.106; S.107
Surat	229 Development Road - Racecourse	Dwelling	28809	85EG141	229 Surat Development Rd	1970's	Craig Carlson	10-Jul-20	Building	Building external asbestos cement sheeting external walls including rear stair landing lining, verandah fascia panel and gable ends	Cement based (1)	Bonded	Confirmed	Q34045S18	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.108; S.109; S.110
Surat	229 Development Road - Racecourse	Dwelling	28809	85EG141	229 Surat Development Rd	1970's	Craig Carlson	10-Jul-20	Building	Building external asbestos cement sheeting soffits including verandah ceiling and carport ceiling	Cement based (1)	Bonded	Presumed	Similar to Q34045S17	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.111; S.112
Surat	37 Charles Street	Dwelling	28817	710S2816	37 Charles St	Late 1980's	Craig Carlson	10-Jul-20	Building	Lounge, kitchen, dining, hall and bedrooms (three) plasterboard walls and ceilings with carpet and ceramic tile flooring	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Surat	37 Charles Street	Dwelling	28817	710S2816	37 Charles St	Late 1980's	Craig Carlson	10-Jul-20	Building	Toilet, bathroom and laundry non-asbestos fibre cement sheeting walls and ceilings with ceramic tile flooring	Cement based (1)	N/A	Not present (tested)	Q34054S13	No asbestos detected	N/A	N/A	N/A	S.75; S.76; S.77
Surat	37 Charles Street	Dwelling	28817	710S2816	37 Charles St	Late 1980's	Craig Carlson	10-Jul-20	Building	Building external non-asbestos fibre cement sheeting artificial weatherboard walls and soffits, gable ends and verandah and carport ceilings	Cement based (1)	N/A	Not present (tested)	Q34054S14	No asbestos detected	N/A	N/A	N/A	S.78; S.79; S.80
Surat	43 William Street	Dwelling	28955	2RP189832	11 Bertha Street	1970's	Craig Carlson	10-Jul-20	Building	Lounge, kitchen, centre hall and bedrooms masonite walls and ceilings with carpet and non-asbestos vinyl sheet flooring	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Surat	43 William Street	Dwelling	28955	2RP189832	11 Bertha Street	1970's	Craig Carlson	10-Jul-20	Building	Laundry and toilet asbestos cement sheeting walls and ceiling with non-asbestos vinyl sheet flooring	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.81; S.82

Town	Facility	Building	Asset No	Lot Plan	Address	Build Date	Auditor	Date of Inspection	ACM Location	Use of ACM / Component	ACM Material	Friable / Bonded	ACM Status	Sample #	ACM Type	ACM Condition	ACM Treatment	ACM Risk	Photo #
Surat	43 William Street	Dwelling	28955	2RP189832	11 Bertha Street	1970's	Craig Carlson	10-Jul-20	Building	Bathroom renovated post 2000 with non-asbestos fibre cement sheeting walls and ceilings with non-asbestos vinyl sheet flooring	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.83
Surat	43 William Street	Dwelling	28955	2RP189832	11 Bertha Street	1970's	Craig Carlson	10-Jul-20	Building	Building external asbestos cement sheeting walls including wall lining in back stair foyer	Cement based (1)	Bonded	Confirmed	Q34054S15	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.84; S.85
Surat	43 William Street	Dwelling	28955	2RP189832	11 Bertha Street	1970's	Craig Carlson	10-Jul-20	Building	Building external asbestos cement sheeting soffits, carport ceiling and gable end at front	Cement based (1)	Bonded	Presumed	Similar to Q34054S15	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.86; S.87; S.88
Surat	45 William Street	Dwelling	28821	707S282	45 William St	1990's	Craig Carlson	9-Jul-20	Building	Lounge, kitchen, dining, hall and bedrooms (three) plasterboard walls and ceilings with carpet and non-asbestos vinyl sheet flooring	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Surat	45 William Street	Dwelling	28821	707S282	45 William St	1990's	Craig Carlson	9-Jul-20	Building	Toilet, bathroom and laundry non-asbestos fibre cement sheeting walls and ceilings with ceramic tile flooring	Cement based (1)	N/A	Not present (not tested)	None taken	No asbestos detected	N/A	N/A	N/A	S.35; S.36; S.37
Surat	45 William Street	Dwelling	28821	707S282	45 William St	1990's	Craig Carlson	9-Jul-20	Building	Building external non-asbestos fibre cement sheeting artificial weatherboard walls and soffits, gable ends and verandah and carport ceilings	Cement based (1)	N/A	Not present (tested)	Q34054S07	No asbestos detected	N/A	N/A	N/A	S.38; S.39; S.40
Surat	72 Burrowes Street	Dwelling	28825	803S282	70-72 Burrowes St	1960's	Craig Carlson	9-Jul-20	Building	Laundry masonite main walls and ceiling with laminated asbestos cement sheeting (Tilux) lower wall along wall behind sink	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.01
Surat	72 Burrowes Street	Dwelling	28825	803S282	70-72 Burrowes St	1960's	Craig Carlson	9-Jul-20	Building	Kitchen and bathroom non-asbestos vinyl sheet flooring	Vinyl sheeting (2)	N/A	Not present (tested)	Q34054S01; Q43054S02	No asbestos detected	N/A	N/A	N/A	S.02; S.03
Surat	72 Burrowes Street	Dwelling	28825	803S282	70-72 Burrowes St	1960's	Craig Carlson	9-Jul-20	Building	Kitchen asbestos cement sheeting partition wall to dining room	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.04
Surat	72 Burrowes Street	Dwelling	28825	803S282	70-72 Burrowes St	1960's	Craig Carlson	9-Jul-20	Building	Lounge, dining, foyer, bedrooms (three), sunroom, bathroom and toilet masonite walls and ceilings	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Surat	72 Burrowes Street	Dwelling	28825	803S282	70-72 Burrowes St	1960's	Craig Carlson	9-Jul-20	Building	Building external asbestos cement sheeting soffits and infill panel above front door	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.05; S.06
Surat	91a Burrowes Street	Dwelling	28829	2RP94717	91A Burrowes St	1960's	Craig Carlson	10-Jul-20	Building	Lounge, kitchen, built-in verandah, bedrooms (three) masonite walls and ceiling with carpet and non-asbestos vinyl sheet flooring	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Surat	91a Burrowes Street	Dwelling	28829	2RP94717	91A Burrowes St	1960's	Craig Carlson	10-Jul-20	Building	Bathroom renovated post 2000 with non-asbestos fibre cement sheeting walls and ceilings with non-asbestos vinyl sheet flooring	Cement based (1)	N/A	Not present (not tested)	None taken	No asbestos detected	N/A	N/A	N/A	S.89
Surat	91a Burrowes Street	Dwelling	28829	2RP94717	91A Burrowes St	1960's	Craig Carlson	10-Jul-20	Building	Rear hallway asbestos cement sheeting ceiling and partition wall to external	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.90
Surat	91a Burrowes Street	Dwelling	28829	2RP94717	91A Burrowes St	1960's	Craig Carlson	10-Jul-20	Building	Lower level under house asbestos textile rope hot water pipe insulation	Woven textile (2)	Friable	Confirmed	Q34054S16	Chrysotile (1)	Poor (3)	Unsealed friable (3)	Medium	S.91; S.92
Surat	91a Burrowes Street	Dwelling	28829	2RP94717	91A Burrowes St	1960's	Craig Carlson	10-Jul-20	Building	Laundry asbestos cement sheeting walls and ceiling	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.93
Surat	91a Burrowes Street	Dwelling	28829	2RP94717	91A Burrowes St	1960's	Craig Carlson	10-Jul-20	Building	Building external asbestos cement sheeting soffits	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	S.94
Surat	91a Burrowes Street	Shed	77748	2RP94717	91A Burrowes St	1960's	Craig Carlson	10-Jul-20	Building	All metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Surat	Surat Effluent Reuse	Pump Shed	47912	94EG284	Ivan St	Unable to locate	Craig Carlson	20-Aug-20	Sewerage Treatment Plant	Building unable to locate	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Surat	Surat Sewerage Treatment Plant	Carport and Equipment Store	63291	98EG129	Augusta St	1970's	Craig Carlson	20-Aug-20	Sewerage Treatment Plant	Shed all metal sheeting construction; tanks all concrete construction; carport no longer present	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.301; S.302

Town	Facility	Building	Asset No	Lot Plan	Address	Build Date	Auditor	Date of Inspection	ACM Location	Use of ACM / Component	ACM Material	Friable / Bonded	ACM Status	Sample #	ACM Type	ACM Condition	ACM Treatment	ACM Risk	Photo #
Surat	Surat Water Treatment Plant	Chemical Dosing Shed	60457	77EG121	Marcus St	Post 2000	Craig Carlson	16-Aug-20	Water Treatment Plant	All metal sheeting construction with non-asbestos fibre cement sheeting internal lining in chlorine end of building	Cement based (1)	N/A	Not present (not tested)	None taken	No asbestos detected	N/A	N/A	N/A	S.138; S.139
Surat	Surat Water Treatment Plant	Chlorine Shed	41923	77EG121	Marcus St	Post 2000	Craig Carlson	16-Aug-20	Water Treatment Plant	See above; section of dosing shed	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.140
Surat	Surat Water Treatment Plant	Control Building	41875	77EG121	Marcus St	1950's	Craig Carlson	16-Aug-20	Water Treatment Plant	Pump room asbestos cement sheeting walls and ceiling; plasterboard partition to main room	Cement based (1)	Bonded	Confirmed	Q34054S19	Chrysotile (1)	Fair (2)	Sealed bonded (1)	Low	S.143
Surat	Surat Water Treatment Plant	Control Building	41875	77EG121	Marcus St	1950's	Craig Carlson	16-Aug-20	Water Treatment Plant	Main room asbestos cement sheeting walls and ceiling; plasterboard partition to pump room	Cement based (1)	Bonded	Presumed	Similar to Q34054S19	Chrysotile (1)	Fair (2)	Sealed bonded (1)	Low	S.144; S.145
Surat	Surat Water Treatment Plant	Control Building	41875	77EG121	Marcus St	1950's	Craig Carlson	16-Aug-20	Water Treatment Plant	Amenities asbestos cement sheeting walls and ceiling	Cement based (1)	Bonded	Presumed	Similar to Q34054S19	Chrysotile (1)	Fair (2)	Sealed bonded (1)	Low	S.146
Surat	Surat Water Treatment Plant	Control Building	41875	77EG121	Marcus St	1950's	Craig Carlson	16-Aug-20	Water Treatment Plant	External asbestos cement sheeting wall behind sink in outdoor covered area	Cement based (1)	Bonded	Presumed	Similar to Q34054S19	Chrysotile (1)	Fair (2)	Sealed bonded (1)	Low	S.147
Surat	Surat Water Treatment Plant	Control Building	41875	77EG121	Marcus St	1950's	Craig Carlson	16-Aug-20	Water Treatment Plant	External asbestos cement sheeting soffits and external covered area ceiling at rear	Cement based (1)	Bonded	Presumed	Similar to Q34054S19	Chrysotile (1)	Fair (2)	Sealed bonded (1)	Low	S.148; S.149
Surat	Surat Water Treatment Plant	Control Building	41875	77EG121	Marcus St	1950's	Craig Carlson	16-Aug-20	Water Treatment Plant	External asbestos cement sheeting infill panel over rear window	Cement based (1)	Bonded	Presumed	Similar to Q34054S19	Chrysotile (1)	Fair (2)	Sealed bonded (1)	Low	S.150
Surat	Surat Water Treatment Plant	Shed	62622	77EG121	Marcus St	Post 2000	Craig Carlson	16-Aug-20	Water Treatment Plant	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.141
Surat	Surat Water Treatment Plant	Mower Shed	Unknown	77EG121	Marcus St	Post 2000	Craig Carlson	16-Aug-20	Water Treatment Plant	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	S.142