

Town	Facility	Building	Asset No	Lot Plan	Address	Build Date	Auditor	Date of Inspection	ACM Location	Use of ACM / Component	ACM Material	Friable / Bonded	ACM Status	Sample #	ACM Type	ACM Condition	ACM Treatment	ACM Risk	Photo #
Mitchell	Mitchell Aerodrome	Storage Shed	56194	113DL370	312 Bollon Rd	1980's	Craig Carlson	23-Jul-20	Building	Shed construction all metal sheeting; generator may have asbestos gaskets present	Fibrous gasket (2)	Friable	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed friable (2)	Low	M.129
Mitchell	Mitchell Aerodrome	Terminal Building	56193	113DL370	312 Bollon Rd	1960's	Craig Carlson	23-Jul-20	Building	Main room masonite walls with timber fibre ceiling panels and asbestos cement sheeting infill panels under glazing to external	Cement based (1)	Bonded	Presumed	Similar to Q34185S18	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.123
Mitchell	Mitchell Aerodrome	Terminal Building	56193	113DL370	312 Bollon Rd	1960's	Craig Carlson	23-Jul-20	Building	Male and female amenities masonite walls with timber fibre ceiling panels	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Mitchell	Mitchell Aerodrome	Terminal Building	56193	113DL370	312 Bollon Rd	1960's	Craig Carlson	23-Jul-20	Building	Building external asbestos cement sheeting infill panels under glazing and upper front wall above glazing including above side louvres	Cement based (1)	Bonded	Presumed	Similar to Q34185S18	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.124
Mitchell	Mitchell Aerodrome	Terminal Building	56193	113DL370	312 Bollon Rd	1960's	Craig Carlson	23-Jul-20	Building	Building external asbestos cement sheeting soffits including front awning ceiling	Cement based (1)	Bonded	Confirmed	Q34185S18	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.125; M.126
Mitchell	Mitchell Aerodrome	Terminal Building	56193	113DL370	312 Bollon Rd	1960's	Craig Carlson	23-Jul-20	Building	External asbestos cement vent pipes for amenities (two)	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Fair (2)	Unsealed bonded (2)	Low	M.126; M.127
Mitchell	Booringa Heritage Museum	Main Building	Unknown	1SP265643	6 Cambridge St	1950's	Craig Carlson	28-Jul-20	Building	Main building all metal sheeting roof and walls	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Mitchell	Booringa Heritage Museum	Main Building	Unknown	1SP265643	6 Cambridge St	1950's	Craig Carlson	28-Jul-20	Building	Internal areas including kitchen, toilet and office non-asbestos fibre cement sheeting walls and ceilings; all installed <10 years ago (based on information provided)	Cement based (1)	N/A	Not present (not tested)	None taken	No asbestos detected	N/A	N/A	N/A	M.234; M.235; M.236; M.237
Mitchell	Booringa Heritage Museum	Carport - Old	55778	1SP265643	6 Cambridge St	1950's	Craig Carlson	28-Jul-20	Building	All timber and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.238
Mitchell	Booringa Heritage Museum	Machinery 5-bay Shed	70139	1SP265643	6 Cambridge St	1950's	Craig Carlson	28-Jul-20	Building	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.239
Mitchell	Booringa Heritage Museum	Storage Shed 4-bay	55779	1SP265643	6 Cambridge St	1950's	Craig Carlson	28-Jul-20	Building	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.240
Mitchell	Booringa Heritage Museum	Toilet Block	55781	1SP265643	6 Cambridge St	1950's	Craig Carlson	28-Jul-20	Building	All timber and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.241
Mitchell	Dance Studio	Building	55726	1RP96250	48-52 Cambridge St	1940's	Craig Carlson	29-Jul-20	Building	Dance studio room non-asbestos vinyl tile flooring on non-asbestos fibre cement sheeting substrate	Vinyl tiles (1)	N/A	Not present (tested)	Q34185S35	No asbestos detected	N/A	N/A	N/A	M.323; M.325
Mitchell	Dance Studio	Building	55726	1RP96250	48-52 Cambridge St	1940's	Craig Carlson	29-Jul-20	Building	Dance studio room and amenities concrete rendered brick and non-asbestos fibre cement sheeting walls	Cement based (1)	N/A	Not present (tested)	Q34185S37	No asbestos detected	N/A	N/A	N/A	M.322; M.324
Mitchell	Dance Studio	Building	55726	1RP96250	48-52 Cambridge St	1940's	Craig Carlson	29-Jul-20	Building	Dance studio room asbestos cement sheeting ceiling	Cement based (1)	Bonded	Presumed	Similar to Q34185S38	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.326
Mitchell	Dance Studio	Building	55726	1RP96250	48-52 Cambridge St	1940's	Craig Carlson	29-Jul-20	Building	Centre tenancy asbestos cement sheeting ceiling; concrete rendered brick walls and carpet flooring	Cement based (1)	Bonded	Presumed	Similar to Q34185S38	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.327
Mitchell	Dance Studio	Building	55726	1RP96250	48-52 Cambridge St	1940's	Craig Carlson	29-Jul-20	Building	Landcare tenancy vinyl asbestos tile flooring; concrete rendered brick walls and timber ceiling	Vinyl tiles (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.328
Mitchell	Dance Studio	Building	55726	1RP96250	48-52 Cambridge St	1940's	Craig Carlson	29-Jul-20	Building	Landcare tenancy asbestos mastic backing to vinyl asbestos tile flooring (blackjack)	Fibrous felt (2)	Friable	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed friable (2)	Low	M.328
Mitchell	Dance Studio	Building	55726	1RP96250	48-52 Cambridge St	1940's	Craig Carlson	29-Jul-20	Building	Building external asbestos cement sheeting front awning ceiling and façade panel	Cement based (1)	Bonded	Confirmed	Q34185S38	Chrysotile (1)	Fair (2)	Sealed bonded (1)	Low	M.329; M.330; M.331
Mitchell	Dance Studio	Building	55726	1RP96250	48-52 Cambridge St	1940's	Craig Carlson	29-Jul-20	Building	Building external asbestos cement sheeting upper wall above block wall on east side	Cement based (1)	Bonded	Presumed	Similar to Q34185S38	Chrysotile (1)	Good (1)	Unsealed bonded (1)	Low	M.332
Mitchell	Dance Studio	Building	55726	1RP96250	48-52 Cambridge St	1940's	Craig Carlson	29-Jul-20	Building	Rear storage building of Dance Studio asbestos cement sheeting external walls and roof; masonite internal walls and ceiling	Cement based (1)	Bonded	Presumed	Similar to Q34185S39	Chrysotile; amosite; crocidolite (3)	Poor (3)	Unsealed bonded (1)	Medium	M.333; M.334

Town	Facility	Building	Asset No	Lot Plan	Address	Build Date	Auditor	Date of Inspection	ACM Location	Use of ACM / Component	ACM Material	Friable / Bonded	ACM Status	Sample #	ACM Type	ACM Condition	ACM Treatment	ACM Risk	Photo #
Mitchell	Dance Studio	Building	55726	1RP96250	48-52 Cambridge St	1940's	Craig Carlson	29-Jul-20	Building	Rear storage building of Dance Studio rear lean-to asbestos cement sheeting roof	Cement based (1)	Bonded	Confirmed	Q34185S39	Chrysotile; amosite; crocidolite (3)	Poor (3)	Unsealed bonded (1)	Medium	M.335
Mitchell	Dance Studio	Building	55726	1RP96250	48-52 Cambridge St	1940's	Craig Carlson	29-Jul-20	Building	Rear storage building of centre tenancy asbestos cement sheeting external walls; no internal access gained only looking through window	Cement based (1)	Bonded	Presumed	Similar to Q34185S39	Chrysotile; amosite; crocidolite (3)	Fair (2)	Unsealed bonded (1)	Medium	M.336; M.337
Mitchell	Great Artesian Spa	Ablution and Toilet Block	75219	1SP265643	6 Cambridge St	2016	Craig Carlson	28-Jul-20	Building	New construction no asbestos detected	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.230
Mitchell	Great Artesian Spa	Chemical Shed	55752	1SP265643	6 Cambridge St	2016	Craig Carlson	28-Jul-20	Building	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.231
Mitchell	Great Artesian Spa	Decking and Ramp	55745	1SP265643	6 Cambridge St	2016	Craig Carlson	28-Jul-20	Building	Deck all timber construction with non-asbestos fibre cement sheeting ceiling on awning	Cement based (1)	N/A	Not present (not tested)	None taken	No asbestos detected	N/A	N/A	N/A	M.232
Mitchell	Great Artesian Spa	Shelters x6	55746	1SP265643	6 Cambridge St	2016	Craig Carlson	28-Jul-20	Building	All steel, timber and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.233
Mitchell	Great Artesian Spa	Spa Building	55744	1SP265643	6 Cambridge St	2016	Craig Carlson	28-Jul-20	Building	Reported as part of the Mitchell Shire Hall	N/A	N/A	N/A	None taken		N/A	N/A	N/A	No image
Mitchell	Maranoa Retirement Village	Accommodation and Offices - A	55758	1DL143	Bollon Rd	1950's	Craig Carlson	25-Jul-20	Building	Rooms 1 - 16 including ensuites, entry foyer and north and south verandahs all plasterboard and timber construction with non-asbestos vinyl sheet flooring	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Mitchell	Maranoa Retirement Village	Accommodation and Offices - A	55758	1DL143	Bollon Rd	1950's	Craig Carlson	25-Jul-20	Building	Front entry foyer area low density asbestos fibreboard ceiling	Low density board (2)	Friable	Presumed	Similar to Q34185S19	Chrysotile; amosite (2)	Good (1)	Sealed friable (2)	Medium	M.130
Mitchell	Maranoa Retirement Village	Accommodation and Offices - A	55758	1DL143	Bollon Rd	1950's	Craig Carlson	25-Jul-20	Building	Bathroom off foyer asbestos cement sheeting (Tilux) walls	Cement based (1)	Bonded	Presumed	Similar to Q34185S21	Chrysotile; amosite (2)	Good (1)	Sealed bonded (1)	Low	M.131
Mitchell	Maranoa Retirement Village	Accommodation and Offices - A	55758	1DL143	Bollon Rd	1950's	Craig Carlson	25-Jul-20	Building	Bathroom off foyer asbestos cement sheeting lining in shower recess	Cement based (1)	Bonded	Presumed	Similar to Q34185S21	Chrysotile; amosite (2)	Poor (3)	Sealed bonded (1)	Medium	M.132
Mitchell	Maranoa Retirement Village	Accommodation and Offices - A	55758	1DL143	Bollon Rd	1950's	Craig Carlson	25-Jul-20	Building	Bathroom off foyer low density asbestos fibreboard ceiling and skylight boxing	Low density board (2)	Friable	Confirmed	Q34185S19	Chrysotile; amosite (2)	Good (1)	Sealed friable (2)	Medium	M.133; M.134
Mitchell	Maranoa Retirement Village	Accommodation and Offices - A	55758	1DL143	Bollon Rd	1950's	Craig Carlson	25-Jul-20	Building	Lounge room north low density asbestos fibreboard wall at entry, to cupboard and to sink recess in south lounge, and wall in sink recess; plasterboard remaining walls and ceiling	Low density board (2)	Friable	Presumed	Similar to Q34185S19	Chrysotile; amosite (2)	Good (1)	Sealed friable (2)	Medium	M.135; M.136
Mitchell	Maranoa Retirement Village	Accommodation and Offices - A	55758	1DL143	Bollon Rd	1950's	Craig Carlson	25-Jul-20	Building	Services cupboard low density asbestos fibreboard ceiling sheeting	Low density board (2)	Friable	Presumed	Similar to Q34185S19	Chrysotile; amosite (2)	Good (1)	Sealed friable (2)	Medium	M.137
Mitchell	Maranoa Retirement Village	Accommodation and Offices - A	55758	1DL143	Bollon Rd	1950's	Craig Carlson	25-Jul-20	Building	Lounge room south low density asbestos fibreboard walls in west half of room, in sink recess, wall around door and partition to laundry; plasterboard remaining walls and ceiling	Low density board (2)	Friable	Presumed	Similar to Q34185S19	Chrysotile; amosite (2)	Good (1)	Sealed friable (2)	Medium	M.138; M.139
Mitchell	Maranoa Retirement Village	Accommodation and Offices - A	55758	1DL143	Bollon Rd	1950's	Craig Carlson	25-Jul-20	Building	Laundry asbestos cement sheeting (Tilux) walls	Cement based (1)	Bonded	Presumed	Similar to Q34185S21	Chrysotile; amosite (2)	Good (1)	Sealed bonded (1)	Low	M.140
Mitchell	Maranoa Retirement Village	Accommodation and Offices - A	55758	1DL143	Bollon Rd	1950's	Craig Carlson	25-Jul-20	Building	Laundry low density asbestos fibreboard ceiling	Low density board (2)	Friable	Presumed	Similar to Q34185S19	Chrysotile; amosite (2)	Good (1)	Sealed friable (2)	Medium	M.141
Mitchell	Maranoa Retirement Village	Accommodation and Offices - A	55758	1DL143	Bollon Rd	1950's	Craig Carlson	25-Jul-20	Building	Amenities off south lounge room low density asbestos fibreboard ceiling	Low density board (2)	Friable	Presumed	Similar to Q34185S19	Chrysotile; amosite (2)	Good (1)	Sealed friable (2)	Medium	M.142
Mitchell	Maranoa Retirement Village	Accommodation and Offices - A	55758	1DL143	Bollon Rd	1950's	Craig Carlson	25-Jul-20	Building	Amenities off south lounge room asbestos cement sheeting (Tilux) walls	Cement based (1)	Bonded	Presumed	Similar to Q34185S21	Chrysotile; amosite (2)	Good (1)	Sealed bonded (1)	Low	M.143
Mitchell	Maranoa Retirement Village	Accommodation and Offices - A	55758	1DL143	Bollon Rd	1950's	Craig Carlson	25-Jul-20	Building	Building external asbestos cement sheeting infill panel above main north entry and roof infill panel in foyer area	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Low	M.144; M.145
Mitchell	Maranoa Retirement Village	Accommodation and Offices - A	55758	1DL143	Bollon Rd	1950's	Craig Carlson	25-Jul-20	Building	Building external asbestos cement sheeting soffits on western end, east wing lounge area and awning and covered walkway ceiling on east end	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Low	M.146; M.147; M.148

Town	Facility	Building	Asset No	Lot Plan	Address	Build Date	Auditor	Date of Inspection	ACM Location	Use of ACM / Component	ACM Material	Friable / Bonded	ACM Status	Sample #	ACM Type	ACM Condition	ACM Treatment	ACM Risk	Photo #
Mitchell	Maranoa Retirement Village	Accommodation and Offices - A	55758	1DL143	Bollon Rd	1950's	Craig Carlson	25-Jul-20	Building	Building external asbestos cement vent pipe on west end of building	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Low	M.149
Mitchell	Maranoa Retirement Village	Accommodation and Offices - A	55758	1DL143	Bollon Rd	1950's	Craig Carlson	25-Jul-20	Building	Link to office and kitchen building asbestos cement sheeting walls and ceiling	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Low	M.150
Mitchell	Maranoa Retirement Village	Accommodation and Offices - B	55759	1DL143	Bollon Rd	1950's	Craig Carlson	25-Jul-20	Building	Accommodation rooms and common areas plasterboard walls and ceilings with non-asbestos vinyl sheet flooring	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Mitchell	Maranoa Retirement Village	Accommodation and Offices - B	55759	1DL143	Bollon Rd	1950's	Craig Carlson	25-Jul-20	Building	Bathroom for room 19 asbestos cement sheeting walls and ceiling	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Low	M.154; M.155
Mitchell	Maranoa Retirement Village	Accommodation and Offices - B	55759	1DL143	Bollon Rd	1950's	Craig Carlson	25-Jul-20	Building	Building external asbestos cement sheeting infill panel on south wall in storeroom area and door infill panel at rear	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Low	M.156; M.157
Mitchell	Maranoa Retirement Village	Carport	55765	1DL143	Bollon Rd	1980's	Craig Carlson	25-Jul-20	Building	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.160
Mitchell	Maranoa Retirement Village	Garage and Carport	55762	1DL143	Bollon Rd	1950's	Craig Carlson	25-Jul-20	Building	All timber and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.159
Mitchell	Maranoa Retirement Village	Isolation Building	55761	1DL143	Bollon Rd	1930's	Craig Carlson	25-Jul-20	Building	All timber and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.158
Mitchell	Maranoa Retirement Village	Laundry	55760	1DL143	Bollon Rd	2001	Craig Carlson	25-Jul-20	Building	All non-asbestos fibre cement sheeting internal walls and ceilings and external walls and soffits	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.162; M.163
Mitchell	Maranoa Retirement Village	Maintenance Building	55764	1DL143	Bollon Rd	1960's	Craig Carlson	25-Jul-20	Building	Main room asbestos cement sheeting end walls	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Low	M.164
Mitchell	Maranoa Retirement Village	Maintenance Building	55764	1DL143	Bollon Rd	1960's	Craig Carlson	25-Jul-20	Building	Main room, centre foyer and bedroom low density asbestos fibreboard ceiling sheeting	Low density board (2)	Friable	Presumed	Similar to Q34185S19	Chrysotile; amosite (2)	Good (1)	Sealed friable (2)	Medium	M.165; M.166; M.167
Mitchell	Maranoa Retirement Village	Maintenance Building	55764	1DL143	Bollon Rd	1960's	Craig Carlson	25-Jul-20	Building	Bathroom asbestos cement sheeting walls with this suspected behind laminate walls in shower recess	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Low	M.168
Mitchell	Maranoa Retirement Village	Maintenance Building	55764	1DL143	Bollon Rd	1960's	Craig Carlson	25-Jul-20	Building	Building external amenities asbestos cement sheeting (Tilux) walls	Cement based (1)	Bonded	Confirmed	Q34185S21	Chrysotile; amosite (2)	Good (1)	Sealed bonded (1)	Low	M.169
Mitchell	Maranoa Retirement Village	Maintenance Building	55764	1DL143	Bollon Rd	1960's	Craig Carlson	25-Jul-20	Building	Building external low density asbestos fibreboard wall lining around door to storeroom	Low density board (2)	Friable	Presumed	Similar to Q34185S19	Chrysotile; amosite (2)	Good (1)	Sealed friable (2)	Medium	M.170
Mitchell	Maranoa Retirement Village	Offices and Kitchen - C	62603	1DL143	Bollon Rd	1970's	Craig Carlson	25-Jul-20	Building	Office and kitchen building main kitchen asbestos cement sheeting walls in cooking recess under ventilation extraction unit	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Low	M.151
Mitchell	Maranoa Retirement Village	Offices and Kitchen - C	62603	1DL143	Bollon Rd	1970's	Craig Carlson	25-Jul-20	Building	Office and kitchen building external asbestos cement sheeting soffits	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Low	M.152
Mitchell	Maranoa Retirement Village	Offices and Kitchen - C	62603	1DL143	Bollon Rd	1970's	Craig Carlson	25-Jul-20	Building	Office and kitchen building link to main building asbestos cement sheeting external cladding	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Low	M.153
Mitchell	Maranoa Retirement Village	Store	55763	1DL143	Bollon Rd	Post 2000	Craig Carlson	25-Jul-20	Building	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.161
Mitchell	Mitchell Cemetery	Storage Shed - Large	26893	118C891	42 Alice St	1970's	Craig Carlson	28-Jul-20	Building	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.242
Mitchell	Mitchell Cemetery	Toilet Block	55733	118C891	42 Alice St	Post 2000	Craig Carlson	28-Jul-20	Public Amenities	All timber, steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.243
Mitchell	Mitchell Cemetery	Tool Shed	26897	118C891	42 Alice St	1950's	Craig Carlson	28-Jul-20	Building	All timber and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.244
Mitchell	Mitchell Library	Library Building	55770	2SP206896	33 Cambridge St	1930's (refurb post 2000)	Craig Carlson	21-Jul-20	Building	Upper level Bio Box area non-asbestos fibre cement sheeting ceiling	Cement based (1)	N/A	Not present (tested)	Q34185S06	No asbestos detected	N/A	N/A	N/A	M.42
Mitchell	Mitchell Library	Library Building	55770	2SP206896	33 Cambridge St	1930's (refurb post 2000)	Craig Carlson	21-Jul-20	Building	Upper level Bio Box area asbestos textile cable insulation on rectifier cables	Woven textile (2)	Friable	Confirmed	Q34185S07	Chrysotile (1)	Poor (3)	Unsealed friable (3)	Medium	M.43

Town	Facility	Building	Asset No	Lot Plan	Address	Build Date	Auditor	Date of Inspection	ACM Location	Use of ACM / Component	ACM Material	Friable / Bonded	ACM Status	Sample #	ACM Type	ACM Condition	ACM Treatment	ACM Risk	Photo #
Mitchell	Mitchell Library	Library Building	55770	2SP206896	33 Cambridge St	1930's (refurb post 2000)	Craig Carlson	21-Jul-20	Building	Main hall asbestos cement sheeting walls to external around northern (rear stage area) exit doors including end walls on side of stage area; brick and rendered brick remaining walls and plasterboard ceiling tiles	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.44; M.45
Mitchell	Mitchell Library	Library Building	55770	2SP206896	33 Cambridge St	1930's (refurb post 2000)	Craig Carlson	21-Jul-20	Building	Main hall stage area asbestos cement sheeting walls and ceiling including lower wall under stage in main hall area	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.46; M.47
Mitchell	Mitchell Library	Library Building	55770	2SP206896	33 Cambridge St	1930's (refurb post 2000)	Craig Carlson	21-Jul-20	Building	Back storeroom asbestos cement sheeting walls and ceiling	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.48
Mitchell	Mitchell Library	Library Building	55770	2SP206896	33 Cambridge St	1930's (refurb post 2000)	Craig Carlson	21-Jul-20	Display Item	Building external rear stored vessel asbestos gasket material on flanges	Fibrous gasket (2)	Friable	Presumed	None taken	Chrysotile (1)	Fair (2)	Unsealed friable (3)	Medium	M.49; M.50
Mitchell	Mitchell Library	Library Building	55770	2SP206896	33 Cambridge St	1930's (refurb post 2000)	Craig Carlson	21-Jul-20	Building	Main building external brick walls with metal sheeting roof; no roof access	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Mitchell	Mitchell Shire Hall	Building	55750	1SP265643	6 Cambridge St	1930's	Craig Carlson	28-Jul-20	Building	Mezzanine Bio-Box area store plasterboard walls and ceiling over asbestos cement sheeting (as visible in access stair/void)	Cement based (1)	Bonded	Confirmed	Q34185S22	Chrysotile; amosite (2)	Fair (2)	Unsealed bonded (2)	Medium	M.189
Mitchell	Mitchell Shire Hall	Building	55750	1SP265643	6 Cambridge St	1930's	Craig Carlson	28-Jul-20	Building	Mezzanine air conditioning plantroom plasterboard walls and ceiling suspected of being over asbestos cement sheeting (as present in storeroom)	Cement based (1)	Bonded	Presumed	Similar to Q34185S22	Chrysotile; amosite (2)	Fair (2)	Unsealed bonded (2)	Medium	No image
Mitchell	Mitchell Shire Hall	Building	55750	1SP265643	6 Cambridge St	1930's	Craig Carlson	28-Jul-20	Building	Mezzanine Bio-Box area access stair asbestos cement sheeting ceiling	Cement based (1)	Bonded	Presumed	Similar to Q34185S22	Chrysotile; amosite (2)	Fair (2)	Unsealed bonded (2)	Medium	M.190
Mitchell	Mitchell Shire Hall	Building	55750	1SP265643	6 Cambridge St	1930's	Craig Carlson	28-Jul-20	Building	Main entry foyer asbestos cement sheeting ceiling	Cement based (1)	Bonded	Presumed	Similar to Q34185S22	Chrysotile; amosite (2)	Good (1)	Sealed bonded (1)	Low	M.191
Mitchell	Mitchell Shire Hall	Building	55750	1SP265643	6 Cambridge St	1930's	Craig Carlson	28-Jul-20	Building	Foyer to Spa area non-asbestos fibre cement sheeting walls and ceiling	Cement based (1)	N/A	Not present (not tested)	None taken	No asbestos detected	N/A	N/A	N/A	M.224
Mitchell	Mitchell Shire Hall	Building	55750	1SP265643	6 Cambridge St	1930's	Craig Carlson	28-Jul-20	Building	Front office strong room door may be internally insulated with asbestos insulation	Loose fill (3)	Friable	Presumed	None taken	Chrysotile (1)	Fair (2)	Sealed friable (2)	Medium	M.192
Mitchell	Mitchell Shire Hall	Building	55750	1SP265643	6 Cambridge St	1930's	Craig Carlson	28-Jul-20	Building	Front office asbestos cement sheeting ceiling above counter area; main ceiling plasterboard ceiling tiles with no access above due to height restrictions; may be asbestos cement sheeting above	Cement based (1)	Bonded	Presumed	Similar to Q34185S22	Chrysotile; amosite (2)	Good (1)	Sealed bonded (1)	Low	M.193
Mitchell	Mitchell Shire Hall	Building	55750	1SP265643	6 Cambridge St	1930's	Craig Carlson	28-Jul-20	Building	Café area timber lower walls with asbestos cement sheeting upper walls and ceiling	Cement based (1)	Bonded	Cement based	Similar to Q34185S22	Chrysotile; amosite (2)	Good (1)	Sealed bonded (1)	Low	M.194; M.195; M.196
Mitchell	Mitchell Shire Hall	Building	55750	1SP265643	6 Cambridge St	1930's	Craig Carlson	28-Jul-20	Building	Café area kitchen including freezer room timber lower walls with asbestos cement sheeting upper walls and ceiling	Cement based (1)	Bonded	Presumed	Similar to Q34185S22	Chrysotile; amosite (2)	Good (1)	Sealed bonded (1)	Low	M.197; M.198
Mitchell	Mitchell Shire Hall	Building	55750	1SP265643	6 Cambridge St	1930's	Craig Carlson	28-Jul-20	Building	Gym area concrete block walls with non-asbestos fibre cement sheeting ceiling and infill panel on partition wall to kitchen	Cement based (1)	N/A	Not present (not tested)	Similar to Q34185S24	No asbestos detected	N/A	N/A	N/A	M.199; M.200
Mitchell	Mitchell Shire Hall	Building	55750	1SP265643	6 Cambridge St	1930's	Craig Carlson	28-Jul-20	Building	Side office area asbestos cement sheeting ceiling	Cement based (1)	Bonded	Presumed	Similar to Q34185S22	Chrysotile; amosite (2)	Good (1)	Sealed bonded (1)	Low	M.201
Mitchell	Mitchell Shire Hall	Building	55750	1SP265643	6 Cambridge St	1930's	Craig Carlson	28-Jul-20	Building	Laundry timber and masonite walls with asbestos cement sheeting ceiling	Cement based (1)	Bonded	Presumed	Similar to Q34185S22	Chrysotile; amosite (2)	Good (1)	Sealed bonded (1)	Low	M.202; M.203
Mitchell	Mitchell Shire Hall	Building	55750	1SP265643	6 Cambridge St	1930's	Craig Carlson	28-Jul-20	Building	Laundry toilet asbestos cement sheeting walls and ceiling	Cement based (1)	Bonded	Presumed	Similar to Q34185S22	Chrysotile; amosite (2)	Good (1)	Sealed bonded (1)	Low	M.204
Mitchell	Mitchell Shire Hall	Building	55750	1SP265643	6 Cambridge St	1930's	Craig Carlson	28-Jul-20	Building	East open area ceiling perforated metal tiles suspected over asbestos cement sheeting ceiling	Cement based (1)	Bonded	Presumed	Similar to Q34185S22	Chrysotile; amosite (2)	Good (1)	Sealed bonded (1)	Low	M.205
Mitchell	Mitchell Shire Hall	Building	55750	1SP265643	6 Cambridge St	1930's	Craig Carlson	28-Jul-20	Building	Main kitchen masonite walls and ceiling with non-asbestos vinyl sheet flooring; asbestos cement sheeting partition to main hall	Cement based (1)	Bonded	Presumed	Similar to Q34185S22	Chrysotile; amosite (2)	Good (1)	Sealed bonded (1)	Low	M.206

Town	Facility	Building	Asset No	Lot Plan	Address	Build Date	Auditor	Date of Inspection	ACM Location	Use of ACM / Component	ACM Material	Friable / Bonded	ACM Status	Sample #	ACM Type	ACM Condition	ACM Treatment	ACM Risk	Photo #
Mitchell	Mitchell Shire Hall	Building	55750	1SP265643	6 Cambridge St	1930's	Craig Carlson	28-Jul-20	Building	Main hall timber lower walls with asbestos cement sheeting upper walls on ends and sides of room including above stage; perforated metal ceiling tiles suspected of being over asbestos cement sheeting ceiling	Cement based (1)	Bonded	Presumed	Similar to Q34185S22	Chrysotile; amosite (2)	Good (1)	Sealed bonded (1)	Low	M.207; M.208; M.209
Mitchell	Mitchell Shire Hall	Building	55750	1SP265643	6 Cambridge St	1930's	Craig Carlson	28-Jul-20	Building	Stage area timber walls with asbestos cement sheeting ceiling and upper walls to rear external	Cement based (1)	Bonded	Presumed	Similar to Q34185S22	Chrysotile; amosite (2)	Good (1)	Sealed bonded (1)	Low	M.210; M.211; M.212
Mitchell	Mitchell Shire Hall	Building	55750	1SP265643	6 Cambridge St	1930's	Craig Carlson	28-Jul-20	Building	Stage area west void asbestos cement sheeting ceiling in main room and walls and ceiling in toilet	Cement based (1)	Bonded	Presumed	Similar to Q34185S22	Chrysotile; amosite (2)	Good (1)	Sealed bonded (1)	Low	M.213; M.214
Mitchell	Mitchell Shire Hall	Building	55750	1SP265643	6 Cambridge St	1930's	Craig Carlson	28-Jul-20	Building	West open area masonite, timber and non-asbestos fibre cement sheeting walls/infill panels	Cement based (1)	N/A	Not present (tested)	Q34185S23	No asbestos detected	N/A	N/A	N/A	M.215; M.216
Mitchell	Mitchell Shire Hall	Building	55750	1SP265643	6 Cambridge St	1930's	Craig Carlson	28-Jul-20	Building	West open area perforated metal ceiling tiles suspected over asbestos cement sheeting ceiling	Cement based (1)	Bonded	Presumed	Similar to Q34185S22	Chrysotile; amosite (2)	Good (1)	Sealed bonded (1)	Low	M.217
Mitchell	Mitchell Shire Hall	Building	55750	1SP265643	6 Cambridge St	1930's	Craig Carlson	28-Jul-20	Building	Male and female amenities including corridor and disabled amenities concrete block walls with non-asbestos fibre cement sheeting ceilings	Cement based (1)	N/A	Not present (tested)	Q34185S24	No asbestos detected	N/A	N/A	N/A	M.218; M.219; M.220
Mitchell	Mitchell Shire Hall	Building	55750	1SP265643	6 Cambridge St	1930's	Craig Carlson	28-Jul-20	Building	Floor coverings throughout non-asbestos vinyl tile and timber flooring	Vinyl tiles (1)	N/A	Not present (not tested)	None taken	No asbestos detected	N/A	N/A	N/A	M.221; M.222;
Mitchell	Mitchell Shire Hall	Building	55750	1SP265643	6 Cambridge St	1930's	Craig Carlson	28-Jul-20	Building	Building external asbestos cement sheeting gable end on south end and on main front	Cement based (1)	Bonded	Presumed	Similar to Q34185S22	Chrysotile; amosite (2)	Good (1)	Sealed bonded (1)	Low	M.225; M.226
Mitchell	Mitchell Shire Hall	Building	55750	1SP265643	6 Cambridge St	1930's	Craig Carlson	28-Jul-20	Building	Building external non-asbestos fibre cement sheeting soffits on amenities/gym extension	Cement based (1)	N/A	Not present (not tested)	Similar to Q34185S24	No asbestos detected	N/A	N/A	N/A	M.227
Mitchell	Mitchell Shire Hall	Building	55750	1SP265643	6 Cambridge St	1930's	Craig Carlson	28-Jul-20	Building	Building external asbestos cement sheeting walls and ceilings in front entry foyer area	Cement based (1)	Bonded	Presumed	Similar to Q34185S22	Chrysotile; amosite (2)	Good (1)	Sealed bonded (1)	Low	M.228
Mitchell	The Men's Shed	Men's Shed	62601	1RP83935	90-92 Mary St	Post 2000	Craig Carlson	29-Jul-20	Building	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.338
Mitchell	The Men's Shed	Old SES Shed	60408	1RP83935	90-92 Mary St	1970's	Craig Carlson	29-Jul-20	Building	Main shed all metal sheeting roof and walls with non-asbestos fibre cement sheeting lining in south east corner	Cement based (1)	N/A	Not present (not tested)	None taken	No asbestos detected	N/A	N/A	N/A	M.339
Mitchell	The Men's Shed	Old SES Shed	60408	1RP83935	90-92 Mary St	1970's	Craig Carlson	29-Jul-20	Building	Main shed asbestos cement sheeting partition to amenities	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.340
Mitchell	The Men's Shed	Old SES Shed	60408	1RP83935	90-92 Mary St	1970's	Craig Carlson	29-Jul-20	Building	Amenities asbestos cement sheeting walls and ceiling throughout including tilux lining in shower recess	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.341; M.342
Mitchell	The Men's Shed	Old SES Shed	60408	1RP83935	90-92 Mary St	1970's	Craig Carlson	29-Jul-20	Building	Amenities asbestos cement sheeting tilux bench top lining	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.343
Mitchell	Mitchell Administration Centre	Archive Store (Old Library)	55900	35M1513	100 Cambridge St	1967	Craig Carlson	30-Jul-20	Building	Main room concrete rendered brick walls with plasterboard ceiling and carpet on vinyl asbestos tile flooring	Vinyl tiles (1)	Bonded	Confirmed	Q34185S42	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.372
Mitchell	Mitchell Administration Centre	Archive Store (Old Library)	55900	35M1513	100 Cambridge St	1967	Craig Carlson	30-Jul-20	Building	Main room asbestos cement sheeting infill panels under glazing on western side	Cement based (1)	Bonded	Presumed	Similar to Q34185S43	Chrysotile; amosite; crocidolite (3)	Good (1)	Sealed bonded (1)	Low	M.373
Mitchell	Mitchell Administration Centre	Archive Store (Old Library)	55900	35M1513	100 Cambridge St	1967	Craig Carlson	30-Jul-20	Building	Back room vinyl asbestos tile flooring	Vinyl tiles (1)	Bonded	Confirmed	Q34185S42	Chrysotile (1)	Poor (3)	Sealed bonded (1)	Low	M.374; M.375
Mitchell	Mitchell Administration Centre	Archive Store (Old Library)	55900	35M1513	100 Cambridge St	1967	Craig Carlson	30-Jul-20	Building	Back room and back amenities asbestos cement sheeting infill panels under glazing to external	Cement based (1)	Bonded	Presumed	Similar to Q34185S43	Chrysotile; amosite; crocidolite (3)	Good (1)	Sealed bonded (1)	Low	M.376; M.377
Mitchell	Mitchell Administration Centre	Archive Store (Old Library)	55900	35M1513	100 Cambridge St	1967	Craig Carlson	30-Jul-20	Building	Building external asbestos cement sheeting infill panels under glazing	Cement based (1)	Bonded	Presumed	Similar to Q34185S43	Chrysotile; amosite; crocidolite (3)	Good (1)	Sealed bonded (1)	Low	M.378; M.379
Mitchell	Mitchell Administration Centre	Archive Store (Old Library)	55900	35M1513	100 Cambridge St	1967	Craig Carlson	30-Jul-20	Building	Building external asbestos cement sheeting soffits including front awning ceiling	Cement based (1)	Bonded	Confirmed	Q34185S43	Chrysotile; amosite; crocidolite (3)	Good (1)	Sealed bonded (1)	Low	M.380; M.381; M.382
Mitchell	Mitchell Administration Centre	Old Courthouse	Unknown	35M1513	100 Cambridge St	1930's	Craig Carlson	30-Jul-20	Building	Internal construction all timber walls, floor and ceiling; external timber walls and metal sheeting roof	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image

Town	Facility	Building	Asset No	Lot Plan	Address	Build Date	Auditor	Date of Inspection	ACM Location	Use of ACM / Component	ACM Material	Friable / Bonded	ACM Status	Sample #	ACM Type	ACM Condition	ACM Treatment	ACM Risk	Photo #
Mitchell	Mitchell Administration Centre	Old Courthouse	Unknown	35M1513	100 Cambridge St	1930's	Craig Carlson	30-Jul-20	Building	External south end asbestos cement sheeting gable end lining; soffit sheeting and small upper walls to soffit lining	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.383; M.384
Mitchell	Mitchell Administration Centre	Council Offices	55899	35M1513	100 Cambridge St	1967	Craig Carlson	30-Jul-20	Building	Front meeting room area fibrous plaster and concrete walls with fibrous plaster ceiling and non-asbestos fibre cement sheeting partition to back office	Cement based (1)	N/A	Not present (not tested)	None taken	No asbestos detected	N/A	N/A	N/A	M.385
Mitchell	Mitchell Administration Centre	Council Offices	55899	35M1513	100 Cambridge St	1967	Craig Carlson	30-Jul-20	Building	Internal areas throughout asbestos cement sheeting infill panels under glazing to building external, under glazing including front meeting room, office areas, server room and lunch room	Cement based (1)	Bonded	Presumed	Similar to Q34185S43	Chrysotile; amosite; crocidolite (3)	Good (1)	Sealed bonded (1)	Low	M.386; M.387; M.388; M.389; M.390; M.391; M.392
Mitchell	Mitchell Administration Centre	Council Offices	55899	35M1513	100 Cambridge St	1967	Craig Carlson	30-Jul-20	Building	North east corner office perforated low density asbestos fibre board ceiling panels	Low density board (2)	Friable	Presumed	Similar to Q34185S44	Chrysotile; amosite (2)	Fair (2)	Sealed friable (2)	Medium	M.393; M.394
Mitchell	Mitchell Administration Centre	Council Offices	55899	35M1513	100 Cambridge St	1967	Craig Carlson	30-Jul-20	Building	Main foyer asbestos cement sheeting partition wall to back office areas	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.395; M.396
Mitchell	Mitchell Administration Centre	Council Offices	55899	35M1513	100 Cambridge St	1967	Craig Carlson	30-Jul-20	Building	East offices perforated low density asbestos fibreboard ceiling panels	Low density board (2)	Friable	Presumed	Similar to Q34185S44	Chrysotile; amosite (2)	Fair (2)	Sealed friable (2)	Medium	M.397; M.398
Mitchell	Mitchell Administration Centre	Council Offices	55899	35M1513	100 Cambridge St	1967	Craig Carlson	30-Jul-20	Building	East server room including cupboard perforated low density asbestos fibreboard ceiling panels	Low density board (2)	Friable	Confirmed	Q34185S44	Chrysotile; amosite (2)	Fair (2)	Sealed friable (2)	Medium	M.399; M.400
Mitchell	Mitchell Administration Centre	Council Offices	55899	35M1513	100 Cambridge St	1967	Craig Carlson	30-Jul-20	Building	South east offices perforated low density asbestos fibreboard ceiling panels	Low density board (2)	Friable	Presumed	Similar to Q34185S44	Chrysotile; amosite (2)	Fair (2)	Sealed friable (2)	Medium	M.401
Mitchell	Mitchell Administration Centre	Council Offices	55899	35M1513	100 Cambridge St	1967	Craig Carlson	30-Jul-20	Building	Male amenities low density asbestos fibreboard panels visible in ceiling cavity and visible in foyer upper window	Low density board (2)	Friable	Presumed	Similar to Q34185S44	Chrysotile; amosite (2)	Fair (2)	Sealed friable (2)	Medium	M.402; M.403
Mitchell	Mitchell Administration Centre	Council Offices	55899	35M1513	100 Cambridge St	1967	Craig Carlson	30-Jul-20	Building	Female amenities low density asbestos fibreboard ceiling in sink area and panels visible in foyer upper window	Low density board (2)	Friable	Presumed	Similar to Q34185S44	Chrysotile; amosite (2)	Fair (2)	Sealed friable (2)	Medium	M.404; M.405
Mitchell	Mitchell Administration Centre	Council Offices	55899	35M1513	100 Cambridge St	1967	Craig Carlson	30-Jul-20	Building	Electrical cupboard at rear door low density asbestos fibreboard ceiling	Low density board (2)	Friable	Presumed	Similar to Q34185S44	Chrysotile; amosite (2)	Fair (2)	Sealed friable (2)	Medium	M.406
Mitchell	Mitchell Administration Centre	Council Offices	55899	35M1513	100 Cambridge St	1967	Craig Carlson	30-Jul-20	Building	Cleaner's room perforated low density asbestos fibreboard ceiling panels	Low density board (2)	Friable	Presumed	Similar to Q34185S44	Chrysotile; amosite (2)	Fair (2)	Sealed friable (2)	Medium	M.407
Mitchell	Mitchell Administration Centre	Council Offices	55899	35M1513	100 Cambridge St	1967	Craig Carlson	30-Jul-20	Building	Lunch room low density asbestos fibreboard ceiling panels (south side of room perforated; north side of room flat sheet)	Low density board (2)	Friable	Presumed	Similar to Q34185S44	Chrysotile; amosite (2)	Fair (2)	Sealed friable (2)	Medium	M.408; M.409
Mitchell	Mitchell Administration Centre	Council Offices	55899	35M1513	100 Cambridge St	1967	Craig Carlson	30-Jul-20	Building	Printing room perforated low density asbestos fibreboard ceiling panels	Low density board (2)	Friable	Presumed	Similar to Q34185S44	Chrysotile; amosite (2)	Fair (2)	Sealed friable (2)	Medium	M.410
Mitchell	Mitchell Administration Centre	Council Offices	55899	35M1513	100 Cambridge St	1967	Craig Carlson	30-Jul-20	Building	Printing room asbestos cement sheeting wall around cupboard	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.411
Mitchell	Mitchell Administration Centre	Council Offices	55899	35M1513	100 Cambridge St	1967	Craig Carlson	30-Jul-20	Building	Office strong room door may be internally insulated with asbestos insulation	Loose fill (3)	Friable	Presumed	None taken	Chrysotile (1)	Fair (2)	Sealed friable (2)	Medium	M.412
Mitchell	Mitchell Administration Centre	Council Offices	55899	35M1513	100 Cambridge St	1967	Craig Carlson	30-Jul-20	Building	Administration office perforated low density asbestos fibreboard ceiling panels	Low density board (2)	Friable	Presumed	Similar to Q34185S44	Chrysotile; amosite (2)	Fair (2)	Sealed friable (2)	Medium	No image
Mitchell	Mitchell Administration Centre	Council Offices	55899	35M1513	100 Cambridge St	1967	Craig Carlson	30-Jul-20	Building	North administration office (construction 2011) non-asbestos fibre cement sheeting walls and ceiling	Cement based (1)	N/A	Not present (not tested)	None taken	No asbestos detected	N/A	N/A	N/A	M.413
Mitchell	Mitchell Administration Centre	Council Offices	55899	35M1513	100 Cambridge St	1967	Craig Carlson	30-Jul-20	Building	Building external asbestos cement sheeting infill panels under glazing	Cement based (1)	Bonded	Presumed	Similar to Q34185S43	Chrysotile; amosite; crocidolite (3)	Good (1)	Sealed bonded (1)	Low	M.414; M.415
Mitchell	Mitchell Administration Centre	Council Offices	55899	35M1513	100 Cambridge St	1967	Craig Carlson	30-Jul-20	Building	Building external asbestos cement sheeting soffits including front awning ceiling	Cement based (1)	Bonded	Presumed	Similar to Q34185S43	Chrysotile; amosite; crocidolite (3)	Good (1)	Sealed bonded (1)	Low	M.416; M.417; M.418
Mitchell	Mitchell Administration Centre	Council Offices	55899	35M1513	100 Cambridge St	1967	Craig Carlson	30-Jul-20	Building	Building external compressed asbestos cement sheeting wall on back carport	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.419

Town	Facility	Building	Asset No	Lot Plan	Address	Build Date	Auditor	Date of Inspection	ACM Location	Use of ACM / Component	ACM Material	Friable / Bonded	ACM Status	Sample #	ACM Type	ACM Condition	ACM Treatment	ACM Risk	Photo #
Mitchell	Mitchell Administration Centre	IT Workshop	55902	35M1513	100 Cambridge St	1990's	Craig Carlson	30-Jul-20	Building	All internal construction plasterboard; external metal sheeting with non-asbestos fibre cement sheeting artificial weatherboard	Cement based (1)	N/A	Not present (not tested)	None taken	No asbestos detected	N/A	N/A	N/A	M.420
Mitchell	Mitchell Council Depot	Batching Plant	56057	16CP861824	Industrial Estate Rd	1980's	Craig Carlson	30-Jul-20	Depot	All steel construction; no suspect gaskets present	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.424
Mitchell	Mitchell Council Depot	Kitchen Demountable	Unknown	16CP861824	Industrial Estate Rd	1990's	Craig Carlson	30-Jul-20	Depot	Demountable internal timber laminate walls and ceiling with non-asbestos vinyl sheet flooring; external all metal sheeting	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.425
Mitchell	Mitchell Council Depot	Shed 2	Unknown	16CP861824	Industrial Estate Rd	Post 2000	Craig Carlson	30-Jul-20	Depot	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.426
Mitchell	Mitchell Council Depot	Workshop	56052	16CP861824	Industrial Estate Rd	Post 2000	Craig Carlson	30-Jul-20	Depot	Main building metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.427
Mitchell	Mitchell Council Depot	Workshop	56052	16CP861824	Industrial Estate Rd	Post 2000	Craig Carlson	30-Jul-20	Depot	Internal predominantly plasterboard walls and ceilings with non-asbestos fibre cement sheeting in male and female amenities	Cement based (1)	N/A	Not present (not tested)	None taken	No asbestos detected	N/A	N/A	N/A	M.428
Mitchell	Mitchell Council Depot	Workshop	56052	16CP861824	Industrial Estate Rd	Post 2000	Craig Carlson	30-Jul-20	Depot	External north wall stored asbestos electrical mounting panel	Insulation board (2)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Low	M.429
Mitchell	Workers Camp (Dunkeld)	Accommodation R01-R02 - PL1105	56101	8KE70	Mitchell St George Rd	1990's	Craig Carlson	28-Jul-20	Depot	Demountable internal timber laminate walls and ceiling with non-asbestos vinyl sheet flooring; external all metal sheeting	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.245
Mitchell	Workers Camp (Dunkeld)	Accommodation R03-R04 - PL1106	68075	8KE70	Mitchell St George Rd	1990's	Craig Carlson	28-Jul-20	Depot	Demountable internal timber laminate walls and ceiling with non-asbestos vinyl sheet flooring; external all metal sheeting	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.246
Mitchell	Workers Camp (Dunkeld)	Accommodation R05-R06 - PL1107	68080	8KE70	Mitchell St George Rd	1990's	Craig Carlson	28-Jul-20	Depot	Demountable internal timber laminate walls and ceiling with non-asbestos vinyl sheet flooring; external all metal sheeting	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.247
Mitchell	Workers Camp (Dunkeld)	Shade Structure - Common Area	60568	8KE70	Mitchell St George Rd	1990's	Craig Carlson	28-Jul-20	Depot	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.248
Mitchell	Workers Camp (Dunkeld)	Pump Shed	Unknown	8KE70	Mitchell St George Rd	1990's	Craig Carlson	28-Jul-20	Depot	All timber and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.249
Mitchell	Major Mitchell Caravan Park	Camp Kitchen and BBQ	55958	1SP265644	Warrego Hwy	Post 2000	Craig Carlson	29-Jul-20	Park	All steel, timber and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.312
Mitchell	Major Mitchell Caravan Park	Office	55955	1SP265644	Warrego Hwy	1990's	Craig Carlson	29-Jul-20	Building	Internal non-asbestos fibre cement sheeting walls and ceiling with metal sheeting external construction	Cement based (1)	N/A	Not present (not tested)	None taken	No asbestos detected	N/A	N/A	N/A	M.302; M.303
Mitchell	Major Mitchell Caravan Park	Residence	Unknown	1SP265644	Warrego Hwy	1970's	Craig Carlson	29-Jul-20	Building	Lounge room asbestos cement sheeting walls and ceiling; timber partition to kitchen and bedroom	Cement based (1)	Bonded	Presumed	Similar to Q34185S34	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.304
Mitchell	Major Mitchell Caravan Park	Residence	Unknown	1SP265644	Warrego Hwy	1970's	Craig Carlson	29-Jul-20	Building	Kitchen asbestos cement sheeting walls and ceiling	Cement based (1)	Bonded	Presumed	Similar to Q34185S34	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.305
Mitchell	Major Mitchell Caravan Park	Residence	Unknown	1SP265644	Warrego Hwy	1970's	Craig Carlson	29-Jul-20	Building	Bedroom including cupboard/wardrobe asbestos cement sheeting walls and ceiling	Cement based (1)	Bonded	Confirmed	Q34185S34	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.306; M.307
Mitchell	Major Mitchell Caravan Park	Residence	Unknown	1SP265644	Warrego Hwy	1970's	Craig Carlson	29-Jul-20	Building	Bathroom asbestos cement sheeting walls and ceiling; ceramic tile flooring on unknown substrate	Cement based (1)	Bonded	Presumed	Similar to Q34185S34	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.308
Mitchell	Major Mitchell Caravan Park	Residence	Unknown	1SP265644	Warrego Hwy	1970's	Craig Carlson	29-Jul-20	Building	Building external asbestos cement cladding on north rear half of building and laundry store, with timber cladding on south front half of building	Cement based (1)	Bonded	Presumed	Similar to Q34185S34	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.309; M.310
Mitchell	Major Mitchell Caravan Park	Residence	Unknown	1SP265644	Warrego Hwy	1970's	Craig Carlson	29-Jul-20	Building	Building external asbestos cement sheeting soffits	Cement based (1)	Bonded	Presumed	Similar to Q34185S34	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.311
Mitchell	Major Mitchell Caravan Park	Picnic Shelter No1	55980	1SP265644	Warrego Hwy	Post 2000	Craig Carlson	29-Jul-20	Park	All timber and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.313
Mitchell	Major Mitchell Caravan Park	Picnic Shelter No2	60401	1SP265644	Warrego Hwy	Post 2000	Craig Carlson	29-Jul-20	Park	All timber and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.314
Mitchell	Major Mitchell Caravan Park	Picnic Shelter No3	60402	1SP265644	Warrego Hwy	Post 2000	Craig Carlson	29-Jul-20	Park	All timber and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.315
Mitchell	Major Mitchell Caravan Park	Picnic Shelter No4	60403	1SP265644	Warrego Hwy	Post 2000	Craig Carlson	29-Jul-20	Park	All timber and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.316

Town	Facility	Building	Asset No	Lot Plan	Address	Build Date	Auditor	Date of Inspection	ACM Location	Use of ACM / Component	ACM Material	Friable / Bonded	ACM Status	Sample #	ACM Type	ACM Condition	ACM Treatment	ACM Risk	Photo #
Mitchell	Major Mitchell Caravan Park	Picnic Shelter No5	60404	1SP265644	Warrego Hwy	Post 2000	Craig Carlson	29-Jul-20	Park	All timber and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.317
Mitchell	Major Mitchell Caravan Park	Picnic Shelter No6	60405	1SP265644	Warrego Hwy	Post 2000	Craig Carlson	29-Jul-20	Park	All timber and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.318
Mitchell	Major Mitchell Caravan Park	Picnic Shelters (Large)	55981	1SP265644	Warrego Hwy	Post 2000	Craig Carlson	29-Jul-20	Park	All timber and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.319
Mitchell	Major Mitchell Caravan Park	Storage Shed	55959	1SP265644	Warrego Hwy	Post 2000	Craig Carlson	29-Jul-20	Building	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.321
Mitchell	Major Mitchell Caravan Park	Amenities Blocks	Unknown	1SP265644	Warrego Hwy	Post 2000	Craig Carlson	29-Jul-20	Public Amenities	All metal sheeting and non-asbestos fibre cement sheeting construction	Cement based (1)	N/A	Not present (not tested)	None taken	No asbestos detected	N/A	N/A	N/A	M.320
Mitchell	Mitchell Recreation Reserve	Rotary Clubroom (Prev Scout Hut)	60527	1M15136	Mary St	1950's	Craig Carlson	30-Jul-20	Building	Internal all masonite walls and ceiling; external timber walls and metal sheeting roof	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Mitchell	Mitchell Recreation Reserve	Rotary Shed - 2 Bay Garage	55774	1M15136	Mary St	1990's	Craig Carlson	30-Jul-20	Building	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.432
Mitchell	Mitchell Recreation Reserve	Toilet Block	27799	1M15136	Mary St	1960's	Craig Carlson	30-Jul-20	Public Amenities	Internal asbestos cement sheeting wall behind urinal (sighted from external; no internal access)	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.433
Mitchell	Mitchell Recreation Reserve	Toilet Block	27799	1M15136	Mary St	1960's	Craig Carlson	30-Jul-20	Public Amenities	External asbestos cement sheeting walls on south and west wall	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.434
Mitchell	Mitchell Recreation Reserve	Toilet Block	27799	1M15136	Mary St	1960's	Craig Carlson	30-Jul-20	Public Amenities	External asbestos cement vent pipe	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.435
Mitchell	Mitchell RSL and Sports Grounds	Amenities Building	62608	115DL335	36 Liverpool St	Post 2000	Craig Carlson	29-Jul-20	Public Amenities	Demountable internal timber laminate walls and ceiling with non-asbestos vinyl sheet flooring; external all metal sheeting	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.280
Mitchell	Mitchell RSL and Sports Grounds	Campdraft Building	62609	115DL335	36 Liverpool St	Post 2000	Craig Carlson	29-Jul-20	Building	All metal sheeting roof and walls	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.279
Mitchell	Mitchell RSL and Sports Grounds	Canteen	62610	115DL335	36 Liverpool St	1960's	Craig Carlson	29-Jul-20	Building	All metal sheeting roof and walls	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.278
Mitchell	Mitchell RSL and Sports Grounds	Mitchell RSL Building	27777	115DL335	36 Liverpool St	1970's (relocated 1994)	Craig Carlson	29-Jul-20	Building	Level 1 Bar area masonite walls and ceilings in main area with asbestos cement sheeting walls and ceiling in small foyer to external adjacent cold room	Cement based (1)	Bonded	Presumed	Similar to Q34185S30	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.287
Mitchell	Mitchell RSL and Sports Grounds	Mitchell RSL Building	27777	115DL335	36 Liverpool St	1970's (relocated 1994)	Craig Carlson	29-Jul-20	Building	Level 1 Kitchen masonite main walls and ceilings with asbestos cement sheeting partition to main hall and to cleaner's cupboard	Cement based (1)	Bonded	Presumed	Similar to Q34185S30	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.288
Mitchell	Mitchell RSL and Sports Grounds	Mitchell RSL Building	27777	115DL335	36 Liverpool St	1970's (relocated 1994)	Craig Carlson	29-Jul-20	Building	Level 1 Main hall and back foyer area masonite and timber walls and ceiling with limited areas of non-asbestos fibre cement sheeting replacement panels	Cement based (1)	N/A	Not present (not tested)	None taken	No asbestos detected	N/A	N/A	N/A	No image
Mitchell	Mitchell RSL and Sports Grounds	Mitchell RSL Building	27777	115DL335	36 Liverpool St	1970's (relocated 1994)	Craig Carlson	29-Jul-20	Building	Level 1 male amenities asbestos cement sheeting walls throughout including tilux section on centre partition; masonite ceiling	Cement based (1)	Bonded	Confirmed	Q34185S30	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.289; M.290
Mitchell	Mitchell RSL and Sports Grounds	Mitchell RSL Building	27777	115DL335	36 Liverpool St	1970's (relocated 1994)	Craig Carlson	29-Jul-20	Building	Level 1 female amenities asbestos cement sheeting walls throughout; masonite ceiling	Cement based (1)	Bonded	Presumed	Similar to Q34185S30	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.291
Mitchell	Mitchell RSL and Sports Grounds	Mitchell RSL Building	27777	115DL335	36 Liverpool St	1970's (relocated 1994)	Craig Carlson	29-Jul-20	Building	Level G throughout concrete block walls with non-asbestos fibre cement sheeting ceilings in two canteen areas	Cement based (1)	N/A	Not present (not tested)	None taken	No asbestos detected	N/A	N/A	N/A	M.292; M.293
Mitchell	Mitchell RSL and Sports Grounds	Mitchell RSL Building	27777	115DL335	36 Liverpool St	1970's (relocated 1994)	Craig Carlson	29-Jul-20	Building	Level G male amenities asbestos cement sheeting fragments present on upper ceiling structure	Cement based (1)	Bonded	Presumed	Similar to Q34185S30	Chrysotile (1)	Poor (3)	Unsealed bonded (2)	Medium	M.294
Mitchell	Mitchell RSL and Sports Grounds	Mitchell RSL Building	27777	115DL335	36 Liverpool St	1970's (relocated 1994)	Craig Carlson	29-Jul-20	Building	Building external non-asbestos fibre cement sheeting upper wall above level G block walls	Cement based (1)	N/A	Not present (tested)	Q34185S31	No asbestos detected	N/A	N/A	N/A	M.295; M.296
Mitchell	Mitchell RSL and Sports Grounds	Mitchell RSL Building	27777	115DL335	36 Liverpool St	1970's (relocated 1994)	Craig Carlson	29-Jul-20	Building	Building external non-asbestos fibre cement sheeting soffits, verandah ceiling and verandah fascia pane	Cement based (1)	N/A	Not present (tested)	Q34185S33	No asbestos detected	N/A	N/A	N/A	M.297; M.298; M.299



Town	Facility	Building	Asset No	Lot Plan	Address	Build Date	Auditor	Date of Inspection	ACM Location	Use of ACM / Component	ACM Material	Friable / Bonded	ACM Status	Sample #	ACM Type	ACM Condition	ACM Treatment	ACM Risk	Photo #
Mitchell	Mitchell RSL and Sports Grounds	Mitchell RSL Building	27777	115DL335	36 Liverpool St	1970's (relocated 1994)	Craig Carlson	29-Jul-20	Building	Building external level 1 external cladding asbestos cement sheeting (shadowline)	Cement based (1)	bonded	Confirmed	Q34185S32	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.300
Mitchell	Mitchell RSL and Sports Grounds	Rodeo Canteen	62611	115DL335	36 Liverpool St	1970's	Craig Carlson	29-Jul-20	Building	Internal non-asbestos fibre cement sheeting walls and ceiling	Cement based (1)	N/A	Not present (tested)	Q34185S28	No asbestos detected	N/A	N/A	N/A	M.282
Mitchell	Mitchell RSL and Sports Grounds	Rodeo Canteen	62611	115DL335	36 Liverpool St	1970's	Craig Carlson	29-Jul-20	Building	Laminated asbestos cement sheeting (Tilux) sink splashback, old stove backing under extraction fan and benchtop	Cement based (1)	Bonded	Confirmed	Q34185S29	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.283; M.284; M.285
Mitchell	Mitchell RSL and Sports Grounds	Rodeo Canteen	62611	115DL335	36 Liverpool St	1970's	Craig Carlson	29-Jul-20	Building	External electrical board compressed asbestos mounting panel	Insulation board (2)	Bonded	Presumed	None taken	Chrysotile (1)	Fair (2)	Unsealed bonded (2)	Low	M.286
Mitchell	Mitchell RSL and Sports Grounds	Shower and Toilet Block	62301	115DL335	36 Liverpool St	Post 2000	Craig Carlson	29-Jul-20	Public Amenities	Demountable internal timber laminate walls and ceiling with non-asbestos vinyl sheet flooring; external all metal sheeting	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.281
Mitchell	Mitchell Showgrounds	West Toilet Block	Unknown	27M15140	210 Alice St	1970's	Craig Carlson	25-Jul-20	Public Amenities	Brick walls with metal sheeting roof; three asbestos cement vent pipes	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.172
Mitchell	Mitchell Showgrounds	SES Facility	Unknown	27M15140	210 Alice St	Post 2000	Craig Carlson	25-Jul-20	Building	All metal sheeting external and non-asbestos fibre cement sheeting internal	Cement based (1)	N/A	Not present (not tested)	None taken	No asbestos detected	N/A	N/A	N/A	M.173; M.174; M.175; M.176
Mitchell	Mitchell Showgrounds	North Toilet Block	Unknown	27M15140	210 Alice St	1970's	Craig Carlson	25-Jul-20	Public Amenities	Brick walls with metal sheeting roof; asbestos cement vent pipe	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.177
Mitchell	Mitchell Showgrounds	South Toilet Block	Unknown	27M15140	210 Alice St	1970's	Craig Carlson	25-Jul-20	Public Amenities	Concrete block walls with metal sheeting roof; asbestos cement vent pipe	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.187
Mitchell	Mitchell Showgrounds	Jack Carlyon Pavilion	Unknown	27M15140	210 Alice St	1960's	Craig Carlson	25-Jul-20	Building	Building all steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.182
Mitchell	Mitchell Showgrounds	Jack Carlyon Pavilion	Unknown	27M15140	210 Alice St	1960's	Craig Carlson	25-Jul-20	Building	Electrical board compressed asbestos mounting panel	Insulation board (2)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Unsealed bonded (2)	Low	M.181
Mitchell	Mitchell Showgrounds	Shed next to Jack Carlyon Pavilion	Unknown	27M15140	210 Alice St	1970's	Craig Carlson	25-Jul-20	Building	Building all steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.183
Mitchell	Mitchell Showgrounds	Joe Rolfe Pavilion	Unknown	27M15140	210 Alice St	1970's	Craig Carlson	25-Jul-20	Building	Building all steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.185
Mitchell	Mitchell Showgrounds	Stables	Unknown	27M15140	210 Alice St	1970's	Craig Carlson	25-Jul-20	Building	Building all steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.188
Mitchell	Mitchell Showgrounds	Bird and Chook Pavilion	27815	27M15140	210 Alice St	1990's	Craig Carlson	25-Jul-20	Building	Building all steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.184
Mitchell	Mitchell Showgrounds	Boxing Shed and Canteen	27807	27M15140	210 Alice St	1960's	Craig Carlson	25-Jul-20	Building	External metal sheeting roof and walls; asbestos cement vent pipe (currently disused)	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.178; M.179
Mitchell	Mitchell Showgrounds	Boxing Shed and Canteen	27807	27M15140	210 Alice St	1960's	Craig Carlson	25-Jul-20	Building	Electrical board compressed asbestos mounting panel	Insulation board (2)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Unsealed bonded (2)	Low	M.180
Mitchell	Mitchell Showgrounds	Boxing Shed and Canteen	27807	27M15140	210 Alice St	1960's	Craig Carlson	25-Jul-20	Building	Electrical board asbestos cement sheeting internal lining	Cement based (1)	Bonded	Presumed	None taken	Chrysotile; amosite (2)	Fair (2)	Unsealed bonded (2)	Medium	M.180
Mitchell	Mitchell Showgrounds	Carport	55952	27M15140	210 Alice St	1970's	Craig Carlson	25-Jul-20	Building	Building all steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.186
Mitchell	Mitchell Swimming Pool	Pool Shade	55735	1SP265643	6 Cambridge St	Post 2000	Craig Carlson	28-Jul-20	Swimming Pool	All steel and shadecloth construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.250
Mitchell	Mitchell Swimming Pool	Pump House	55741	1SP265643	6 Cambridge St	Post 2000	Craig Carlson	28-Jul-20	Swimming Pool	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.251
Mitchell	Mitchell Swimming Pool	Shed Sail - Wet Play	62602	1SP265643	6 Cambridge St	Post 2000	Craig Carlson	28-Jul-20	Swimming Pool	All steel and shadecloth construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.252
Mitchell	Mitchell Swimming Pool	Disabled Amenities Building	Unknown	1SP265643	6 Cambridge St	Post 2000	Craig Carlson	28-Jul-20	Swimming Pool	All steel and metal sheeting construction; currently used as storage only	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.253

Town	Facility	Building	Asset No	Lot Plan	Address	Build Date	Auditor	Date of Inspection	ACM Location	Use of ACM / Component	ACM Material	Friable / Bonded	ACM Status	Sample #	ACM Type	ACM Condition	ACM Treatment	ACM Risk	Photo #
Mitchell	Mitchell Swimming Pool	Main Building	Unknown	1SP265643	6 Cambridge St	1955 (renovated 2016)	Craig Carlson	28-Jul-20	Swimming Pool	Male change room, female change room, canteen and open areas all non-asbestos fibre cement sheeting walls and ceilings (suspected newly installed in 2016 renovation)	Cement based (1)	N/A	Not present (tested)	Q34185S25	No asbestos detected	N/A	N/A	N/A	M.254; M.255; M.256; M.257; M.258; M.259
Mitchell	Mitchell Swimming Pool	Main Building	Unknown	1SP265643	6 Cambridge St	1955 (renovated 2016)	Craig Carlson	28-Jul-20	Swimming Pool	External soffits non-asbestos fibre cement sheeting (suspected newly installed in 2016 renovation)	Cement based (1)	N/A	Not present (not tested)	None taken	No asbestos detected	N/A	N/A	N/A	M.260
Mitchell	Mitchell Swimming Pool	Main Building	Unknown	1SP265643	6 Cambridge St	1955 (renovated 2016)	Craig Carlson	28-Jul-20	Swimming Pool	External asbestos cement vent pipe for female amenities	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Fair (2)	Unsealed bonded (2)	Low	M.261
Mitchell	Mitchell Swimming Pool	Main Building	Unknown	1SP265643	6 Cambridge St	1955 (renovated 2016)	Craig Carlson	28-Jul-20	Swimming Pool	External asbestos cement sheeting front gable end and soffits on front gable	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.262; M.263
Mitchell	Pony Club Grounds (Old Saleyards)	Building	62604	127SP203119	Rowallan Estate Rd	1960's	Craig Carlson	28-Jul-20	Building	West room masonite and timber walls with metal sheeting roof and concrete flooring	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Mitchell	Pony Club Grounds (Old Saleyards)	Building	62604	127SP203119	Rowallan Estate Rd	1960's	Craig Carlson	28-Jul-20	Building	East room timber main walls with asbestos cement sheeting wall around pantry and internal walls and ceiling in pantry	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.265; M.266
Mitchell	Pony Club Grounds (Old Saleyards)	Building	62604	127SP203119	Rowallan Estate Rd	1960's	Craig Carlson	28-Jul-20	Building	East room non-asbestos fibre cement sheeting packers under servery bench	Cement based (1)	N/A	Not present (tested)	Q34185S26	No asbestos detected	N/A	N/A	N/A	M.267
Mitchell	Pony Club Grounds (Old Saleyards)	Building	62604	127SP203119	Rowallan Estate Rd	1960's	Craig Carlson	28-Jul-20	Building	East room asbestos cement sheeting wall lining above and under servery bench	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.268; M.269
Mitchell	Pony Club Grounds (Old Saleyards)	Building	62604	127SP203119	Rowallan Estate Rd	1960's	Craig Carlson	28-Jul-20	Building	Male and female amenities timber walls with metal sheeting roof and asbestos cement sheeting wall lining in shower recess in male amenities	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.270
Mitchell	Pony Club Grounds (Old Saleyards)	Building	62604	127SP203119	Rowallan Estate Rd	1960's	Craig Carlson	28-Jul-20	Building	Building external asbestos cement sheeting soffits	Cement based (1)	Bonded	Confirmed	Q34185S27	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.271; M.272
Mitchell	Pony Club Grounds (Old Saleyards)	Building	62604	127SP203119	Rowallan Estate Rd	1960's	Craig Carlson	28-Jul-20	Building	Building external asbestos cement vent pipe for male amenities	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Unsealed bonded (2)	Low	M.273
Mitchell	Pony Club Grounds (Old Saleyards)	Building	62604	127SP203119	Rowallan Estate Rd	1960's	Craig Carlson	28-Jul-20	Building	Building electrical board mounting panel compressed asbestos board	Insulation board (2)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Unsealed bonded (2)	Low	M.274
Mitchell	Pony Club Grounds (Old Saleyards)	Carport	62605	127SP203119	Rowallan Estate Rd	1960's	Craig Carlson	28-Jul-20	Building	All steel, timber and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.276
Mitchell	Pony Club Grounds (Old Saleyards)	Storage Shed	62606	127SP203119	Rowallan Estate Rd	1980's	Craig Carlson	28-Jul-20	Building	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.277
Mitchell	Fisherman's Rest	Toilet Block	27705	Road Reserve	Fisherman's Rest Rd	Post 2000	Craig Carlson	21-Jul-20	Public Amenities	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.18
Mitchell	Memorial Park	Shade Shelter No1	68659	2M15146	Ann St	Post 2000	Craig Carlson	21-Jul-20	Park	All steel and shadecloth construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.05
Mitchell	Memorial Park	Shade Shelter No2	68660	2M15146	Ann St	Post 2000	Craig Carlson	21-Jul-20	Park	All steel and shadecloth construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.06
Mitchell	Memorial Park	Stage Shelter	27757	2M15146	Ann St	1990's	Craig Carlson	21-Jul-20	Park	All steel, timber and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.07
Mitchell	Memorial Park	Storage Shed - Parks	27762	2M15146	Ann St	Post 2000	Craig Carlson	21-Jul-20	Building	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.08
Mitchell	Memorial Park	Table Shelter 1	27750	2M15146	Ann St	1990's	Craig Carlson	21-Jul-20	Park	All steel, timber and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.09
Mitchell	Memorial Park	Table Shelter 2	27751	2M15146	Ann St	1990's	Craig Carlson	21-Jul-20	Park	All steel, timber and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.10
Mitchell	Memorial Park	Table Shelter 3	27752	2M15146	Ann St	1990's	Craig Carlson	21-Jul-20	Park	All steel, timber and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.11
Mitchell	Mitchell Youth Precinct and Skate Park	Pergola	56037	3I71817	41-45 Hutton St	Post 2000	Craig Carlson	21-Jul-20	Park	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.12
Mitchell	Mitchell Youth Precinct and Skate Park	Skate Park Shed (Youth Hub)	27771	3I71817	41-45 Hutton St	Post 2000	Craig Carlson	21-Jul-20	Park	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.13

Town	Facility	Building	Asset No	Lot Plan	Address	Build Date	Auditor	Date of Inspection	ACM Location	Use of ACM / Component	ACM Material	Friable / Bonded	ACM Status	Sample #	ACM Type	ACM Condition	ACM Treatment	ACM Risk	Photo #
Mitchell	Mitchell Youth Precinct and Skate Park	Table Shelter	27766	3I71817	41-45 Hutton St	None present	Craig Carlson	21-Jul-20	Park	No table shelter present	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Mitchell	Rotary Weir Park	Shelter 1	27720	3DL366	Racecourse Rd	1980's	Craig Carlson	21-Jul-20	Park	All timber and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.14
Mitchell	Rotary Weir Park	Shelter 2	27721	3DL366	Racecourse Rd	1980's	Craig Carlson	21-Jul-20	Park	All timber and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.15
Mitchell	Rotary Weir Park	Shelter 3	27722	3DL366	Racecourse Rd	1980's	Craig Carlson	21-Jul-20	Park	All timber and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.16
Mitchell	Rotary Weir Park	Toilet Block	Unknown	3DL366	Racecourse Rd	1980's	Craig Carlson	21-Jul-20	Public Amenities	Concrete block walls with metal sheeting roof	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.17
Mitchell	1 St George Road MRV	Dwelling Duplex 1-2	29049	1DL143	Bollon Rd	1990's	Craig Carlson	21-Jul-20	Building	Internal throughout unit 1 and unit 2 plasterboard walls and ceilings in lounge, kitchen, dining and bedrooms (two) with non-asbestos vinyl sheet and carpet flooring.	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Mitchell	1 St George Road MRV	Dwelling Duplex 1-2	29049	1DL143	Bollon Rd	1990's	Craig Carlson	21-Jul-20	Building	Unit 1 and unit 2 laundry and unit 1 bathroom non-asbestos fibre cement sheeting and plasterboard walls and ceilings with ceramic tile flooring	Cement based (1)	N/A	Not present (not tested)	None taken	No asbestos detected	N/A	N/A	N/A	M.01; M.02
Mitchell	1 St George Road MRV	Dwelling Duplex 1-2	29049	1DL143	Bollon Rd	1990's	Craig Carlson	21-Jul-20	Building	Unit 2 bathroom renovated post 2000 with timber laminate walls and ceramic tile flooring	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.03
Mitchell	1 St George Road MRV	Dwelling Duplex 1-2	29049	1DL143	Bollon Rd	1990's	Craig Carlson	21-Jul-20	Building	External non-asbestos fibre cement sheeting soffits, and infill panels above glazing	Cement based (1)	N/A	Not present (tested)	Q34185S01	No asbestos detected	N/A	N/A	N/A	M.04
Mitchell	11 Adelaide Street	Dwelling	28746	3M15128	11 Adelaide St	1960's	Craig Carlson	22-Jul-20	Building	Lounge, foyer and bedrooms (two) masonite walls and ceiling with carpet flooring	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Mitchell	11 Adelaide Street	Dwelling	28746	3M15128	11 Adelaide St	1960's	Craig Carlson	22-Jul-20	Building	Bathroom non-asbestos fibre cement sheeting walls and ceiling; post 2000 renovation	Cement based (1)	N/A	Not present (not tested)	None taken	No asbestos detected	N/A	N/A	N/A	M.88
Mitchell	11 Adelaide Street	Dwelling	28746	3M15128	11 Adelaide St	1960's	Craig Carlson	22-Jul-20	Building	Bathroom original asbestos cement sheeting upper wall sections and ceiling sheeting present; as visible in roof cavity	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Poor (3)	Unsealed bonded (2)	Medium	M.89
Mitchell	11 Adelaide Street	Dwelling	28746	3M15128	11 Adelaide St	1960's	Craig Carlson	22-Jul-20	Building	Kitchen/dining room asbestos cement sheeting and masonite walls and ceiling at random locations; no pattern to usage; masonite ceiling in main room and asbestos cement in outer section	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.90
Mitchell	11 Adelaide Street	Dwelling	28746	3M15128	11 Adelaide St	1960's	Craig Carlson	22-Jul-20	Building	Rear extension (1990's) non-asbestos fibre cement sheeting internal walls and ceiling in main room and toilet; non-asbestos fibre cement sheeting external artificial weatherboards	Cement based (1)	N/A	No asbestos detected	Q34185S14	No asbestos detected	N/A	N/A	N/A	M.91; M.92; M.96
Mitchell	11 Adelaide Street	Dwelling	28746	3M15128	11 Adelaide St	1960's	Craig Carlson	22-Jul-20	Building	Building external asbestos cement sheeting soffits and gable ends (three)	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.93; M.94
Mitchell	11 Adelaide Street	Dwelling	28746	3M15128	11 Adelaide St	1960's	Craig Carlson	22-Jul-20	Building	Building external asbestos cement vent pipe	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.95
Mitchell	11 Adelaide Street	Dwelling	28746	3M15128	11 Adelaide St	1960's	Craig Carlson	22-Jul-20	Building	Rear shed asbestos cement sheeting external walls; the sheeting has sustained damage and fragments are visible on the surface ground	Cement based (1)	Bonded	Confirmed	Q340185S14	Chrysotile; amosite (2)	Poor (3)	Unsealed bonded (2)	Medium	M.97; M.98; M.100
Mitchell	181 Alice Street	Dwelling	76960	8M15144	181 Alice St	1950's	Craig Carlson	21-Jul-20	Building	Lounge, foyer, hall and bedrooms (three) masonite walls and ceilings	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Mitchell	181 Alice Street	Dwelling	76960	8M15144	181 Alice St	1950's	Craig Carlson	21-Jul-20	Building	Kitchen masonite walls and ceiling in main room with asbestos cement sheeting walls and ceiling in stove recess	Cement based (1)	Bonded	Confirmed	Q34185S05	Chrysotile; amosite; crocidolite (3)	Good (1)	Sealed bonded (1)	Low	M.33
Mitchell	181 Alice Street	Dwelling	76960	8M15144	181 Alice St	1950's	Craig Carlson	21-Jul-20	Building	Bathroom asbestos cement sheeting walls and ceiling with ceramic tile flooring on unknown substrate	Cement based (1)	Bonded	Presumed	Similar to Q34185S05	Chrysotile; amosite; crocidolite (3)	Good (1)	Sealed bonded (1)	Low	M.34

Town	Facility	Building	Asset No	Lot Plan	Address	Build Date	Auditor	Date of Inspection	ACM Location	Use of ACM / Component	ACM Material	Friable / Bonded	ACM Status	Sample #	ACM Type	ACM Condition	ACM Treatment	ACM Risk	Photo #
Mitchell	181 Alice Street	Dwelling	76960	8M15144	181 Alice St	1950's	Craig Carlson	21-Jul-20	Building	Back open room asbestos cement sheeting ceiling	Cement based (1)	Bonded	Presumed	Similar to Q34185S05	Chrysotile; amosite; crocidolite (3)	Good (1)	Sealed bonded (1)	Low	M.35
Mitchell	181 Alice Street	Dwelling	76960	8M15144	181 Alice St	1950's	Craig Carlson	21-Jul-20	Building	Back open room asbestos cement vent pipe to roof	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.36; M.37
Mitchell	181 Alice Street	Dwelling	76960	8M15144	181 Alice St	1950's	Craig Carlson	21-Jul-20	Building	Toilet and laundry asbestos cement sheeting walls and ceiling	Cement based (1)	Bonded	Presumed	Similar to Q34185S05	Chrysotile; amosite; crocidolite (3)	Good (1)	Sealed bonded (1)	Low	M.38; M.39
Mitchell	181 Alice Street	Dwelling	76960	8M15144	181 Alice St	1950's	Craig Carlson	21-Jul-20	Building	Toilet vinyl asbestos tile flooring	Vinyl tiles (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	No image
Mitchell	181 Alice Street	Dwelling	76960	8M15144	181 Alice St	1950's	Craig Carlson	21-Jul-20	Building	Building external asbestos cement sheeting soffits and external ceilings including front verandah ceiling	Cement based (1)	Bonded	Presumed	Similar to Q34185S05	Chrysotile; amosite; crocidolite (3)	Good (1)	Sealed bonded (1)	Low	M.40, M.41
Mitchell	181 Alice Street	Dwelling	76960	8M15144	181 Alice St	1950's	Craig Carlson	21-Jul-20	Building	Building external asbestos cement vent pipe	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Low	M.41
Mitchell	2 Elizabeth Street - Pool	Dwelling	28758	1SP265643	6 Cambridge St	1960's	Craig Carlson	22-Jul-20	Building	Entry foyer asbestos cement sheeting ceiling and walls to external	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.100
Mitchell	2 Elizabeth Street - Pool	Dwelling	28758	1SP265643	6 Cambridge St	1960's	Craig Carlson	22-Jul-20	Building	Lounge/dining room asbestos cement sheeting ceiling with masonite walls	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.101
Mitchell	2 Elizabeth Street - Pool	Dwelling	28758	1SP265643	6 Cambridge St	1960's	Craig Carlson	22-Jul-20	Building	Kitchen asbestos cement sheeting walls and ceiling	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.102
Mitchell	2 Elizabeth Street - Pool	Dwelling	28758	1SP265643	6 Cambridge St	1960's	Craig Carlson	22-Jul-20	Building	Bedrooms (two) asbestos cement sheeting ceiling and masonite walls	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.103; M.104
Mitchell	2 Elizabeth Street - Pool	Dwelling	28758	1SP265643	6 Cambridge St	1960's	Craig Carlson	22-Jul-20	Building	Bathroom asbestos cement sheeting walls and ceiling	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.105
Mitchell	2 Elizabeth Street - Pool	Dwelling	28758	1SP265643	6 Cambridge St	1960's	Craig Carlson	22-Jul-20	Building	Toilet (external) asbestos cement sheeting walls and ceiling	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.106
Mitchell	2 Elizabeth Street - Pool	Dwelling	28758	1SP265643	6 Cambridge St	1960's	Craig Carlson	22-Jul-20	Building	Building external asbestos cement sheeting ceiling in covered area and laundry	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.107
Mitchell	2 Elizabeth Street - Pool	Dwelling	28758	1SP265643	6 Cambridge St	1960's	Craig Carlson	22-Jul-20	Building	Building external asbestos cement sheeting soffits	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.108; M.109
Mitchell	2 Elizabeth Street - Pool	Dwelling	28758	1SP265643	6 Cambridge St	1960's	Craig Carlson	22-Jul-20	Building	Building external asbestos cement vent pipe	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.110
Mitchell	2 Elizabeth Street - Pool	Dwelling	28758	1SP265643	6 Cambridge St	1960's	Craig Carlson	22-Jul-20	Building	Building external asbestos cement sheeting infill panel around front entry door	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.111
Mitchell	27 Edinburgh Street	Dwelling	28762	1RP100841	27 Edinburgh St	1950's	Craig Carlson	22-Jul-20	Building	Front built-in verandah asbestos cement sheeting walls (including suspected behind lower walls), and ceiling sheeting	Cement based (1)	Bonded	Presumed	Similar to Q34185S09	Chrysotile; amosite (2)	Good (1)	Sealed bonded (1)	Low	M.52; M.53
Mitchell	27 Edinburgh Street	Dwelling	28762	1RP100841	27 Edinburgh St	1950's	Craig Carlson	22-Jul-20	Building	Front built-in verandah non-asbestos vinyl sheet flooring	Vinyl sheeting (2)	N/A	Not present (tested)	Q34185S08	No asbestos detected	N/A	N/A	N/A	M.54
Mitchell	27 Edinburgh Street	Dwelling	28762	1RP100841	27 Edinburgh St	1950's	Craig Carlson	22-Jul-20	Building	Lounge/dining room asbestos cement sheeting ceiling	Cement based (1)	Bonded	Confirmed	Q34185S09	Chrysotile; amosite (2)	Good (1)	Sealed bonded (1)	Low	M.55
Mitchell	27 Edinburgh Street	Dwelling	28762	1RP100841	27 Edinburgh St	1950's	Craig Carlson	22-Jul-20	Building	Kitchen asbestos cement sheeting wall behind stove	Cement based (1)	Bonded	Presumed	Similar to Q34185S09	Chrysotile; amosite (2)	Good (1)	Sealed bonded (1)	Low	M.56
Mitchell	27 Edinburgh Street	Dwelling	28762	1RP100841	27 Edinburgh St	1950's	Craig Carlson	22-Jul-20	Building	Bedrooms (four) and centre hall asbestos cement sheeting upper walls and ceilings	Cement based (1)	Bonded	Presumed	Similar to Q34185S09	Chrysotile; amosite (2)	Good (1)	Sealed bonded (1)	Low	M.57; M.58; M.59
Mitchell	27 Edinburgh Street	Dwelling	28762	1RP100841	27 Edinburgh St	1950's	Craig Carlson	22-Jul-20	Building	Toilet, bathroom and toilet foyer area asbestos cement sheeting ceilings with masonite walls	Cement based (1)	Bonded	Presumed	Similar to Q34185S09	Chrysotile; amosite (2)	Good (1)	Sealed bonded (1)	Low	M.60; M.61

Town	Facility	Building	Asset No	Lot Plan	Address	Build Date	Auditor	Date of Inspection	ACM Location	Use of ACM / Component	ACM Material	Friable / Bonded	ACM Status	Sample #	ACM Type	ACM Condition	ACM Treatment	ACM Risk	Photo #
Mitchell	27 Edinburgh Street	Dwelling	28762	1RP100841	27 Edinburgh St	1950's	Craig Carlson	22-Jul-20	Building	Stair foyer asbestos cement sheeting walls and ceiling	Cement based (1)	Bonded	Presumed	Similar to Q34185S09	Chrysotile; amosite (2)	Good (1)	Sealed bonded (1)	Low	M.62
Mitchell	27 Edinburgh Street	Dwelling	28762	1RP100841	27 Edinburgh St	1950's	Craig Carlson	22-Jul-20	Building	Laundry asbestos cement sheeting walls and ceiling	Cement based (1)	Bonded	Presumed	Similar to Q34185S09	Chrysotile; amosite (2)	Good (1)	Sealed bonded (1)	Low	M.63
Mitchell	27 Edinburgh Street	Dwelling	28762	1RP100841	27 Edinburgh St	1950's	Craig Carlson	22-Jul-20	Building	Back stair foyer asbestos cement sheeting walls and ceiling	Cement based (1)	Bonded	Presumed	Similar to Q34185S09	Chrysotile; amosite (2)	Good (1)	Sealed bonded (1)	Low	M.64
Mitchell	27 Edinburgh Street	Dwelling	28762	1RP100841	27 Edinburgh St	1950's	Craig Carlson	22-Jul-20	Building	Building external asbestos cement sheeting soffits; main building timber walls with metal sheeting roof	Cement based (1)	Bonded	Presumed	Similar to Q34185S09	Chrysotile; amosite (2)	Good (1)	Sealed bonded (1)	Low	M.65; M.66
Mitchell	36 Edinburgh Street	Dwelling	28766	3M15121	36 Edinburgh St	1970's	Craig Carlson	22-Jul-20	Building	Front foyer, lounge room, hall, bedrooms (three) masonite walls and ceilings with non-asbestos vinyl sheet and carpet flooring	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Mitchell	36 Edinburgh Street	Dwelling	28766	3M15121	36 Edinburgh St	1970's	Craig Carlson	22-Jul-20	Building	Lounge room asbestos cement wall and ceiling sheeting in stove recess	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.67
Mitchell	36 Edinburgh Street	Dwelling	28766	3M15121	36 Edinburgh St	1970's	Craig Carlson	22-Jul-20	Building	Bathroom asbestos cement sheeting (painted Tilux) lower walls with masonite upper walls and ceiling	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.68
Mitchell	36 Edinburgh Street	Dwelling	28766	3M15121	36 Edinburgh St	1970's	Craig Carlson	22-Jul-20	Building	Rumpus room asbestos cement sheeting ceiling in main room with asbestos cement sheeting walls and ceiling in store	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.69; M.70
Mitchell	36 Edinburgh Street	Dwelling	28766	3M15121	36 Edinburgh St	1970's	Craig Carlson	22-Jul-20	Building	External asbestos cement sheeting infill panels above glazing on back rumpus room	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.71
Mitchell	36 Edinburgh Street	Dwelling	28766	3M15121	36 Edinburgh St	1970's	Craig Carlson	22-Jul-20	Building	Building external asbestos cement sheeting soffits including front entry ceiling	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.72; M.73
Mitchell	36 Edinburgh Street	Dwelling	28766	3M15121	36 Edinburgh St	1970's	Craig Carlson	22-Jul-20	Building	Building external asbestos cement vent pipe; also present within the rumpus room	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Fair (2)	Unsealed bonded (2)	Low	M.74
Mitchell	38 Edinburgh Street	Dwelling	28770	3M15121	38 Edinburgh St	1970's	Craig Carlson	22-Jul-20	Building	Foyer, lounge, kitchen, hallway and bedrooms (three) masonite walls and ceilings with non-asbestos vinyl sheet and carpet flooring	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Mitchell	38 Edinburgh Street	Dwelling	28770	3M15121	38 Edinburgh St	1970's	Craig Carlson	22-Jul-20	Building	Kitchen stove recess asbestos cement sheeting walls and ceiling	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.75
Mitchell	38 Edinburgh Street	Dwelling	28770	3M15121	38 Edinburgh St	1970's	Craig Carlson	22-Jul-20	Building	Bathroom masonite upper walls and ceiling with asbestos cement sheeting (Tilux) lower walls	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.76
Mitchell	38 Edinburgh Street	Dwelling	28770	3M15121	38 Edinburgh St	1970's	Craig Carlson	22-Jul-20	Building	Laundry and rear entry stair asbestos cement sheeting walls and ceiling	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.77; M.78
Mitchell	38 Edinburgh Street	Dwelling	28770	3M15121	38 Edinburgh St	1970's	Craig Carlson	22-Jul-20	Building	Building external asbestos cement sheeting soffits including front entry ceiling	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.79; M.80
Mitchell	38 Edinburgh Street	Dwelling	28770	3M15121	38 Edinburgh St	1970's	Craig Carlson	22-Jul-20	Building	Building external non-asbestos fibre cement sheeting rear verandah west wall	Cement based (1)	N/A	Not present (tested)	Q34085S10	No asbestos detected	N/A	N/A	N/A	M.81
Mitchell	38 Edinburgh Street	Dwelling	28770	3M15121	38 Edinburgh St	1970's	Craig Carlson	22-Jul-20	Building	Building external asbestos cement vent pipe	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Fair (2)	Unsealed bonded (2)	Low	M.82
Mitchell	38 Oxford Street	Dwelling Duplex 1-2	29020	1RP78659	38 Oxford Street	1990's	Craig Carlson	22-Jul-20	Building	Unit 1 and Unit 2 internal lounge, kitchen, dining, bedrooms (two) and laundry all plasterboard walls and ceiling with carpet and non-asbestos vinyl sheet flooring	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Mitchell	38 Oxford Street	Dwelling Duplex 1-2	29020	1RP78659	38 Oxford Street	1990's	Craig Carlson	22-Jul-20	Building	Unit 1 and 2 bathrooms non-asbestos fibre cement sheeting walls with plasterboard ceilings	Cement based (1)	N/A	Not present (not tested)	None taken	No asbestos detected	N/A	N/A	N/A	M.112; M.113
Mitchell	38 Oxford Street	Dwelling Duplex 1-2	29020	1RP78659	38 Oxford Street	1990's	Craig Carlson	22-Jul-20	Building	Unit 1 and 2 garages non-asbestos fibre cement sheeting walls to house area	Cement based (1)	N/A	Not present (not tested)	None taken	No asbestos detected	N/A	N/A	N/A	M.114; M.115

Town	Facility	Building	Asset No	Lot Plan	Address	Build Date	Auditor	Date of Inspection	ACM Location	Use of ACM / Component	ACM Material	Friable / Bonded	ACM Status	Sample #	ACM Type	ACM Condition	ACM Treatment	ACM Risk	Photo #
Mitchell	38 Oxford Street	Dwelling Duplex 1-2	29020	1RP78659	38 Oxford Street	1990's	Craig Carlson	22-Jul-20	Building	External non-asbestos fibre cement sheeting soffits, front entry foyer ceilings, rear verandah ceilings and front gable ends	Cement based (1)	N/A	Not present (tested)	Q34185S15	No asbestos detected	N/A	N/A	N/A	M.116; M.117; M.118; M.119
Mitchell	40 Edinburgh Street	Carport	62600	3M15121	40 Edinburgh St	1980's	Craig Carlson	22-Jul-20	Building	All steel and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Mitchell	40 Edinburgh Street	Dwelling	29026	3M15121	40 Edinburgh St	1980's	Craig Carlson	22-Jul-20	Building	Internal lounge, kitchen, dining, hall and bedrooms (three) plasterboard walls and ceilings with non-asbestos vinyl sheet flooring	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Mitchell	40 Edinburgh Street	Dwelling	29026	3M15121	40 Edinburgh St	1980's	Craig Carlson	22-Jul-20	Building	Bathroom, toilet and laundry non-asbestos fibre cement sheeting walls with plasterboard ceiling	Cement based (1)	N/A	Not present (tested)	Q34085S11	No asbestos detected	N/A	N/A	N/A	M.83; M.84
Mitchell	40 Edinburgh Street	Dwelling	29026	3M15121	40 Edinburgh St	1980's	Craig Carlson	22-Jul-20	Building	Building external non-asbestos fibre cement sheeting soffits, front awning ceiling, gable ends and infill panels above glazing	Cement based (1)	N/A	Not present (tested)	Q34085S12	No asbestos detected	N/A	N/A	N/A	M.85; M.86; M.87
Mitchell	75 Rugby Street	Dwelling	28866	11RP78288	75 Rugby St	1980's	Craig Carlson	23-Jul-20	Building	Lounge, kitchen, dining, bedrooms (three) and toilet plasterboard and concrete block walls with plasterboard ceiling and carpet and non-asbestos vinyl sheet flooring	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Mitchell	75 Rugby Street	Dwelling	28866	11RP78288	75 Rugby St	1980's	Craig Carlson	23-Jul-20	Building	Bathroom non-asbestos fibre cement sheeting walls and ceiling and laundry wall behind sink	Cement based (1)	N/A	Not present (tested)	Q34185S16	No asbestos detected	N/A	N/A	N/A	M.120; M.121
Mitchell	75 Rugby Street	Dwelling	28866	11RP78288	75 Rugby St	1980's	Craig Carlson	23-Jul-20	Building	Building external non-asbestos fibre cement sheeting soffits	Cement based (1)	N/A	Not present (tested)	Q34185S17	No asbestos detected	N/A	N/A	N/A	M.122
Mitchell	8 Cambridge Lane	Dwelling	29030	4RP75700	8 Cambridge Lane	1990's	Craig Carlson	21-Jul-20	Building	Internal throughout plasterboard walls and ceilings in lounge, kitchen, dining, bedrooms and toilet with non-asbestos vinyl sheet, ceramic tile and carpet flooring	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Mitchell	8 Cambridge Lane	Dwelling	29030	4RP75700	8 Cambridge Lane	1990's	Craig Carlson	21-Jul-20	Building	Laundry and bathroom non-asbestos fibre cement sheeting walls and ceilings with ceramic tile flooring	Cement based (1)	N/A	Not present (not tested)	None taken	No asbestos detected	N/A	N/A	N/A	M.19; M.20
Mitchell	8 Cambridge Lane	Dwelling	29030	4RP75700	8 Cambridge Lane	1990's	Craig Carlson	21-Jul-20	Building	External non-asbestos fibre cement sheeting soffits, verandah ceilings, carport ceiling and gable ends	Cement based (1)	N/A	Not present (not tested)	None taken	No asbestos detected	N/A	N/A	N/A	M.21; M.22
Mitchell	97 Ann Street OAP Units	Dwelling - OAP Unit 1 (Held for Sale)	28778	1SP200053	97 Ann St	1950's	Craig Carlson	29-Jul-20	Building	Kitchen asbestos cement sheeting ceiling and walls and ceiling in stove recess	Cement based (1)	Bonded	Presumed	Similar to Q34185S41	Chrysotile (1)	Fair (2)	Sealed bonded (1)	Low	M.344; M.345
Mitchell	97 Ann Street OAP Units	Dwelling - OAP Unit 1 (Held for Sale)	28778	1SP200053	97 Ann St	1950's	Craig Carlson	29-Jul-20	Building	Bathroom asbestos cement sheeting walls and ceiling	Cement based (1)	Bonded	Presumed	Similar to Q34185S41	Chrysotile (1)	Fair (2)	Sealed bonded (1)	Low	M.346
Mitchell	97 Ann Street OAP Units	Dwelling - OAP Unit 1 (Held for Sale)	28778	1SP200053	97 Ann St	1950's	Craig Carlson	29-Jul-20	Building	Bathroom asbestos backed vinyl sheeting flooring	Vinyl sheeting (2)	Friable	Confirmed	Q34185S40	Chrysotile (1)	Poor (3)	Unsealed friable (3)	Medium	M.347
Mitchell	97 Ann Street OAP Units	Dwelling - OAP Unit 1 (Held for Sale)	28778	1SP200053	97 Ann St	1950's	Craig Carlson	29-Jul-20	Building	Main room including rear foyer timber walls with asbestos cement sheeting ceiling	Cement based (1)	Bonded	Presumed	Similar to Q34185S41	Chrysotile (1)	Fair (2)	Sealed bonded (1)	Low	M.348
Mitchell	97 Ann Street OAP Units	Dwelling - OAP Unit 1 (Held for Sale)	28778	1SP200053	97 Ann St	1950's	Craig Carlson	29-Jul-20	Building	Front verandah asbestos cement sheeting ceiling and partition to bathroom	Cement based (1)	Bonded	Presumed	Similar to Q34185S41	Chrysotile (1)	Fair (2)	Sealed bonded (1)	Low	M.349; M.350
Mitchell	97 Ann Street OAP Units	Dwelling - OAP Unit 1 (Held for Sale)	28778	1SP200053	97 Ann St	1950's	Craig Carlson	29-Jul-20	Building	Building external asbestos cement walls and metal sheeting roof	Cement based (1)	Bonded	Confirmed	Q34185S41	Chrysotile (1)	Fair (2)	Sealed bonded (1)	Low	M.351
Mitchell	97 Ann Street OAP Units	Dwelling - OAP Unit 2 (Held for Sale)	28779	1SP200053	97 Ann St	1950's	Craig Carlson	29-Jul-20	Building	Kitchen asbestos cement sheeting ceiling and walls and ceiling in stove recess	Cement based (1)	Bonded	Presumed	Similar to Q34185S41	Chrysotile (1)	Fair (2)	Sealed bonded (1)	Low	M.352; M.353
Mitchell	97 Ann Street OAP Units	Dwelling - OAP Unit 2 (Held for Sale)	28779	1SP200053	97 Ann St	1950's	Craig Carlson	29-Jul-20	Building	Main room including rear foyer timber walls with asbestos cement sheeting ceiling	Cement based (1)	Bonded	Presumed	Similar to Q34185S41	Chrysotile (1)	Fair (2)	Sealed bonded (1)	Low	M.354
Mitchell	97 Ann Street OAP Units	Dwelling - OAP Unit 2 (Held for Sale)	28779	1SP200053	97 Ann St	1950's	Craig Carlson	29-Jul-20	Building	Bathroom asbestos cement sheeting ceiling and wall lining behind bath	Cement based (1)	Bonded	Presumed	Similar to Q34185S41	Chrysotile (1)	Fair (2)	Sealed bonded (1)	Low	M.355
Mitchell	97 Ann Street OAP Units	Dwelling - OAP Unit 2 (Held for Sale)	28779	1SP200053	97 Ann St	1950's	Craig Carlson	29-Jul-20	Building	Front verandah asbestos cement sheeting ceiling and partition walls to external	Cement based (1)	Bonded	Presumed	Similar to Q34185S41	Chrysotile (1)	Fair (2)	Sealed bonded (1)	Low	M.356; M.357

Town	Facility	Building	Asset No	Lot Plan	Address	Build Date	Auditor	Date of Inspection	ACM Location	Use of ACM / Component	ACM Material	Friable / Bonded	ACM Status	Sample #	ACM Type	ACM Condition	ACM Treatment	ACM Risk	Photo #
Mitchell	97 Ann Street OAP Units	Dwelling - OAP Unit 2 (Held for Sale)	28779	1SP200053	97 Ann St	1950's	Craig Carlson	29-Jul-20	Building	Building external asbestos cement walls and metal sheeting roof	Cement based (1)	Bonded	Presumed	Similar to Q34185S41	Chrysotile (1)	Fair (2)	Sealed bonded (1)	Low	M.358
Mitchell	97 Ann Street OAP Units	Dwelling - OAP Unit 3 (Held for Sale)	28780	1SP200053	97 Ann St	1950's	Craig Carlson	29-Jul-20	Building	Kitchen asbestos cement sheeting ceiling and walls and ceiling in stove recess	Cement based (1)	Bonded	Presumed	Similar to Q34185S41	Chrysotile (1)	Fair (2)	Sealed bonded (1)	Low	M.359; M.360
Mitchell	97 Ann Street OAP Units	Dwelling - OAP Unit 3 (Held for Sale)	28780	1SP200053	97 Ann St	1950's	Craig Carlson	29-Jul-20	Building	Main room including rear foyer timber walls with asbestos cement sheeting ceiling	Cement based (1)	Bonded	Presumed	Similar to Q34185S41	Chrysotile (1)	Fair (2)	Sealed bonded (1)	Low	M.361; M.362
Mitchell	97 Ann Street OAP Units	Dwelling - OAP Unit 3 (Held for Sale)	28780	1SP200053	97 Ann St	1950's	Craig Carlson	29-Jul-20	Building	Bathroom asbestos cement sheeting walls and ceiling	Cement based (1)	Bonded	Presumed	Similar to Q34185S41	Chrysotile (1)	Fair (2)	Sealed bonded (1)	Low	M.363
Mitchell	97 Ann Street OAP Units	Dwelling - OAP Unit 3 (Held for Sale)	28780	1SP200053	97 Ann St	1950's	Craig Carlson	29-Jul-20	Building	Bathroom asbestos backed vinyl sheeting flooring	Vinyl sheeting (2)	Friable	Confirmed	Similar to Q34185S40	Chrysotile (1)	Poor (3)	Unsealed friable (3)	Medium	M.364
Mitchell	97 Ann Street OAP Units	Dwelling - OAP Unit 3 (Held for Sale)	28780	1SP200053	97 Ann St	1950's	Craig Carlson	29-Jul-20	Building	Front verandah asbestos cement sheeting ceiling and partition to bathroom	Cement based (1)	Bonded	Presumed	Similar to Q34185S41	Chrysotile (1)	Fair (2)	Sealed bonded (1)	Low	M.365; M.366
Mitchell	97 Ann Street OAP Units	Dwelling - OAP Unit 3 (Held for Sale)	28780	1SP200053	97 Ann St	1950's	Craig Carlson	29-Jul-20	Building	Building external asbestos cement walls and metal sheeting roof	Cement based (1)	Bonded	Confirmed	Q34185S41	Chrysotile (1)	Fair (2)	Sealed bonded (1)	Low	M.367
Mitchell	97 Ann Street Units 3-6	Dwelling Unit 3	60366	1SP200053	97 Ann St	Post 2000	Craig Carlson	29-Jul-20	Building	New demountable building	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.368
Mitchell	97 Ann Street Units 3-6	Dwelling Unit 4	60367	1SP200053	97 Ann St	Post 2000	Craig Carlson	29-Jul-20	Building	New demountable building	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.369
Mitchell	97 Ann Street Units 3-6	Dwelling Unit 5	60368	1SP200053	97 Ann St	Post 2000	Craig Carlson	29-Jul-20	Building	New demountable building	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.370
Mitchell	97 Ann Street Units 3-6	Dwelling Unit 6	60369	1SP200053	97 Ann St	Post 2000	Craig Carlson	29-Jul-20	Building	New demountable building	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.371
Mitchell	Warrego Highway - Saleyards	Carport	75572	127SP203119	Rowallan Estate Rd	1970's	Craig Carlson	21-Jul-20	Building	All timber and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Mitchell	Warrego Highway - Saleyards	Dwelling	28783	127SP203119	Rowallan Estate Rd	1970's	Craig Carlson	21-Jul-20	Building	Dining room in back west corner asbestos cement sheeting walls and ceiling with non-asbestos vinyl sheet flooring	Cement based (1)	Bonded	Presumed	Similar to Q34185S03	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.23
Mitchell	Warrego Highway - Saleyards	Dwelling	28783	127SP203119	Rowallan Estate Rd	1970's	Craig Carlson	21-Jul-20	Building	Kitchen masonite walls and ceiling in main room with asbestos cement sheeting walls and ceiling in pantry	Cement based (1)	Bonded	Confirmed	Q34185S03	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.24
Mitchell	Warrego Highway - Saleyards	Dwelling	28783	127SP203119	Rowallan Estate Rd	1970's	Craig Carlson	21-Jul-20	Building	West side front and rear bedrooms and lounge room asbestos cement sheeting walls and ceilings with non-asbestos vinyl sheet and timber flooring	Cement based (1)	Bonded	Presumed	Similar to Q34185S03; Q34185S04 (vinyl flooring)	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.25; M.26; M.27
Mitchell	Warrego Highway - Saleyards	Dwelling	28783	127SP203119	Rowallan Estate Rd	1970's	Craig Carlson	21-Jul-20	Building	Formal dining room, entry foyer, back bedrooms (three), hall, bathroom and toilet masonite walls and ceilings	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	No image
Mitchell	Warrego Highway - Saleyards	Dwelling	28783	127SP203119	Rowallan Estate Rd	1970's	Craig Carlson	21-Jul-20	Building	Laundry asbestos cement sheeting walls and ceiling with limited areas of masonite present	Cement based (1)	Bonded	Presumed	Similar to Q34185S03	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.28
Mitchell	Warrego Highway - Saleyards	Dwelling	28783	127SP203119	Rowallan Estate Rd	1970's	Craig Carlson	21-Jul-20	Building	Building external asbestos cement sheeting soffits and external ceilings including front verandah ceiling	Cement based (1)	Bonded	Presumed	Similar to Q34185S03	Chrysotile (1)	Good (1)	Sealed bonded (1)	Very low	M.29; M.30; M.31
Mitchell	Warrego Highway - Saleyards	Dwelling	28783	127SP203119	Rowallan Estate Rd	1970's	Craig Carlson	21-Jul-20	Building	Building external asbestos cement vent pipe	Cement based (1)	Bonded	Presumed	None taken	Chrysotile (1)	Fair (2)	Unsealed bonded (2)	Low	M.32
Mitchell	Mitchell Bore 1	Bore 1 Treatment Building	60693	125SP265642	Oxford St	Post 2000	Craig Carlson	30-Jul-20	Water Treatment Plant	All concrete block and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.430
Mitchell	Mitchell Bore 2	Bore 2 Treatment Building	60696	2M15146	Ann St	Post 2000	Craig Carlson	30-Jul-20	Water Treatment Plant	All concrete block and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.431
Mitchell	Mitchell St George Reservoir	Reservoir StG Rd Treatment Building	60699	Road Reserve	Mitchell St George Rd	Post 2000	Craig Carlson	29-Jul-20	Water Treatment Plant	All concrete block and metal sheeting construction	N/A	N/A	No asbestos detected	None taken	No asbestos detected	N/A	N/A	N/A	M.423